

15 Years of Stormwater Planning, Design and Implementation for the City of Pewaukee

Wed., April 2, 2025

Rick Eilertson, PE, ENV SP

rick.eilertson@aecom.com 608-402-5862

Delivering a better world














Rick Eilertson, P.E. Project Engineer/Manager



Topics to be covered:

- 1. Flood risks that contributed to the pursuit of stormwater conveyance retrofits and design criteria
- 2. Project Hurdles (RR permits, WDNR/ACOE permits, private owner permission, etc.)
- 3. Keys to successfully installing casing pipes and culverts under active RR and through wetlands/waterways on private property





Emerald Acres Drainage Basin



2010 Flooding



North side of Green Road




South side of Green Road



2017 Flooding




South side Green Road (post Road Reconstruction)



View of ditch from Emerald Lane (south of Green Road)



Emerald Lane Flooding





City of Pewaukee


Figure 10
South end of Emerald Lane



Final Report

Figure 11
Frontyard of N3021 condo unit
At south end of Emerald Lane











DNR Permitting 2016-2018






Emerald Acres Flood Mitigation Project Original Concrete Headwall Design





Railroad Requirements


- Railroad Flaggers
- Railroad Protective Insurance
- Utilities Fiber Optic Line
- RR review and approval









Alternative Sheeting Design







Settlement Monitoring



- Subsurface Points
- Surface Points
- Contingency Plans



Monitoring occurred before, during, & after Boring Operations




Challenges – Site Access



Boring and Jacking Operations

(3 – 72" Diameter Steel Casing Pipes)









Challenges – Bank Stability







Boring and Jacking Operations

(3 – 72" Diameter Steel Casing Pipes)









HDPE Liner - Grouting










Challenges – Maintaining Flow





Downstream Side








Emerald Acres Flood Mitigation Project Final Cleanup







































June 21, 2021












June 21, 2021


















Photo of watermain assembly at the end of the day.




Photo of the removal of the existing 15" CMP just west of Springdale Road.














Installed erosion log downstream across concrete flume at ~STA 8+00



Leveled out soil after blasting between STA 5+50 to 7+50 (MH3 to MH4).







Progress of seeding and matting between MH1 and MH2



Seeded and matted area around MH2.








Transporting topsoil to site for final grading.

Final seeding and matting between MH1 and MH2 (closest).





Area around MH1 (located near the bottom middle of the photograph) looking west.



MH 1 looking north. Four bolts still missing from casting.



Questions?





Contact Information:

Rick Eilertson, PE, ENV SP

rick.eilertson@aecom.com 608-402-5862