

**December, 2015
Trunked Radio Usage**

| Parent agency | Department | Make | Model Number | Serial Number | Type | Airtime Minutes |
|---------------------------------------|---|----------|--------------|---------------|-----------------------|-----------------|
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H01UCF6PW1BN | 466ABW3162 | MTS-2000 Model II | 0.44 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H01UCF6PW1BN | 466ABW4180 | MTS-2000 Model II | 0.09 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CFC0899 | XTS-5000 Model II | 0.05 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CFC0900 | XTS-5000 Model II | 0.05 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CFC0903 | XTS-5000 Model II | 0.15 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CFC0893 | XTS-5000 Model II | 0.04 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CEG0126 | XTS-5000 Model II | 0.04 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | H18UCF9PW6AN | 721CEG0135 | XTS-5000 Model II | 0.05 |
| Ashippun Fire Department | Ashippun Fire Department | Motorola | M21URM9PW1AN | 514CNH1483 | XTL-2500 Mobile | 0.38 |
| | Ashippun Fire Department Total | | | | | 1.29 |
| Ashippun Fire Department Total | | | | | | 1.29 |
| Aurora Health Care | Aurora Medical Center Summit | Motorola | L20URS9PW1AN | 276CKV0200 | XTL-5000 Control Base | 10.42 |
| | Aurora Medical Center Summit Total | | | | | 10.42 |
| Aurora Health Care Total | | | | | | 10.42 |
| Big Bend | Big Bend Fire Department | Motorola | H01UCD6PW1BN | 466ABE2315 | MTS-2000 Model I | 0.05 |
| Big Bend | Big Bend Fire Department | Motorola | H46UCF9PW6BN | 205CJR3389 | XTS-2500 Model II FM | 0.53 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 756CQP2381 | APX-6000XE Model 2.5 | 0.26 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2139 | APX-6000 Model 2.5 | 0.06 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2138 | APX-6000 Model 2.5 | 1.75 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2137 | APX-6000 Model 2.5 | 1.30 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2136 | APX-6000 Model 2.5 | 0.10 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2135 | APX-6000 Model 2.5 | 1.87 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2134 | APX-6000 Model 2.5 | 0.39 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2131 | APX-6000 Model 2.5 | 2.41 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2130 | APX-6000 Model 2.5 | 8.47 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2140 | APX-6000 Model 2.5 | 0.55 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2129 | APX-6000 Model 2.5 | 0.11 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 481CQP2128 | APX-6000 Model 2.5 | 6.51 |
| Big Bend | Big Bend Fire Department | Motorola | H98UCF9PW6AN | 756CQP2384 | APX-6000XE Model 2.5 | 0.64 |
| Big Bend | Big Bend Fire Department | Motorola | M21URM9PW2AN | 624CJK0820 | XTL-2500RB | 4.71 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3906 | APX-6500 Mobile | 0.30 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3903 | APX-6500 Mobile | 0.71 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3893 | APX-6500 Mobile | 11.47 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3892 | APX-6500 Mobile | 1.27 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------|---|----------|--------------|------------|----------------------|---------------|
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3891 | APX-6500 Mobile | 5.92 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3890 | APX-6500 Mobile | 1.00 |
| Big Bend | Big Bend Fire Department | Motorola | M25URS9PW1AN | 527CQM3887 | APX-6500 Mobile | 2.78 |
| | Big Bend Fire Department Total | | | | | 53.16 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5502 | XTS-2500 Model II FM | 4.22 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5505 | XTS-2500 Model II FM | 1.06 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5507 | XTS-2500 Model II FM | 0.44 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5503 | XTS-2500 Model II FM | 4.18 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5501 | XTS-2500 Model II FM | 1.67 |
| Big Bend | Big Bend Police Department | Motorola | H46UCF9PW6BN | 205CJF5506 | XTS-2500 Model II FM | 5.10 |
| Big Bend | Big Bend Police Department | Motorola | H98UCF9PW6AN | 481CQP2124 | APX-6000 Model 2.5 | 0.54 |
| Big Bend | Big Bend Police Department | Motorola | M25URS9PW1AN | 527CQM3905 | APX-6500 Mobile | 7.07 |
| Big Bend | Big Bend Police Department | Motorola | M25URS9PW1AN | 527CQM3901 | APX-6500 Mobile | 38.51 |
| Big Bend | Big Bend Police Department | Motorola | M25URS9PW1AN | 527CQM3900 | APX-6500 Mobile | 1.21 |
| Big Bend | Big Bend Police Department | Motorola | M25URS9PW1AN | 527CQM3899 | APX-6500 Mobile | 49.23 |
| | Big Bend Police Department Total | | | | | 113.23 |
| Big Bend | Big Bend Public Works | Motorola | H51UCF9PW6AN | 426CQM5113 | APX-4000 Model 2 | 11.69 |
| Big Bend | Big Bend Public Works | Motorola | H51UCF9PW6AN | 426CQM5112 | APX-4000 Model 2 | 1.70 |
| Big Bend | Big Bend Public Works | Motorola | M22URS9PW1AN | 471CQM2170 | APX-4500 Mobile | 1.45 |
| Big Bend | Big Bend Public Works | Motorola | M22URS9PW1AN | 471CQM2171 | APX-4500 Mobile | 3.38 |
| Big Bend | Big Bend Public Works | Motorola | M25URS9PW1AN | 527CQM3904 | APX-6500 Mobile | 0.22 |
| | Big Bend Public Works Total | | | | | 18.44 |
| Big Bend Total | | | | | | 184.83 |
| Brookfield, City | Brookfield City Engineering Division | Motorola | H46UCF9PW6BN | 205CJF0553 | XTS-2500 Model II FM | 2.27 |
| Brookfield, City | Brookfield City Engineering Division | Motorola | H46UCF9PW6BN | 205CJF0556 | XTS-2500 Model II FM | 0.21 |
| Brookfield, City | Brookfield City Engineering Division | Motorola | H46UCF9PW6BN | 205CJF0558 | XTS-2500 Model II FM | 0.37 |
| Brookfield, City | Brookfield City Engineering Division | Motorola | H46UCF9PW6BN | 205CJF0560 | XTS-2500 Model II FM | 0.05 |
| | Brookfield City Engineering Division Total | | | | | 2.90 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0368 | APX-7000XE Model 3.5 | 3.79 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0369 | APX-7000XE Model 3.5 | 2.12 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0370 | APX-7000XE Model 3.5 | 0.27 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0371 | APX-7000XE Model 3.5 | 0.33 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0372 | APX-7000XE Model 3.5 | 0.10 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0374 | APX-7000XE Model 3.5 | 6.11 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0367 | APX-7000XE Model 3.5 | 2.03 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|---------------------------------|----------|--------------|------------|----------------------|-------|
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0377 | APX-7000XE Model 3.5 | 0.16 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0379 | APX-7000XE Model 3.5 | 0.07 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0403 | APX-7000XE Model 3.5 | 0.22 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0376 | APX-7000XE Model 3.5 | 1.33 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0366 | APX-7000XE Model 3.5 | 0.95 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0364 | APX-7000XE Model 3.5 | 0.19 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0393 | APX-7000XE Model 3.5 | 0.38 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0402 | APX-7000XE Model 3.5 | 0.08 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0391 | APX-7000XE Model 3.5 | 15.40 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0400 | APX-7000XE Model 3.5 | 0.21 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0399 | APX-7000XE Model 3.5 | 0.34 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0398 | APX-7000XE Model 3.5 | 0.29 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0397 | APX-7000XE Model 3.5 | 17.01 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0396 | APX-7000XE Model 3.5 | 0.96 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0395 | APX-7000XE Model 3.5 | 1.13 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0401 | APX-7000XE Model 3.5 | 0.47 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0389 | APX-7000XE Model 3.5 | 0.89 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0405 | APX-7000XE Model 3.5 | 2.38 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0394 | APX-7000XE Model 3.5 | 0.27 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0406 | APX-7000XE Model 3.5 | 0.65 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0387 | APX-7000XE Model 3.5 | 17.86 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0388 | APX-7000XE Model 3.5 | 0.11 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0384 | APX-7000XE Model 3.5 | 0.24 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0385 | APX-7000XE Model 3.5 | 2.06 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0378 | APX-7000XE Model 3.5 | 1.18 |
| Brookfield, City | Brookfield City Fire Department | Motorola | H49TGD9PW1AN | 562CQH0404 | APX-7000XE Model 3.5 | 0.10 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M01UGL6PW4BN | 722ABJ0515 | MCS-2000 Model I | 0.07 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW1AN | 514CLR0120 | XTL-2500 Mobile | 1.33 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0299 | XTL-2500RB | 1.08 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0295 | XTL-2500RB | 0.14 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0298 | XTL-2500RB | 0.14 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0294 | XTL-2500RB | 1.04 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0300 | XTL-2500RB | 0.63 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0297 | XTL-2500RB | 1.21 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJK1055 | XTL-2500RB | 0.20 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|----------------------|---------------|
| Brookfield, City | Brookfield City Fire Department | Motorola | M21URM9PW2AN | 624CJX0296 | XTL-2500RB | 0.20 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2271 | APX-7500 Mobile | 6.68 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2276 | APX-7500 Mobile | 13.48 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2278 | APX-7500 Mobile | 3.94 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2274 | APX-7500 Mobile | 7.46 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2273 | APX-7500 Mobile | 6.64 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2272 | APX-7500 Mobile | 6.80 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2266 | APX-7500 Mobile | 0.06 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2267 | APX-7500 Mobile | 0.40 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2275 | APX-7500 Mobile | 0.11 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2260 | APX-7500 Mobile | 0.05 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2261 | APX-7500 Mobile | 19.47 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2262 | APX-7500 Mobile | 23.45 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2263 | APX-7500 Mobile | 20.98 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2264 | APX-7500 Mobile | 0.38 |
| Brookfield, City | Brookfield City Fire Department | Motorola | M30TSS9PW1AN | 656CQF2265 | APX-7500 Mobile | 5.53 |
| | Brookfield City Fire Department Total | | | | | 201.15 |
| Brookfield, City | Brookfield City Fleet Division | Motorola | H46UCF9PW6BN | 205CJF0421 | XTS-2500 Model II FM | 1.07 |
| Brookfield, City | Brookfield City Fleet Division | Motorola | M21URM9PW2AN | 624CJX0293 | XTL-2500RB | 0.99 |
| | Brookfield City Fleet Division Total | | | | | 2.06 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0588 | XTS-2500 Model II FM | 10.01 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0580 | XTS-2500 Model II FM | 0.12 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0581 | XTS-2500 Model II FM | 2.52 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0582 | XTS-2500 Model II FM | 0.52 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0583 | XTS-2500 Model II FM | 3.68 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0586 | XTS-2500 Model II FM | 0.69 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0595 | XTS-2500 Model II FM | 5.80 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0594 | XTS-2500 Model II FM | 3.38 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0592 | XTS-2500 Model II FM | 5.85 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0591 | XTS-2500 Model II FM | 3.87 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0587 | XTS-2500 Model II FM | 1.35 |
| Brookfield, City | Brookfield City Highway Division | Motorola | H46UCF9PW6BN | 205CJF0589 | XTS-2500 Model II FM | 1.39 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW1AN | 514CND0003 | XTL-2500 Mobile | 0.77 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0242 | XTL-2500RB | 20.55 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0253 | XTL-2500RB | 0.89 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|----------------------|---------------|
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0240 | XTL-2500RB | 2.79 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0248 | XTL-2500RB | 1.75 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0239 | XTL-2500RB | 0.34 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0245 | XTL-2500RB | 3.69 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0246 | XTL-2500RB | 2.56 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0247 | XTL-2500RB | 4.40 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJK1050 | XTL-2500RB | 0.64 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0244 | XTL-2500RB | 2.12 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0249 | XTL-2500RB | 0.62 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0238 | XTL-2500RB | 0.30 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0252 | XTL-2500RB | 0.70 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0241 | XTL-2500RB | 0.11 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0254 | XTL-2500RB | 3.96 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0255 | XTL-2500RB | 1.99 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0257 | XTL-2500RB | 0.70 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0258 | XTL-2500RB | 0.45 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0259 | XTL-2500RB | 0.47 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0263 | XTL-2500RB | 0.27 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0264 | XTL-2500RB | 2.17 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0272 | XTL-2500RB | 4.12 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0250 | XTL-2500RB | 0.59 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0236 | XTL-2500RB | 0.33 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0235 | XTL-2500RB | 0.51 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0232 | XTL-2500RB | 5.88 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0231 | XTL-2500RB | 0.13 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0243 | XTL-2500RB | 1.31 |
| Brookfield, City | Brookfield City Highway Division | Motorola | M21URM9PW2AN | 624CJX0237 | XTL-2500RB | 7.09 |
| | Brookfield City Highway Division Total | | | | | 111.38 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | H46UCF9PW6BN | 205CJF0485 | XTS-2500 Model II FM | 0.29 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | H46UCF9PW6BN | 205CJF0489 | XTS-2500 Model II FM | 1.57 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | H46UCF9PW6BN | 205CJF0494 | XTS-2500 Model II FM | 1.32 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | H46UCF9PW6BN | 205CJF0495 | XTS-2500 Model II FM | 0.72 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | H46UCF9PW6BN | 205CJF0488 | XTS-2500 Model II FM | 0.71 |
| Brookfield, City | Brookfield City Inspection Services | Motorola | M21URM9PW2AN | 624CJK1049 | XTL-2500RB | 1.33 |
| | Brookfield City Inspection Services Total | | | | | 5.94 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|--------------------|-------------|
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0285 | XTL-2500RB | 0.27 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0282 | XTL-2500RB | 0.75 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0280 | XTL-2500RB | 0.06 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0278 | XTL-2500RB | 1.23 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0284 | XTL-2500RB | 0.68 |
| Brookfield, City | Brookfield City Parks and Recreation Department | Motorola | M21URM9PW2AN | 624CJX0287 | XTL-2500RB | 0.38 |
| | Brookfield City Parks and Recreation Department Total | | | | | 3.37 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1837 | MTS-2000 Model II | 0.71 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1821 | MTS-2000 Model II | 1.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1165 | APX-7000 Model 3.5 | 18.53 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1166 | APX-7000 Model 3.5 | 24.59 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1168 | APX-7000 Model 3.5 | 20.69 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1170 | APX-7000 Model 3.5 | 9.72 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1169 | APX-7000 Model 3.5 | 13.52 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1187 | APX-7000 Model 3.5 | 9.17 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1171 | APX-7000 Model 3.5 | 12.03 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1167 | APX-7000 Model 3.5 | 4.92 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1186 | APX-7000 Model 3.5 | 12.42 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1183 | APX-7000 Model 3.5 | 10.63 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1182 | APX-7000 Model 3.5 | 12.31 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1181 | APX-7000 Model 3.5 | 0.07 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1177 | APX-7000 Model 3.5 | 17.04 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1176 | APX-7000 Model 3.5 | 11.26 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1174 | APX-7000 Model 3.5 | 1.92 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1173 | APX-7000 Model 3.5 | 4.71 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1172 | APX-7000 Model 3.5 | 6.93 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1184 | APX-7000 Model 3.5 | 1.72 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1151 | APX-7000 Model 3.5 | 18.09 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1157 | APX-7000 Model 3.5 | 19.45 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1188 | APX-7000 Model 3.5 | 8.23 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1141 | APX-7000 Model 3.5 | 16.29 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1131 | APX-7000 Model 3.5 | 9.60 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1142 | APX-7000 Model 3.5 | 13.34 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1155 | APX-7000 Model 3.5 | 26.28 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1154 | APX-7000 Model 3.5 | 1.50 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|-----------------------------------|----------|--------------|------------|--------------------|-------|
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1144 | APX-7000 Model 3.5 | 18.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1152 | APX-7000 Model 3.5 | 14.32 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1160 | APX-7000 Model 3.5 | 9.86 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1150 | APX-7000 Model 3.5 | 13.08 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1149 | APX-7000 Model 3.5 | 23.00 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1148 | APX-7000 Model 3.5 | 7.90 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1147 | APX-7000 Model 3.5 | 13.68 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1146 | APX-7000 Model 3.5 | 5.87 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1143 | APX-7000 Model 3.5 | 0.07 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1145 | APX-7000 Model 3.5 | 8.86 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1153 | APX-7000 Model 3.5 | 12.19 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1197 | APX-7000 Model 3.5 | 14.43 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1132 | APX-7000 Model 3.5 | 11.04 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1133 | APX-7000 Model 3.5 | 8.38 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1139 | APX-7000 Model 3.5 | 7.23 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1164 | APX-7000 Model 3.5 | 12.97 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1189 | APX-7000 Model 3.5 | 0.43 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1190 | APX-7000 Model 3.5 | 0.27 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1192 | APX-7000 Model 3.5 | 1.72 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1158 | APX-7000 Model 3.5 | 27.94 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1195 | APX-7000 Model 3.5 | 0.05 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1159 | APX-7000 Model 3.5 | 12.16 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1198 | APX-7000 Model 3.5 | 7.15 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1200 | APX-7000 Model 3.5 | 0.21 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1140 | APX-7000 Model 3.5 | 23.43 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQP3498 | APX-7000 Model 3.5 | 0.38 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1163 | APX-7000 Model 3.5 | 8.70 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1162 | APX-7000 Model 3.5 | 11.76 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1161 | APX-7000 Model 3.5 | 5.31 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1156 | APX-7000 Model 3.5 | 20.71 |
| Brookfield, City | Brookfield City Police Department | Motorola | H97TGD9PW1AN | 655CQM1193 | APX-7000 Model 3.5 | 0.17 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGL6PW4BN | 722ABJ0516 | MCS-2000 Model I | 21.33 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABW0859 | MCS-2000 Model II | 75.38 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1324 | MCS-2000 Model II | 18.93 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1329 | MCS-2000 Model II | 7.06 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|----------------------|-----------------|
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1340 | MCS-2000 Model II | 0.35 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1326 | MCS-2000 Model II | 2.83 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1339 | MCS-2000 Model II | 125.86 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1332 | MCS-2000 Model II | 150.10 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1347 | MCS-2000 Model II | 1.96 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGm6PW6BN | 722ABJ0546 | MCS-2000 Model II | 173.00 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1349 | MCS-2000 Model II | 4.67 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1338 | MCS-2000 Model II | 24.04 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1335 | MCS-2000 Model II | 5.65 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1319 | MCS-2000 Model II | 76.23 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1328 | MCS-2000 Model II | 122.03 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1336 | MCS-2000 Model II | 88.28 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1297 | MCS-2000 Model II | 2.13 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722AZE2044 | MCS-2000 Model II | 160.80 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722AZE2052 | MCS-2000 Model II | 129.64 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1275 | APX-7500 Mobile | 1.52 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1274 | APX-7500 Mobile | 124.68 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1272 | APX-7500 Mobile | 125.78 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1271 | APX-7500 Mobile | 103.28 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1270 | APX-7500 Mobile | 122.62 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1268 | APX-7500 Mobile | 90.25 |
| Brookfield, City | Brookfield City Police Department | Motorola | M30TSS9PW1AN | 656CQM1276 | APX-7500 Mobile | 36.76 |
| | Brookfield City Police Department Total | | | | | 2,403.48 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H46UCF9PW6BN | 205CJF0541 | XTS-2500 Model II FM | 28.93 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H46UCF9PW6BN | 205CJF0539 | XTS-2500 Model II FM | 2.15 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H46UCF9PW6BN | 205CJF0537 | XTS-2500 Model II FM | 0.74 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H46UCF9PW6BN | 205CJF0538 | XTS-2500 Model II FM | 16.97 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | H46UCF9PW6BN | 205CJF0542 | XTS-2500 Model II FM | 5.13 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0321 | XTL-2500RB | 4.17 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0324 | XTL-2500RB | 1.92 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0322 | XTL-2500RB | 3.96 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0319 | XTL-2500RB | 0.55 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0318 | XTL-2500RB | 6.87 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0317 | XTL-2500RB | 1.65 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0315 | XTL-2500RB | 0.96 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|--|----------|--------------|------------|----------------------|-----------------|
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJK1064 | XTL-2500RB | 44.61 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0316 | XTL-2500RB | 7.99 |
| Brookfield, City | Brookfield City Sewer Utility | Motorola | M21URM9PW2AN | 624CJV0323 | XTL-2500RB | 8.92 |
| | Brookfield City Sewer Utility Total | | | | | 135.52 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0615 | XTS-2500 Model II FM | 5.13 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0605 | XTS-2500 Model II FM | 1.65 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0606 | XTS-2500 Model II FM | 0.26 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0609 | XTS-2500 Model II FM | 11.23 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0611 | XTS-2500 Model II FM | 2.45 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0612 | XTS-2500 Model II FM | 3.53 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0614 | XTS-2500 Model II FM | 1.08 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0604 | XTS-2500 Model II FM | 5.06 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0602 | XTS-2500 Model II FM | 7.44 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H46UCF9PW6BN | 205CJF0613 | XTS-2500 Model II FM | 4.43 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H97TGD9PW1AN | 655CQM1134 | APX-7000 Model 3.5 | 5.88 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H97TGD9PW1AN | 655CQM1135 | APX-7000 Model 3.5 | 23.91 |
| Brookfield, City | Brookfield City Water Utility | Motorola | H97TGD9PW1AN | 655CQM1136 | APX-7000 Model 3.5 | 10.65 |
| Brookfield, City | Brookfield City Water Utility | Motorola | M21URM9PW2AN | 624CJX0292 | XTL-2500RB | 8.83 |
| | Brookfield City Water Utility Total | | | | | 91.53 |
| Brookfield, City Total | | | | | | 2,957.33 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2651 | APX-6000XE Model 2.5 | 0.05 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2665 | APX-6000XE Model 2.5 | 0.11 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2653 | APX-6000XE Model 2.5 | 2.63 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2663 | APX-6000XE Model 2.5 | 4.08 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2660 | APX-6000XE Model 2.5 | 0.53 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2657 | APX-6000XE Model 2.5 | 0.40 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2645 | APX-6000XE Model 2.5 | 7.97 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2659 | APX-6000XE Model 2.5 | 0.38 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2662 | APX-6000XE Model 2.5 | 4.00 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2647 | APX-6000XE Model 2.5 | 0.36 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2652 | APX-6000XE Model 2.5 | 9.26 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2644 | APX-6000XE Model 2.5 | 0.34 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2654 | APX-6000XE Model 2.5 | 9.25 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2656 | APX-6000XE Model 2.5 | 2.47 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2648 | APX-6000XE Model 2.5 | 3.54 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|----------------------|---------------|
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2661 | APX-6000XE Model 2.5 | 1.04 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | H98UCF9PW6AN | 756CQM2650 | APX-6000XE Model 2.5 | 0.70 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M01UGM6PW6BN | 722ABL1332 | MCS-2000 Model II | 33.04 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2284 | APX-6500 Mobile | 0.97 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2283 | APX-6500 Mobile | 1.98 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2282 | APX-6500 Mobile | 10.33 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2281 | APX-6500 Mobile | 2.65 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2280 | APX-6500 Mobile | 30.24 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2279 | APX-6500 Mobile | 4.54 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2278 | APX-6500 Mobile | 0.11 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2277 | APX-6500 Mobile | 0.88 |
| Brookfield, Town | Brookfield Town Fire Department | Motorola | M25URS9PW1AN | 527CQM2275 | APX-6500 Mobile | 13.08 |
| | Brookfield Town Fire Department Total | | | | | 144.93 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0201 | XTS-5000 Model II | 0.86 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H18UCF9PW6AN | 721CEG0204 | XTS-5000 Model II | 8.23 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0049 | APX-6000 Model 2.5 | 13.47 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0055 | APX-6000 Model 2.5 | 6.20 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0054 | APX-6000 Model 2.5 | 6.29 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0052 | APX-6000 Model 2.5 | 1.47 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0036 | APX-6000 Model 2.5 | 19.04 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0050 | APX-6000 Model 2.5 | 3.94 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0037 | APX-6000 Model 2.5 | 37.90 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0047 | APX-6000 Model 2.5 | 11.12 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0046 | APX-6000 Model 2.5 | 31.29 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0040 | APX-6000 Model 2.5 | 11.17 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0051 | APX-6000 Model 2.5 | 2.17 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0039 | APX-6000 Model 2.5 | 0.06 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0045 | APX-6000 Model 2.5 | 44.85 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0041 | APX-6000 Model 2.5 | 9.91 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0042 | APX-6000 Model 2.5 | 8.31 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0043 | APX-6000 Model 2.5 | 5.20 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0044 | APX-6000 Model 2.5 | 23.08 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | H98UCF9PW6AN | 481CQR0038 | APX-6000 Model 2.5 | 13.03 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1335 | MCS-2000 Model II | 54.36 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M01UGM6PW6BN | 722abl1333 | MCS-2000 Model II | 1.23 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|--|----------|--------------|------------|----------------------|---------------|
| Brookfield, Town | Brookfield Town Police Department | Motorola | m01ugm6pw6bn | 722abl1329 | MCS-2000 Model II | 3.18 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M25URS9PW1AN | 527CQM2271 | APX-6500 Mobile | 0.58 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M25URS9PW1AN | 527CQM2270 | APX-6500 Mobile | 54.68 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M25URS9PW1AN | 527CQM2273 | APX-6500 Mobile | 72.14 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M25URS9PW1AN | 527CQM2274 | APX-6500 Mobile | 141.72 |
| Brookfield, Town | Brookfield Town Police Department | Motorola | M25URS9PW1AN | 527CQM2272 | APX-6500 Mobile | 154.57 |
| | Brookfield Town Police Department Total | | | | | 740.05 |
| Brookfield, Town Total | | | | | | 884.98 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1383 | XTS-5000 Model II FM | 6.49 |
| Butler | Butler Fire Department | Motorola | H18UCF9PW6AN | 721CFV1382 | XTS-5000 Model II FM | 0.11 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0050 | APX-6000XE Model 2.5 | 1.52 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0058 | APX-6000XE Model 2.5 | 2.10 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0067 | APX-6000XE Model 2.5 | 0.08 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0072 | APX-6000XE Model 2.5 | 1.32 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0073 | APX-6000XE Model 2.5 | 1.36 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0074 | APX-6000XE Model 2.5 | 2.65 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0049 | APX-6000XE Model 2.5 | 1.36 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0057 | APX-6000XE Model 2.5 | 0.23 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0054 | APX-6000XE Model 2.5 | 1.99 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0055 | APX-6000XE Model 2.5 | 1.04 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0056 | APX-6000XE Model 2.5 | 1.36 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0051 | APX-6000XE Model 2.5 | 0.25 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0053 | APX-6000XE Model 2.5 | 1.34 |
| Butler | Butler Fire Department | Motorola | H98UCF9PW6AN | 756CQH0052 | APX-6000XE Model 2.5 | 5.15 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0288 | APX-6500 Mobile | 0.80 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0286 | APX-6500 Mobile | 14.58 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0293 | APX-6500 Mobile | 1.64 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0292 | APX-6500 Mobile | 3.51 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0294 | APX-6500 Mobile | 0.88 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0289 | APX-6500 Mobile | 0.71 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0290 | APX-6500 Mobile | 2.45 |
| Butler | Butler Fire Department | Motorola | M25URS9PW1AN | 527CQH0295 | APX-6500 Mobile | 2.96 |
| | Butler Fire Department Total | | | | | 55.88 |
| Butler | Butler Police Department | Motorola | H01UCF6PW1BN | 466CEN0352 | MTS-2000 Model II | 4.68 |
| Butler | Butler Police Department | Motorola | H18UCF9PW6AN | 721CGX2622 | XTS-5000 Model II | 2.80 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------------------|---|----------|--------------|------------|--------------------|---------------|
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2077 | APX-6000 Model 2.5 | 7.19 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2080 | APX-6000 Model 2.5 | 15.50 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2076 | APX-6000 Model 2.5 | 2.39 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2075 | APX-6000 Model 2.5 | 15.76 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2074 | APX-6000 Model 2.5 | 7.39 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2072 | APX-6000 Model 2.5 | 4.78 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2070 | APX-6000 Model 2.5 | 7.50 |
| Butler | Butler Police Department | Motorola | H98UCF9PW6AN | 481CQP2068 | APX-6000 Model 2.5 | 9.78 |
| Butler | Butler Police Department | Motorola | M21URM9PW1AN | 514CJB1883 | XTL-2500 Mobile | 21.65 |
| Butler | Butler Police Department | Motorola | M21URM9PW1AN | 514CKK0792 | XTL-2500 Mobile | 40.45 |
| Butler | Butler Police Department | Motorola | M25URS9PW1AN | 527CQM2999 | APX-6500 Mobile | 62.76 |
| | Butler Police Department Total | | | | | 202.63 |
| Butler Total | | | | | | 258.51 |
| Chenequa | Chenequa Village Fire Department | Motorola | M21URM9PW2AN | 624CJP0950 | XTL-2500RB | 0.27 |
| | Chenequa Village Fire Department Total | | | | | 0.27 |
| Chenequa | Chenequa Village Highway/Forestry Department | Motorola | H98UCD9PW5AN | 481CQP0840 | APX-6000 Model 1.5 | 1.64 |
| Chenequa | Chenequa Village Highway/Forestry Department | Motorola | H98UCD9PW5AN | 481CQP0839 | APX-6000 Model 1.5 | 2.99 |
| | Chenequa Village Highway/Forestry Department Total | | | | | 4.63 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1777 | APX-7000 Model 3.5 | 0.56 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1778 | APX-7000 Model 3.5 | 5.74 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1783 | APX-7000 Model 3.5 | 1.37 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1780 | APX-7000 Model 3.5 | 6.52 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1781 | APX-7000 Model 3.5 | 2.33 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1782 | APX-7000 Model 3.5 | 0.87 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1776 | APX-7000 Model 3.5 | 0.93 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1779 | APX-7000 Model 3.5 | 0.90 |
| Chenequa | Chenequa Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1785 | APX-7000 Model 3.5 | 0.92 |
| Chenequa | Chenequa Village Police Department | Motorola | H98UCF9PW6AN | 481CQP0917 | APX-6000 Model 2.5 | 0.11 |
| Chenequa | Chenequa Village Police Department | Motorola | H98UCF9PW6AN | 481CQP0918 | APX-6000 Model 2.5 | 0.23 |
| Chenequa | Chenequa Village Police Department | Motorola | H98UCF9PW6AN | 481CQP0920 | APX-6000 Model 2.5 | 0.44 |
| Chenequa | Chenequa Village Police Department | Motorola | M25URS9PW1AN | 527CQM3638 | APX-6500 Mobile | 12.35 |
| Chenequa | Chenequa Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1653 | APX-7500 Mobile | 11.96 |
| Chenequa | Chenequa Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1654 | APX-7500 Mobile | 14.15 |
| Chenequa | Chenequa Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1652 | APX-7500 Mobile | 47.51 |
| | Chenequa Village Police Department Total | | | | | 106.89 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------|---|----------|--------------|------------|----------------------|---------------|
| Chenequa Total | | | | | | 111.79 |
| Delafield, City | Delafield City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2378 | MCS-2000 Model II | 0.20 |
| | Delafield City Fire Department Total | | | | | 0.20 |
| Delafield, City | Delafield City Police Department | Motorola | H46UCF9PW6BN | 205CGV2123 | XTS-2500 Model II FM | 0.67 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2411 | APX-6000 Model 2.5 | 2.00 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2418 | APX-6000 Model 2.5 | 25.43 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2417 | APX-6000 Model 2.5 | 12.56 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2416 | APX-6000 Model 2.5 | 9.08 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2415 | APX-6000 Model 2.5 | 6.43 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2414 | APX-6000 Model 2.5 | 5.54 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2412 | APX-6000 Model 2.5 | 36.24 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2419 | APX-6000 Model 2.5 | 27.67 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2421 | APX-6000 Model 2.5 | 26.75 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2413 | APX-6000 Model 2.5 | 19.69 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2424 | APX-6000 Model 2.5 | 14.32 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2422 | APX-6000 Model 2.5 | 7.91 |
| Delafield, City | Delafield City Police Department | Motorola | H98UCF9PW6AN | 481CQP2420 | APX-6000 Model 2.5 | 25.81 |
| Delafield, City | Delafield City Police Department | Motorola | M01UJM6PW6AN | 722AYE2799 | MCS-2000 Model II | 0.63 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CQR0853 | APX-6500 Mobile | 141.11 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CQR0857 | APX-6500 Mobile | 142.77 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CQR0854 | APX-6500 Mobile | 7.85 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CQR0852 | APX-6500 Mobile | 8.46 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CQR0856 | APX-6500 Mobile | 42.74 |
| Delafield, City | Delafield City Police Department | Motorola | M25URS9PW1AN | 527CPM0786 | APX-6500 Mobile | 47.53 |
| | Delafield City Police Department Total | | | | | 611.19 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3123 | MCS-2000 Model II | 0.08 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3119 | MCS-2000 Model II | 0.29 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2400 | MCS-2000 Model II | 0.28 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2797 | MCS-2000 Model II | 0.09 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE3121 | MCS-2000 Model II | 0.66 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2794 | MCS-2000 Model II | 0.23 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2796 | MCS-2000 Model II | 0.45 |
| Delafield, City | Delafield City Public Works Department | Motorola | M01UJM6PW6AN | 722AYE2473 | MCS-2000 Model II | 0.35 |
| Delafield, City | Delafield City Public Works Department | Motorola | M22URS9PW1AN | 471CQZ6206 | APX-4500 Mobile | 0.95 |
| | Delafield City Public Works Department Total | | | | | 3.38 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------------------|--------------------------------|----------|--------------|------------|----------------------|---------------|
| Delafield, City Total | | | | | | 614.77 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CRF0007 | APX-7000XE Model 3.5 | 3.37 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CQR0062 | APX-7000XE Model 3.5 | 2.72 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0420 | APX-7000XE Model 3.5 | 1.65 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0422 | APX-7000XE Model 3.5 | 0.05 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0400 | APX-7000XE Model 3.5 | 1.71 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0390 | APX-7000XE Model 3.5 | 3.83 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0391 | APX-7000XE Model 3.5 | 3.34 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0392 | APX-7000XE Model 3.5 | 3.26 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0393 | APX-7000XE Model 3.5 | 0.17 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0394 | APX-7000XE Model 3.5 | 3.48 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0395 | APX-7000XE Model 3.5 | 0.42 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0396 | APX-7000XE Model 3.5 | 4.24 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0397 | APX-7000XE Model 3.5 | 0.85 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0411 | APX-7000XE Model 3.5 | 0.14 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0399 | APX-7000XE Model 3.5 | 7.59 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0413 | APX-7000XE Model 3.5 | 0.38 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0401 | APX-7000XE Model 3.5 | 2.42 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0404 | APX-7000XE Model 3.5 | 8.08 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0405 | APX-7000XE Model 3.5 | 6.56 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0407 | APX-7000XE Model 3.5 | 0.35 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0409 | APX-7000XE Model 3.5 | 0.25 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0412 | APX-7000XE Model 3.5 | 1.35 |
| Delafield, Town | Delafield Town Fire Department | Motorola | H49TGD9PW1AN | 562CPP0398 | APX-7000XE Model 3.5 | 4.39 |
| Delafield, Town | Delafield Town Fire Department | Motorola | L30TSS9PW1AN | 761CQP0092 | APX-7500 Consolette | 6.21 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M25URS9PW1AN | 527CMR0115 | APX-6500 Mobile | 1.35 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1762 | APX-7500 Mobile | 0.11 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1758 | APX-7500 Mobile | 16.01 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1768 | APX-7500 Mobile | 0.15 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1767 | APX-7500 Mobile | 2.27 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1766 | APX-7500 Mobile | 3.01 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1764 | APX-7500 Mobile | 1.85 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1765 | APX-7500 Mobile | 1.69 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1761 | APX-7500 Mobile | 0.56 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1760 | APX-7500 Mobile | 4.52 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------------------|---|----------|--------------|------------|--------------------|---------------|
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1759 | APX-7500 Mobile | 3.09 |
| Delafield, Town | Delafield Town Fire Department | Motorola | M30TSS9PW1AN | 656CPM1769 | APX-7500 Mobile | 0.68 |
| | Delafield Town Fire Department Total | | | | | 102.10 |
| Delafield, Town Total | | | | | | 102.10 |
| Dousman | Dousman Police Department | Motorola | H18UCF9PW6AN | 721CEA4982 | XTS-5000 Model II | 0.62 |
| | Dousman Police Department Total | | | | | 0.62 |
| Dousman Total | | | | | | 0.62 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H18UCF9PW6AN | 721CJZ0901 | XTS-5000 Model II | 6.47 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H18UCF9PW6AN | 721CLB0221 | XTS-5000 Model II | 1.71 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H18UCF9PW6AN | 721CMK0219 | XTS-5000 Model II | 1.27 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H18UCF9PW6AN | 721CLB0222 | XTS-5000 Model II | 9.12 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6223 | APX-6000 Model 2.5 | 1.34 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6206 | APX-6000 Model 2.5 | 8.56 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6199 | APX-6000 Model 2.5 | 2.95 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6200 | APX-6000 Model 2.5 | 3.66 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6201 | APX-6000 Model 2.5 | 3.91 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6202 | APX-6000 Model 2.5 | 2.05 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6203 | APX-6000 Model 2.5 | 0.97 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6204 | APX-6000 Model 2.5 | 2.56 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6205 | APX-6000 Model 2.5 | 0.35 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6232 | APX-6000 Model 2.5 | 3.21 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CPF0406 | APX-6000 Model 2.5 | 4.13 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CPF0407 | APX-6000 Model 2.5 | 2.92 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CMK0768 | APX-6000 Model 2.5 | 14.45 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CMK0767 | APX-6000 Model 2.5 | 10.01 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CMK0769 | APX-6000 Model 2.5 | 0.79 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6221 | APX-6000 Model 2.5 | 0.11 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6233 | APX-6000 Model 2.5 | 4.78 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6207 | APX-6000 Model 2.5 | 4.97 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6231 | APX-6000 Model 2.5 | 1.74 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6230 | APX-6000 Model 2.5 | 17.59 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6229 | APX-6000 Model 2.5 | 1.16 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6227 | APX-6000 Model 2.5 | 1.16 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6226 | APX-6000 Model 2.5 | 1.53 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6217 | APX-6000 Model 2.5 | 1.74 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--------------------------------------|--------------------------------------|----------|--------------|------------|--------------------|---------------|
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6225 | APX-6000 Model 2.5 | 0.80 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6212 | APX-6000 Model 2.5 | 3.71 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6211 | APX-6000 Model 2.5 | 0.11 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6216 | APX-6000 Model 2.5 | 13.23 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6219 | APX-6000 Model 2.5 | 1.23 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6220 | APX-6000 Model 2.5 | 3.06 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6222 | APX-6000 Model 2.5 | 0.82 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6210 | APX-6000 Model 2.5 | 0.10 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6209 | APX-6000 Model 2.5 | 1.64 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6208 | APX-6000 Model 2.5 | 1.00 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6224 | APX-6000 Model 2.5 | 6.51 |
| Dousman Fire Department | Dousman Fire Department | Motorola | H98UCF9PW6AN | 481CQX6213 | APX-6000 Model 2.5 | 6.84 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1364 | MCS-2000 Model II | 9.21 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1409 | MCS-2000 Model II | 6.95 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UGM6PW6BN | 722ABS1381 | MCS-2000 Model II | 28.42 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UJM6PW6AN | 722AXY0632 | MCS-2000 Model II | 8.02 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UJM6PW6AN | 722AXY0624 | MCS-2000 Model II | 2.88 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UJM6PW6AN | 722AXY0628 | MCS-2000 Model II | 10.00 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M01UJM6PW6BN | 722AAW1858 | MCS-2000 Model II | 0.05 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M20URS9PW1AN | 500CLB0217 | XTL-5000 Mobile | 4.96 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M21URM9PW1AN | 514CFV1035 | XTL-2500 Mobile | 0.65 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M21URM9PW1AN | 514CJV1655 | XTL-2500 Mobile | 4.98 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M25URS9PW1AN | 527CQX2452 | APX-6500 Mobile | 46.09 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M25URS9PW1AN | 527CPF0006 | APX-6500 Mobile | 17.32 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M25URS9PW1AN | 527CNB0165 | APX-6500 Mobile | 36.16 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M25URS9PW1AN | 527CQX2451 | APX-6500 Mobile | 1.57 |
| Dousman Fire Department | Dousman Fire Department | Motorola | M25URS9PW1AN | 527CNB0166 | APX-6500 Mobile | 1.16 |
| | Dousman Fire Department Total | | | | | 332.68 |
| Dousman Fire Department Total | | | | | | 332.68 |
| Eagle Fire District | Eagle Fire District | Motorola | H01UCD6PW1BN | 466ABG2998 | MTS-2000 Model I | 0.07 |
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CGZ4331 | XTS-5000 Model II | 1.39 |
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CGZ4328 | XTS-5000 Model II | 4.52 |
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CGZ4327 | XTS-5000 Model II | 3.34 |
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CHT0782 | XTS-5000 Model II | 14.70 |
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CHT0784 | XTS-5000 Model II | 9.18 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------------------------|--|----------|--------------|------------|----------------------|--------------|
| Eagle Fire District | Eagle Fire District | Motorola | H18UCF9PW6AN | 721CND0009 | XTS-5000 Model II FM | 3.71 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205CFZ1913 | XTS-2500 Model II FM | 1.86 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205CFZ1914 | XTS-2500 Model II FM | 0.99 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205CFZ1911 | XTS-2500 Model II FM | 1.02 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6AN | 205CFZ1918 | XTS-2500 Model II FM | 0.05 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2274 | XTS-2500 Model II | 1.43 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2290 | XTS-2500 Model II | 0.10 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2282 | XTS-2500 Model II | 0.01 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2277 | XTS-2500 Model II | 0.60 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2268 | XTS-2500 Model II | 0.58 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2275 | XTS-2500 Model II | 6.48 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2287 | XTS-2500 Model II | 1.23 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2258 | XTS-2500 Model II | 1.16 |
| Eagle Fire District | Eagle Fire District | Motorola | H46UCF9PW6BN | 205CMG2265 | XTS-2500 Model II | 2.14 |
| Eagle Fire District | Eagle Fire District | Motorola | M21URM9PW1AN | 514CGB0041 | XTL-2500 Mobile | 0.21 |
| Eagle Fire District | Eagle Fire District | Motorola | M21URM9PW1AN | 514CGB0042 | XTL-2500 Mobile | 0.14 |
| Eagle Fire District | Eagle Fire District | Motorola | M21URM9PW1AN | 514CGB0040 | XTL-2500 Mobile | 2.85 |
| Eagle Fire District | Eagle Fire District | Motorola | M21URM9PW1AN | 514CGB0039 | XTL-2500 Mobile | 1.49 |
| Eagle Fire District | Eagle Fire District | Motorola | M25URS9PW1AN | 527CRH0845 | APX-6500 Mobile | 8.88 |
| Eagle Fire District | Eagle Fire District | Motorola | M30TSS9PW1AN | 656CRH0326 | APX-7500 Mobile | 9.41 |
| Eagle Fire District | Eagle Fire District | Motorola | M30TSS9PW1AN | 656CQP0453 | APX-7500 Mobile | 0.40 |
| | Eagle Fire District Total | | | | | 77.94 |
| Eagle Fire District Total | | | | | | 77.94 |
| Eagle, Town | Eagle Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0442 | XTL-2500RB | 3.78 |
| Eagle, Town | Eagle Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0441 | XTL-2500RB | 3.86 |
| | Eagle Town Highway Department Total | | | | | 7.64 |
| Eagle, Town Total | | | | | | 7.64 |
| Eagle, Village | Eagle Village Police Department | Motorola | H46UCF9PW6BN | 205CJK6523 | XTS-2500 Model II | 1.18 |
| Eagle, Village | Eagle Village Police Department | Motorola | H46UCF9PW6BN | 205CMG2285 | XTS-2500 Model II | 10.93 |
| Eagle, Village | Eagle Village Police Department | Motorola | H46UCF9PW6BN | 205CMG2270 | XTS-2500 Model II | 2.09 |
| Eagle, Village | Eagle Village Police Department | Motorola | H46UCF9PW6BN | 205CMG2260 | XTS-2500 Model II | 15.03 |
| Eagle, Village | Eagle Village Police Department | Motorola | H98UCF9PW6AN | 481CRB2363 | APX-6000 Model 2.5 | 2.61 |
| Eagle, Village | Eagle Village Police Department | Motorola | H98UCF9PW6AN | 481CRB2364 | APX-6000 Model 2.5 | 6.69 |
| Eagle, Village | Eagle Village Police Department | Motorola | M21URM9PW1AN | 500CGS7243 | XTL-2500 Mobile | 20.33 |
| Eagle, Village | Eagle Village Police Department | Motorola | M21URM9PW2AN | 624CJP0443 | XTL-2500RB | 45.92 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------------|---|----------|--------------|------------|----------------------|---------------|
| | Eagle Village Police Department Total | | | | | 104.78 |
| Eagle, Village Total | | | | | | 104.78 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3364 | MTS-2000 Model II | 0.67 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466CEW0427 | MTS-2000 Model II | 0.05 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3365 | MTS-2000 Model II | 0.11 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3371 | MTS-2000 Model II | 0.90 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3369 | MTS-2000 Model II | 0.18 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H01UCF6PW1BN | 466ABS3396 | MTS-2000 Model II | 2.10 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H18UCF9PW6AN | 721CHF0206 | XTS-5000 Model II FM | 0.41 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H18UCF9PW6AN | 721CHF0209 | XTS-5000 Model II FM | 0.72 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H18UCF9PW6AN | 721CHF0205 | XTS-5000 Model II FM | 0.27 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H98UCF9PW6AN | 481CQFC212 | APX-6000 Model 2.5 | 0.13 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | H98UCF9PW6AN | 481CQFC216 | APX-6000 Model 2.5 | 0.39 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1432 | MCS-2000 Model II | 1.15 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1437 | MCS-2000 Model II | 16.27 |
| Elm Grove | Elm Grove Emergency Medical Services | Motorola | M01UGM6PW6BN | 722ABS1431 | MCS-2000 Model II | 0.47 |
| | Elm Grove Emergency Medical Services Total | | | | | 23.82 |
| Elm Grove | Elm Grove Fire Department | Motorola | H01UCF6PW1BN | 466ABS3473 | MTS-2000 Model II FM | 0.21 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CQFC245 | APX-6000 Model 2.5 | 2.37 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1890 | APX-6000XE Model 2.5 | 0.42 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQM1360 | APX-6000XE Model 2.5 | 0.10 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1883 | APX-6000XE Model 2.5 | 0.45 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1884 | APX-6000XE Model 2.5 | 0.44 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1885 | APX-6000XE Model 2.5 | 0.11 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1887 | APX-6000XE Model 2.5 | 0.84 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1888 | APX-6000XE Model 2.5 | 1.61 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CQFC248 | APX-6000 Model 2.5 | 0.10 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1889 | APX-6000XE Model 2.5 | 0.68 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CQFC244 | APX-6000 Model 2.5 | 0.37 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1891 | APX-6000XE Model 2.5 | 0.05 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 756CQF1893 | APX-6000XE Model 2.5 | 0.14 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CQFC242 | APX-6000 Model 2.5 | 10.70 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CQFC243 | APX-6000 Model 2.5 | 0.71 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CPB1260 | APX-6000 Model 2.5 | 0.10 |
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CPB1259 | APX-6000 Model 2.5 | 8.44 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------|--|----------|--------------|------------|--------------------|--------------|
| Elm Grove | Elm Grove Fire Department | Motorola | H98UCF9PW6AN | 481CPB1261 | APX-6000 Model 2.5 | 4.47 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1416 | MCS-2000 Model II | 1.18 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1377 | MCS-2000 Model II | 5.06 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1421 | MCS-2000 Model II | 0.99 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1426 | MCS-2000 Model II | 1.25 |
| Elm Grove | Elm Grove Fire Department | Motorola | M01UGM6PW6BN | 722ABS1423 | MCS-2000 Model II | 0.40 |
| | Elm Grove Fire Department Total | | | | | 41.19 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3404 | MTS-2000 Model II | 22.23 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3384 | MTS-2000 Model II | 1.72 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3389 | MTS-2000 Model II | 0.45 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466CDY1171 | MTS-2000 Model II | 9.25 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3378 | MTS-2000 Model II | 7.74 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3382 | MTS-2000 Model II | 0.66 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3385 | MTS-2000 Model II | 1.50 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3405 | MTS-2000 Model II | 8.14 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3410 | MTS-2000 Model II | 7.94 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3412 | MTS-2000 Model II | 0.45 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3393 | MTS-2000 Model II | 12.50 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3383 | MTS-2000 Model II | 7.67 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3403 | MTS-2000 Model II | 2.43 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3411 | MTS-2000 Model II | 6.84 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3395 | MTS-2000 Model II | 18.34 |
| Elm Grove | Elm Grove Police Department | Motorola | H01UCF6PW1BN | 466ABS3387 | MTS-2000 Model II | 0.20 |
| Elm Grove | Elm Grove Police Department | Motorola | H98UCF9PW6AN | 481CQFC226 | APX-6000 Model 2.5 | 13.06 |
| Elm Grove | Elm Grove Police Department | Motorola | H98UCF9PW6AN | 481CQFC224 | APX-6000 Model 2.5 | 28.22 |
| Elm Grove | Elm Grove Police Department | Motorola | H98UCF9PW6AN | 481CQFC223 | APX-6000 Model 2.5 | 1.21 |
| Elm Grove | Elm Grove Police Department | Motorola | H98UCF9PW6AN | 481CQFC225 | APX-6000 Model 2.5 | 25.63 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3130 | MCS-2000 Model I | 21.64 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3129 | MCS-2000 Model I | 26.16 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3127 | MCS-2000 Model I | 380.16 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGL6PW4BN | 722ABE3128 | MCS-2000 Model I | 0.17 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1419 | MCS-2000 Model II | 76.76 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1366 | MCS-2000 Model II | 3.34 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1370 | MCS-2000 Model II | 2.76 |
| Elm Grove | Elm Grove Police Department | Motorola | M01UGM6PW6BN | 722ABS1355 | MCS-2000 Model II | 1.80 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--|--|--------------|----------------|-----------------|----------------------|-----------------|
| Elm Grove | Elm Grove Police Department | Motorola | M21URM9PW2AN | 624CJP1002 | XTL-2500RB | 0.23 |
| Elm Grove | Elm Grove Police Department | Motorola | M25URS9PW1AN | 527CQF3504 | APX-6500 Mobile | 70.67 |
| Elm Grove | Elm Grove Police Department | Motorola | M25URS9PW1AN | 527CPB0427 | APX-6500 Mobile | 0.12 |
| Elm Grove | Elm Grove Police Department | Motorola | M25URS9PW1AN | 527CQF3500 | APX-6500 Mobile | 104.36 |
| Elm Grove | Elm Grove Police Department | Motorola | M25URS9PW1AN | 527CQF3501 | APX-6500 Mobile | 82.91 |
| | Elm Grove Police Department Total | | | | | 947.26 |
| Elm Grove | Elm Grove Public Works Department | Motorola | H46UCF9PW6BN | 205CJF0414 | XTS-2500 Model II FM | 1.75 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M01UGM6PW6BN | 722ABS1398 | MCS-2000 Model II | 0.35 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M01UGM6PW6BN | 722ABS1374 | MCS-2000 Model II | 3.07 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1005 | XTL-2500RB | 3.50 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1006 | XTL-2500RB | 3.20 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1003 | XTL-2500RB | 2.03 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1008 | XTL-2500RB | 0.42 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1004 | XTL-2500RB | 0.28 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1013 | XTL-2500RB | 2.31 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1011 | XTL-2500RB | 1.24 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1010 | XTL-2500RB | 2.43 |
| Elm Grove | Elm Grove Public Works Department | Motorola | M21URM9PW2AN | 624CJP1009 | XTL-2500RB | 3.02 |
| | Elm Grove Public Works Department Total | | | | | 23.60 |
| Elm Grove Total | | | | | | 1,035.87 |
| Franklin | Franklin Police Department | Motorola | H18UCF9PW6AN | 721CKM2923 | XTS-5000 Model II | 0.68 |
| Franklin | Franklin Police Department | Motorola | H98UCF9PW6AN | 481CNX0689 | APX-6000 Model 2.5 | 1.07 |
| Franklin | Franklin Police Department | Motorola | M25URS9PW1AN | 527CNZ0043 | APX-6500 Mobile | 1.32 |
| Franklin | Franklin Police Department | Motorola | M25URS9PW1AN | 527CNZ0046 | APX-6500 Mobile | 0.08 |
| Franklin | Franklin Police Department | Motorola | M25URS9PW1AN | 527CNZ0037 | APX-6500 Mobile | 0.71 |
| | Franklin Police Department Total | | | | | 3.86 |
| Franklin Total | | | | | | 3.86 |
| Froedtert & The Medical College of WI | Community Memorial Hospital | Motorola | L04UJH9PW9AN | 761CEW0110 | Base, low power | 0.79 |
| | Community Memorial Hospital Total | | | | | 0.79 |
| Froedtert & The Medical College of WI Total | | | | | | 0.79 |
| Hales Corners | Hales Corners Police Department | Motorola | M21URM9PW1AN | 514CGX2975 | XTL-2500 Mobile | 0.66 |
| | Hales Corners Police Department Total | | | | | 0.66 |
| Hales Corners Total | | | | | | 0.66 |
| Hartland | Hartland Fire Department | E.F. Johnson | 242-527E974R16 | 5170F3811C37532 | 51XX Portable | 0.20 |
| Hartland | Hartland Fire Department | E.F. Johnson | 242-527E974R16 | 5170F3811C37500 | 51XX Portable | 0.37 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------|--------------------------|----------|--------------|------------|----------------------|-------|
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABS3062 | MTS-2000 Model I | 3.49 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3334 | MTS-2000 Model I | 1.34 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3329 | MTS-2000 Model I | 1.37 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3324 | MTS-2000 Model I | 1.59 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3333 | MTS-2000 Model I | 2.87 |
| Hartland | Hartland Fire Department | Motorola | H01UCD6PW1BN | 466ABL3325 | MTS-2000 Model I | 0.11 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0282 | XTS-5000 Model II FM | 0.80 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJB2098 | XTS-5000 Model II | 0.29 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJB2097 | XTS-5000 Model II | 2.61 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0280 | XTS-5000 Model II FM | 0.18 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0286 | XTS-5000 Model II FM | 0.01 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0284 | XTS-5000 Model II FM | 1.87 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0285 | XTS-5000 Model II FM | 0.52 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CJK0283 | XTS-5000 Model II FM | 4.21 |
| Hartland | Hartland Fire Department | Motorola | H18UCF9PW6AN | 721CLR0861 | XTS-5000 Model II | 0.38 |
| Hartland | Hartland Fire Department | Motorola | H49TGD9PW1AN | 562CQM0331 | APX-7000XE Model 3.5 | 11.98 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5275 | APX-6000 Model 2.5 | 19.25 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5277 | APX-6000 Model 2.5 | 3.28 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM4048 | APX-6000 Model 2.5 | 0.22 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM4047 | APX-6000 Model 2.5 | 3.77 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5276 | APX-6000 Model 2.5 | 14.06 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM0207 | APX-6000 Model 2.5 | 0.38 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM0203 | APX-6000 Model 2.5 | 0.19 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM0204 | APX-6000 Model 2.5 | 2.11 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM0205 | APX-6000 Model 2.5 | 3.03 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM0206 | APX-6000 Model 2.5 | 0.81 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5279 | APX-6000 Model 2.5 | 1.65 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5281 | APX-6000 Model 2.5 | 1.49 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5284 | APX-6000 Model 2.5 | 10.72 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5283 | APX-6000 Model 2.5 | 10.73 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5282 | APX-6000 Model 2.5 | 4.35 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5280 | APX-6000 Model 2.5 | 3.90 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CQM5278 | APX-6000 Model 2.5 | 0.52 |
| Hartland | Hartland Fire Department | Motorola | H98UCF9PW6AN | 481CPMD317 | APX-6000 Model 2.5 | 1.34 |
| Hartland | Hartland Fire Department | Motorola | M01UGM6PW6BN | 722ABL1325 | MCS-2000 Model II | 0.95 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------|---------------------------------------|----------|--------------|------------|----------------------|---------------|
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0936 | XTL-5000 Mobile | 1.38 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0934 | XTL-5000 Mobile | 33.89 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0933 | XTL-5000 Mobile | 3.67 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0938 | XTL-5000 Mobile | 0.40 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0939 | XTL-5000 Mobile | 3.63 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0940 | XTL-5000 Mobile | 1.05 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0932 | XTL-5000 Mobile | 0.57 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0931 | XTL-5000 Mobile | 0.26 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0930 | XTL-5000 Mobile | 9.49 |
| Hartland | Hartland Fire Department | Motorola | M20URS9PW1AN | 500CJP0935 | XTL-5000 Mobile | 4.73 |
| Hartland | Hartland Fire Department | Motorola | M25URS9PW1AN | 527CQM0977 | APX-6500 Mobile | 4.69 |
| | Hartland Fire Department Total | | | | | 180.70 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0308 | XTS-5000 Model II FM | 12.29 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0296 | XTS-5000 Model II FM | 15.20 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0295 | XTS-5000 Model II FM | 14.88 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0294 | XTS-5000 Model II FM | 17.69 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0293 | XTS-5000 Model II FM | 11.38 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0300 | XTS-5000 Model II FM | 0.28 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0299 | XTS-5000 Model II FM | 2.35 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0302 | XTS-5000 Model II FM | 13.16 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0298 | XTS-5000 Model II FM | 6.90 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0290 | XTS-5000 Model II FM | 12.87 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0292 | XTS-5000 Model II FM | 0.06 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0291 | XTS-5000 Model II FM | 0.05 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0307 | XTS-5000 Model II FM | 14.74 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0306 | XTS-5000 Model II FM | 15.73 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0303 | XTS-5000 Model II FM | 4.76 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0297 | XTS-5000 Model II FM | 29.46 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0304 | XTS-5000 Model II FM | 0.89 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0288 | XTS-5000 Model II FM | 9.72 |
| Hartland | Hartland Police Department | Motorola | H18UCF9PW6AN | 721CJK0301 | XTS-5000 Model II FM | 13.29 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJP0943 | XTL-5000 Mobile | 1.87 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJP0942 | XTL-5000 Mobile | 45.97 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJP0946 | XTL-5000 Mobile | 76.73 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJB0921 | XTL-5000 Mobile | 6.09 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------------------|---|----------|--------------|------------|----------------------|---------------|
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJP0941 | XTL-5000 Mobile | 0.55 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJP0944 | XTL-5000 Mobile | 35.85 |
| Hartland | Hartland Police Department | Motorola | M20URS9PW1AN | 500CJB0920 | XTL-5000 Mobile | 89.74 |
| Hartland | Hartland Police Department | Motorola | M25URS9PW1AN | 527CNX2139 | APX-6500 Mobile | 28.38 |
| | Hartland Police Department Total | | | | | 480.88 |
| Hartland | Hartland Public Works Department | Motorola | H18UCF9PW6AN | 721CJK0273 | XTS-5000 Model II FM | 0.05 |
| Hartland | Hartland Public Works Department | Motorola | M20URS9PW1AN | 500CJP0964 | XTL-5000 Mobile | 0.94 |
| | Hartland Public Works Department Total | | | | | 0.99 |
| Hartland Total | | | | | | 662.57 |
| Ixonia | Ixonia Fire Department | Motorola | H46UCD9PW5BN | 205CNX2657 | XTS-2500 Model I | 0.71 |
| Ixonia | Ixonia Fire Department | Motorola | M21URM9PW1AN | 514CMZ0441 | XTL-2500 Mobile | 7.53 |
| | Ixonia Fire Department Total | | | | | 8.24 |
| Ixonia Total | | | | | | 8.24 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0574 | APX-7000XE Model 3.5 | 4.27 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0580 | APX-7000XE Model 3.5 | 3.36 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0496 | APX-7000XE Model 3.5 | 0.27 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0579 | APX-7000XE Model 3.5 | 4.12 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0578 | APX-7000XE Model 3.5 | 0.84 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0577 | APX-7000XE Model 3.5 | 4.05 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0500 | APX-7000XE Model 3.5 | 0.18 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0573 | APX-7000XE Model 3.5 | 6.54 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0575 | APX-7000XE Model 3.5 | 4.54 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0502 | APX-7000XE Model 3.5 | 0.31 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0571 | APX-7000XE Model 3.5 | 9.54 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0572 | APX-7000XE Model 3.5 | 1.57 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0570 | APX-7000XE Model 3.5 | 6.89 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0584 | APX-7000XE Model 3.5 | 4.71 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0490 | APX-7000XE Model 3.5 | 0.62 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0582 | APX-7000XE Model 3.5 | 8.33 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0569 | APX-7000XE Model 3.5 | 1.01 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0583 | APX-7000XE Model 3.5 | 1.37 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0493 | APX-7000XE Model 3.5 | 3.21 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CQP0498 | APX-7000XE Model 3.5 | 0.06 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H49TGD9PW1AN | 562CPD0015 | APX-7000XE Model 3.5 | 3.34 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2654 | APX-6000XE Model 2.5 | 0.44 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---|---|----------|--------------|------------|-----------------------|---------------|
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2657 | APX-6000XE Model 2.5 | 0.55 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2662 | APX-6000XE Model 2.5 | 1.01 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2663 | APX-6000XE Model 2.5 | 1.76 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2652 | APX-6000XE Model 2.5 | 1.58 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | H98UCF9PW6AN | 756CQP2653 | APX-6000XE Model 2.5 | 0.25 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1765 | APX-7500 Mobile | 0.36 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1764 | APX-7500 Mobile | 1.11 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1763 | APX-7500 Mobile | 0.06 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1761 | APX-7500 Mobile | 9.01 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1759 | APX-7500 Mobile | 7.85 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1760 | APX-7500 Mobile | 0.99 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1762 | APX-7500 Mobile | 4.20 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1767 | APX-7500 Mobile | 24.35 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1758 | APX-7500 Mobile | 18.90 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1766 | APX-7500 Mobile | 1.32 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CQM1768 | APX-7500 Mobile | 0.41 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CPB2211 | APX-7500 Mobile | 2.73 |
| Lake Country Fire Department | Lake Country Fire Department | Motorola | M30TSS9PW1AN | 656CPB2212 | APX-7500 Mobile | 11.37 |
| | Lake Country Fire Department Total | | | | | 157.38 |
| Lake Country Fire Department Total | | | | | | 157.38 |
| Lannon | Lannon Fire Department | Motorola | H18UCF9PW6AN | 721CLF4564 | XTS-5000 Model II FM | 2.12 |
| Lannon | Lannon Fire Department | Motorola | H18UCF9PW6AN | 721CLF4548 | XTS-5000 Model II FM | 1.57 |
| Lannon | Lannon Fire Department | Motorola | H18UCF9PW6AN | 721CLF4556 | XTS-5000 Model II FM | 0.71 |
| Lannon | Lannon Fire Department | Motorola | H18UCF9PW6AN | 721CLF4565 | XTS-5000 Model II FM | 1.95 |
| Lannon | Lannon Fire Department | Motorola | H18UCF9PW6AN | 721CLF4553 | XTS-5000 Model II FM | 2.59 |
| Lannon | Lannon Fire Department | Motorola | M21URM9PW1AN | 514CLF3635 | XTL-2500 Dual Control | 68.62 |
| Lannon | Lannon Fire Department | Motorola | M21URM9PW1AN | 514CLF3544 | XTL-2500 Mobile | 0.25 |
| | Lannon Fire Department Total | | | | | 77.81 |
| Lannon | Lannon Police Department | Motorola | H46UCF9PW6BN | 205CJZ0394 | XTS-2500 Model II FM | 5.88 |
| Lannon | Lannon Police Department | Motorola | H46UCF9PW6BN | 205CJB4697 | XTS-2500 Model II | 6.57 |
| Lannon | Lannon Police Department | Motorola | H46UCF9PW6BN | 205CJB4698 | XTS-2500 Model II | 10.41 |
| Lannon | Lannon Police Department | Motorola | M20URS9PW1AN | 500CJD0826 | XTL-5000 Mobile | 42.49 |
| Lannon | Lannon Police Department | Motorola | M20URS9PW1AN | 500CJD0825 | XTL-5000 Mobile | 18.54 |
| | Lannon Police Department Total | | | | | 83.89 |
| Lannon Total | | | | | | 161.70 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--------|-------------------------------------|--------------|-----------------|-----------------|----------------------|---------------|
| Lisbon | Lisbon Fire Department | E.F. Johnson | 242-527E-074BQ6 | 5170F3811C37542 | 51XX Portable | 0.06 |
| Lisbon | Lisbon Fire Department | E.F. Johnson | 242-527E-074BQ6 | 5170F3811C37454 | 51XX Portable | 0.49 |
| Lisbon | Lisbon Fire Department | E.F. Johnson | 242-527E-074BQ6 | 5170F3811C37354 | 51XX Portable | 0.47 |
| Lisbon | Lisbon Fire Department | E.F. Johnson | 242-527E-074BQ6 | 5170F3711C37111 | 51XX Portable | 0.16 |
| Lisbon | Lisbon Fire Department | E.F. Johnson | 242-527E-074BQ6 | 5170F3811C37451 | 51XX Portable | 0.33 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCD6PW1BN | 466ABE5001 | MTS-2000 Model I | 0.42 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1900 | MTS-2000 Model II | 3.51 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCF6PW1BN | 466ABE1896 | MTS-2000 Model II | 1.17 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4026 | MTS-2000 Model III | 1.44 |
| Lisbon | Lisbon Fire Department | Motorola | H01UCH6PW1BN | 466AAL4035 | MTS-2000 Model III | 2.88 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6569 | XTS-5000 Model II FM | 6.39 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6573 | XTS-5000 Model II FM | 0.37 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6570 | XTS-5000 Model II FM | 0.72 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6574 | XTS-5000 Model II FM | 1.84 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6575 | XTS-5000 Model II FM | 0.52 |
| Lisbon | Lisbon Fire Department | Motorola | H18UCF9PW6AN | 721CJF6568 | XTS-5000 Model II FM | 1.63 |
| Lisbon | Lisbon Fire Department | Motorola | H46UCF9PW6AN | 205CGP0257 | XTS-2500 Model II FM | 2.64 |
| Lisbon | Lisbon Fire Department | Motorola | H46UCF9PW6AN | 205CGP0259 | XTS-2500 Model II FM | 2.92 |
| Lisbon | Lisbon Fire Department | Motorola | H98UCF9PW6AN | 756CQR0006 | APX-6000XE Model 2.5 | 2.47 |
| Lisbon | Lisbon Fire Department | Motorola | H98UCF9PW6AN | 756CQR0008 | APX-6000XE Model 2.5 | 2.68 |
| Lisbon | Lisbon Fire Department | Motorola | H98UCF9PW6AN | 756CQR0009 | APX-6000XE Model 2.5 | 6.31 |
| Lisbon | Lisbon Fire Department | Motorola | H98UCF9PW6AN | 756CQR0005 | APX-6000XE Model 2.5 | 1.73 |
| Lisbon | Lisbon Fire Department | Motorola | M01UGM6PW6BN | 722ABS1372 | MCS-2000 Model II | 1.27 |
| Lisbon | Lisbon Fire Department | Motorola | M01UGM6PW6BN | 722ABS1354 | MCS-2000 Model II | 31.93 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW1AN | 514CHD2157 | XTL-2500 Mobile | 0.20 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW1AN | 514CHD2156 | XTL-2500 Mobile | 22.24 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0432 | XTL-2500RB | 0.18 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0434 | XTL-2500RB | 11.99 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0435 | XTL-2500RB | 2.12 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0431 | XTL-2500RB | 3.22 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0429 | XTL-2500RB | 2.04 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0438 | XTL-2500RB | 1.50 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0426 | XTL-2500RB | 3.80 |
| Lisbon | Lisbon Fire Department | Motorola | M21URM9PW2AN | 624CJP0428 | XTL-2500RB | 2.34 |
| | Lisbon Fire Department Total | | | | | 123.98 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------------------|---------------------------------|----------|--------------|------------|----------------------|---------------|
| Lisbon Total | | | | | | 123.98 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2406 | XTS-5000 Model II FM | 16.30 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2402 | XTS-5000 Model II FM | 0.95 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1727 | XTS-5000 Model II FM | 1.95 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CHF6497 | XTS-5000 Model II FM | 11.62 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CHF6498 | XTS-5000 Model II FM | 0.34 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2401 | XTS-5000 Model II FM | 4.76 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CHF6499 | XTS-5000 Model II FM | 2.56 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1285 | XTS-5000 Model II | 0.63 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1298 | XTS-5000 Model II | 0.11 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1297 | XTS-5000 Model II | 3.99 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2687 | XTS-5000 Model II FM | 1.32 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1292 | XTS-5000 Model II | 0.11 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1301 | XTS-5000 Model II | 0.33 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2686 | XTS-5000 Model II FM | 6.42 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1733 | XTS-5000 Model II FM | 0.79 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1293 | XTS-5000 Model II | 1.02 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1736 | XTS-5000 Model II FM | 2.51 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1282 | XTS-5000 Model II | 1.04 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1283 | XTS-5000 Model II | 1.16 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1288 | XTS-5000 Model II | 2.63 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1291 | XTS-5000 Model II | 0.18 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1284 | XTS-5000 Model II | 0.31 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1295 | XTS-5000 Model II | 0.69 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFM2684 | XTS-5000 Model II FM | 0.70 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1739 | XTS-5000 Model II FM | 0.14 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB008 | XTS-5000 Model II FM | 2.70 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB005 | XTS-5000 Model II FM | 2.11 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFTB004 | XTS-5000 Model II FM | 0.85 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1740 | XTS-5000 Model II FM | 0.22 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1725 | XTS-5000 Model II FM | 0.21 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1724 | XTS-5000 Model II FM | 2.67 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CKH1300 | XTS-5000 Model II | 0.57 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1726 | XTS-5000 Model II FM | 0.53 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1737 | XTS-5000 Model II FM | 3.53 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|--|----------|--------------|------------|-----------------------|---------------|
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1732 | XTS-5000 Model II FM | 3.20 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1731 | XTS-5000 Model II FM | 1.70 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1729 | XTS-5000 Model II FM | 3.71 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1730 | XTS-5000 Model II FM | 3.92 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1738 | XTS-5000 Model II FM | 3.24 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721CFP1743 | XTS-5000 Model II FM | 2.31 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | H18UCF9PW6AN | 721cgb2400 | XTS-5000 Model II FM | 1.05 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0396 | XTL-5000 Mobile | 21.86 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0604 | XTL-5000 Mobile | 61.10 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2836 | XTL-5000 Mobile | 502.08 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFM2835 | XTL-5000 Mobile | 18.96 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0390 | XTL-5000 Mobile | 0.68 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0391 | XTL-5000 Mobile | 11.01 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0395 | XTL-5000 Mobile | 8.50 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0399 | XTL-5000 Mobile | 0.71 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0400 | XTL-5000 Mobile | 53.46 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0603 | XTL-5000 Mobile | 31.19 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0606 | XTL-5000 Mobile | 14.01 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFX1006 | XTL-5000 Mobile | 0.69 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CGM1782 | XTL-5000 Dual Control | 56.30 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CFR0403 | XTL-5000 Mobile | 37.32 |
| Menomonee Falls | Menomonee Falls Fire Department | Motorola | M20URS9PW1AN | 500CLD0202 | XTL-5000 Mobile | 33.36 |
| | Menomonee Falls Fire Department Total | | | | | 946.31 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2504 | XTS-2500 Model II | 12.76 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2509 | XTS-2500 Model II | 4.88 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2508 | XTS-2500 Model II | 20.08 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2502 | XTS-2500 Model II | 1.69 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2507 | XTS-2500 Model II | 4.35 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2501 | XTS-2500 Model II | 14.28 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2505 | XTS-2500 Model II | 12.74 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2531 | XTS-2500 Model II | 1.07 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2522 | XTS-2500 Model II | 8.86 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2523 | XTS-2500 Model II | 2.76 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2524 | XTS-2500 Model II | 15.11 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2525 | XTS-2500 Model II | 8.09 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|-----------------------------------|----------|--------------|------------|-------------------|-------|
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2526 | XTS-2500 Model II | 2.60 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2527 | XTS-2500 Model II | 59.87 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2528 | XTS-2500 Model II | 6.35 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2541 | XTS-2500 Model II | 16.40 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2530 | XTS-2500 Model II | 10.24 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2518 | XTS-2500 Model II | 11.34 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2532 | XTS-2500 Model II | 23.89 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2533 | XTS-2500 Model II | 8.80 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2534 | XTS-2500 Model II | 0.08 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2535 | XTS-2500 Model II | 47.01 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2536 | XTS-2500 Model II | 5.91 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2537 | XTS-2500 Model II | 0.78 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2538 | XTS-2500 Model II | 4.37 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2539 | XTS-2500 Model II | 12.64 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2529 | XTS-2500 Model II | 10.64 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2510 | XTS-2500 Model II | 16.41 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2484 | XTS-2500 Model II | 3.32 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2485 | XTS-2500 Model II | 14.29 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2486 | XTS-2500 Model II | 0.51 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2487 | XTS-2500 Model II | 10.81 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2488 | XTS-2500 Model II | 4.77 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2489 | XTS-2500 Model II | 11.59 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2491 | XTS-2500 Model II | 12.64 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2500 | XTS-2500 Model II | 22.20 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2521 | XTS-2500 Model II | 1.09 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2494 | XTS-2500 Model II | 4.96 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2520 | XTS-2500 Model II | 0.95 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2511 | XTS-2500 Model II | 16.77 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2512 | XTS-2500 Model II | 19.36 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2513 | XTS-2500 Model II | 5.56 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2514 | XTS-2500 Model II | 7.99 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2515 | XTS-2500 Model II | 2.31 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2516 | XTS-2500 Model II | 17.77 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2517 | XTS-2500 Model II | 4.38 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2492 | XTS-2500 Model II | 19.37 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|-----------------------------------|----------|--------------|------------|--------------------|--------|
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2493 | XTS-2500 Model II | 13.83 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2496 | XTS-2500 Model II | 14.78 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2543 | XTS-2500 Model II | 9.48 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2544 | XTS-2500 Model II | 16.73 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2545 | XTS-2500 Model II | 16.83 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2495 | XTS-2500 Model II | 4.45 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2497 | XTS-2500 Model II | 8.85 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2498 | XTS-2500 Model II | 15.59 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2499 | XTS-2500 Model II | 6.12 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2542 | XTS-2500 Model II | 13.15 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H46UCF9PW6BN | 205CKH2490 | XTS-2500 Model II | 6.54 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | H98UCF9PW6AN | 481CPMD324 | APX-6000 Model 2.5 | 0.36 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M20URS9PW1AN | 500CHR0358 | XTL-5000 Mobile | 0.57 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0365 | XTL-2500 Mobile | 1.05 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2749 | XTL-2500 Mobile | 20.08 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH1521 | XTL-2500 Mobile | 0.38 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2762 | XTL-2500 Mobile | 142.41 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2761 | XTL-2500 Mobile | 4.93 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0360 | XTL-2500 Mobile | 10.23 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0361 | XTL-2500 Mobile | 1.31 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0362 | XTL-2500 Mobile | 7.13 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0363 | XTL-2500 Mobile | 16.23 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0364 | XTL-2500 Mobile | 14.77 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2750 | XTL-2500 Mobile | 288.02 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2752 | XTL-2500 Mobile | 145.01 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0367 | XTL-2500 Mobile | 106.13 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH1524 | XTL-2500 Mobile | 0.16 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2758 | XTL-2500 Mobile | 62.99 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0366 | XTL-2500 Mobile | 2.84 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0370 | XTL-2500 Mobile | 1.74 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2760 | XTL-2500 Mobile | 0.17 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2757 | XTL-2500 Mobile | 295.12 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2759 | XTL-2500 Mobile | 260.34 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CMB0413 | XTL-2500 Mobile | 11.26 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2754 | XTL-2500 Mobile | 235.73 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------------------|--|----------|--------------|------------|----------------------|-----------------|
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2755 | XTL-2500 Mobile | 221.32 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2756 | XTL-2500 Mobile | 202.96 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH2753 | XTL-2500 Mobile | 56.41 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0368 | XTL-2500 Mobile | 145.03 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH0369 | XTL-2500 Mobile | 0.54 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH1527 | XTL-2500 Mobile | 0.68 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH1529 | XTL-2500 Mobile | 11.03 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CKH1530 | XTL-2500 Mobile | 2,307.58 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW1AN | 514CLF2244 | XTL-2500 Mobile | 36.64 |
| Menomonee Falls | Menomonee Falls Police Department | Motorola | M21URM9PW2AN | 624CJK1052 | XTL-2500RB | 0.25 |
| | Menomonee Falls Police Department Total | | | | | 5,262.39 |
| Menomonee Falls Total | | | | | | 6,208.70 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5489 | XTS-2500 Model II FM | 0.20 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5497 | XTS-2500 Model II FM | 1.09 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5492 | XTS-2500 Model II FM | 0.05 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5500 | XTS-2500 Model II FM | 0.67 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5488 | XTS-2500 Model II FM | 0.29 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5486 | XTS-2500 Model II FM | 0.44 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5484 | XTS-2500 Model II FM | 0.71 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5483 | XTS-2500 Model II FM | 2.79 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5481 | XTS-2500 Model II FM | 0.70 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5477 | XTS-2500 Model II FM | 1.90 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5476 | XTS-2500 Model II FM | 0.10 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5475 | XTS-2500 Model II FM | 3.38 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5474 | XTS-2500 Model II FM | 0.13 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5471 | XTS-2500 Model II FM | 6.13 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5482 | XTS-2500 Model II FM | 0.29 |
| Merton Fire Department | Merton Fire Department | Motorola | H46UCF9PW6BN | 205CJF5496 | XTS-2500 Model II FM | 0.27 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0830 | XTL-2500RB | 0.45 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0835 | XTL-2500RB | 6.14 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0836 | XTL-2500RB | 3.48 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0839 | XTL-2500RB | 0.44 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0831 | XTL-2500RB | 5.51 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0834 | XTL-2500RB | 0.53 |
| Merton Fire Department | Merton Fire Department | Motorola | M21URM9PW2AN | 624CJK0833 | XTL-2500RB | 1.26 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------------|--|----------|--------------|------------|-----------------------|--------------|
| | Merton Fire Department Total | | | | | 36.95 |
| Merton Fire Department Total | | | | | | 36.95 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0963 | XTL-2500RB | 0.28 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0961 | XTL-2500RB | 0.12 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0959 | XTL-2500RB | 0.56 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0958 | XTL-2500RB | 0.15 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0957 | XTL-2500RB | 0.25 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0965 | XTL-2500RB | 0.88 |
| Merton, Town | Merton Town Highway Department | Motorola | M21URM9PW2AN | 624CJP0966 | XTL-2500RB | 0.29 |
| | Merton Town Highway Department Total | | | | | 2.53 |
| Merton, Town Total | | | | | | 2.53 |
| Milwaukee County | Milwaukee County Emergency Medical Services | Motorola | H97TGD9PW1AN | 655CNZ3828 | APX-7000 Model 3.5 | 0.05 |
| | Milwaukee County Emergency Medical Services Total | | | | | 0.05 |
| Milwaukee County | Milwaukee County Sheriff Department | Motorola | L20URS9PW1AN | 276CKZ0294 | XTL-5000 Control Base | 0.17 |
| | Milwaukee County Sheriff Department Total | | | | | 0.17 |
| Milwaukee County Total | | | | | | 0.22 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H01UCF6PW1BN | 466ABW4606 | MTS-2000 Model II | 2.91 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H01UCF6PW1BN | 466AAN2275 | MTS-2000 Model II | 1.98 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H01UCF6PW1BN | 466AAE4534 | MTS-2000 Model II | 1.01 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4308 | XTS-2500 Model II FM | 1.01 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4287 | XTS-2500 Model II FM | 6.67 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4285 | XTS-2500 Model II FM | 14.09 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4276 | XTS-2500 Model II FM | 0.09 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4283 | XTS-2500 Model II FM | 1.02 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4284 | XTS-2500 Model II FM | 0.56 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4270 | XTS-2500 Model II FM | 4.95 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4272 | XTS-2500 Model II FM | 1.42 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4280 | XTS-2500 Model II FM | 12.46 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4296 | XTS-2500 Model II FM | 4.38 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4282 | XTS-2500 Model II FM | 13.10 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4279 | XTS-2500 Model II FM | 1.03 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4305 | XTS-2500 Model II FM | 0.22 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4307 | XTS-2500 Model II FM | 1.16 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4286 | XTS-2500 Model II FM | 0.11 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4292 | XTS-2500 Model II FM | 0.74 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--|--|----------|--------------|------------|----------------------|---------------|
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4267 | XTS-2500 Model II FM | 0.75 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4291 | XTS-2500 Model II FM | 1.51 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4290 | XTS-2500 Model II FM | 4.70 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4288 | XTS-2500 Model II FM | 0.30 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4271 | XTS-2500 Model II FM | 10.90 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4281 | XTS-2500 Model II FM | 6.24 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4298 | XTS-2500 Model II FM | 1.01 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4299 | XTS-2500 Model II FM | 5.76 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4274 | XTS-2500 Model II FM | 1.41 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4309 | XTS-2500 Model II FM | 13.50 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4273 | XTS-2500 Model II FM | 2.09 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | H46UCF9PW6AN | 205CFZ4269 | XTS-2500 Model II FM | 6.87 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M20URS9PW1AN | 500CGF1129 | XTL-5000 Mobile | 57.03 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M20URS9PW1AN | 500CGF1127 | XTL-5000 Mobile | 10.95 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0486 | XTL-2500 Mobile | 298.08 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0488 | XTL-2500 Mobile | 1.55 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0487 | XTL-2500 Mobile | 13.40 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0490 | XTL-2500 Mobile | 12.51 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0491 | XTL-2500 Mobile | 7.44 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0485 | XTL-2500 Mobile | 27.32 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0494 | XTL-2500 Mobile | 8.17 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0493 | XTL-2500 Mobile | 0.46 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0483 | XTL-2500 Mobile | 4.64 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0498 | XTL-2500 Mobile | 5.75 |
| Mukwonago Fire Department | Mukwonago Fire Department | Motorola | M21URM9PW1AN | 514CGF0496 | XTL-2500 Mobile | 26.84 |
| | Mukwonago Fire Department Total | | | | | 598.09 |
| Mukwonago Fire Department Total | | | | | | 598.09 |
| Mukwonago, Town | Mukwonago Town Police Department | Motorola | M30URS9PW1AN | 656CLV0275 | APX-7500 Mobile | 0.23 |
| | Mukwonago Town Police Department Total | | | | | 0.23 |
| Mukwonago, Town Total | | | | | | 0.23 |
| Mukwonago, Village | Mukwonago Village Police Department | Motorola | M01UJN6PW6BN | 722ABQ1536 | MCS-2000 Model III | 0.24 |
| Mukwonago, Village | Mukwonago Village Police Department | Motorola | M21URM9PW2AN | 624CJK1053 | XTL-2500RB | 0.11 |
| Mukwonago, Village | Mukwonago Village Police Department | Motorola | M30URS9PW1AN | 656CLV0268 | APX-7500 Mobile | 0.27 |
| | Mukwonago Village Police Department Total | | | | | 0.62 |
| Mukwonago, Village Total | | | | | | 0.62 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------|--------------------------------------|----------|--------------|------------|----------------------|-------------|
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0946 | MTS-2000 Model I | 0.12 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1772 | MTS-2000 Model I FM | 0.11 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1796 | MTS-2000 Model I FM | 0.05 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466CDE1787 | MTS-2000 Model I FM | 0.10 |
| Muskego | Muskego Fire Department | Motorola | H01UCD6PW1BN | 466ABQ0928 | MTS-2000 Model I | 0.10 |
| Muskego | Muskego Fire Department | Motorola | H46UCF9PW6AN | 205CHZ7128 | XTS-2500 Model II FM | 0.05 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6AN | 722ABE1325 | MCS-2000 Model II | 0.09 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6AN | 722ABE1346 | MCS-2000 Model II | 0.75 |
| Muskego | Muskego Fire Department | Motorola | M01UGM6PW6AN | 722ABE1365 | MCS-2000 Model II | 0.04 |
| | Muskego Fire Department Total | | | | | 1.41 |
| Muskego | Muskego Park Department | Motorola | H46UCF9PW6BN | 205CJF0533 | XTS-2500 Model II FM | 0.20 |
| Muskego | Muskego Park Department | Motorola | M21URM9PW2AN | 624CJX0301 | XTL-2500RB | 0.19 |
| Muskego | Muskego Park Department | Motorola | M21URM9PW2AN | 624CJX0303 | XTL-2500RB | 2.45 |
| | Muskego Park Department Total | | | | | 2.84 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4829 | MTS-2000 Model I | 11.58 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4819 | MTS-2000 Model I | 0.19 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4985 | MTS-2000 Model I | 5.16 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4907 | MTS-2000 Model I | 0.15 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4900 | MTS-2000 Model I | 1.13 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4837 | MTS-2000 Model I | 0.19 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4882 | MTS-2000 Model I | 6.08 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466CCU0101 | MTS-2000 Model I | 20.25 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4883 | MTS-2000 Model I | 10.21 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4851 | MTS-2000 Model I | 0.59 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4867 | MTS-2000 Model I | 3.22 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4873 | MTS-2000 Model I | 1.60 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4938 | MTS-2000 Model I | 13.89 |
| Muskego | Muskego Police Department | Motorola | H01UCD6PW1BN | 466ABE4890 | MTS-2000 Model I | 1.29 |
| Muskego | Muskego Police Department | Motorola | H18UCF9PW6AN | 721CEG0210 | XTS-5000 Model II | 0.16 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1966 | APX-6000 Model 2.5 | 12.16 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1990 | APX-6000 Model 2.5 | 0.07 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1995 | APX-6000 Model 2.5 | 13.20 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1997 | APX-6000 Model 2.5 | 14.35 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1998 | APX-6000 Model 2.5 | 5.29 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1999 | APX-6000 Model 2.5 | 27.61 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------|---------------------------|----------|--------------|------------|--------------------|--------|
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP2000 | APX-6000 Model 2.5 | 19.93 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1986 | APX-6000 Model 2.5 | 26.50 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP2711 | APX-6000 Model 2.5 | 3.41 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1989 | APX-6000 Model 2.5 | 30.26 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1967 | APX-6000 Model 2.5 | 4.61 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1968 | APX-6000 Model 2.5 | 35.12 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP2002 | APX-6000 Model 2.5 | 25.12 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1969 | APX-6000 Model 2.5 | 26.23 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1982 | APX-6000 Model 2.5 | 20.29 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1981 | APX-6000 Model 2.5 | 6.35 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1979 | APX-6000 Model 2.5 | 20.87 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1972 | APX-6000 Model 2.5 | 50.91 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1973 | APX-6000 Model 2.5 | 5.34 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1974 | APX-6000 Model 2.5 | 25.25 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1977 | APX-6000 Model 2.5 | 8.88 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1976 | APX-6000 Model 2.5 | 13.61 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1975 | APX-6000 Model 2.5 | 2.69 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1985 | APX-6000 Model 2.5 | 3.66 |
| Muskego | Muskego Police Department | Motorola | H98UCF9PW6AN | 481CQP1994 | APX-6000 Model 2.5 | 20.13 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0524 | MCS-2000 Model I | 0.24 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0529 | MCS-2000 Model I | 0.15 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0523 | MCS-2000 Model I | 0.10 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0521 | MCS-2000 Model I | 0.12 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0525 | MCS-2000 Model I | 0.23 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0520 | MCS-2000 Model I | 0.12 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0522 | MCS-2000 Model I | 0.10 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABJ0510 | MCS-2000 Model I | 2.90 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0519 | MCS-2000 Model I | 0.22 |
| Muskego | Muskego Police Department | Motorola | M01UGL6PW4BN | 722ABG0527 | MCS-2000 Model I | 0.11 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1411 | MCS-2000 Model II | 1.46 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1361 | MCS-2000 Model II | 65.00 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1344 | MCS-2000 Model II | 2.00 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1354 | MCS-2000 Model II | 9.56 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1368 | MCS-2000 Model II | 119.47 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1366 | MCS-2000 Model II | 4.90 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------|--|----------|--------------|------------|----------------------|-----------------|
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1360 | MCS-2000 Model II | 0.06 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1356 | MCS-2000 Model II | 158.78 |
| Muskego | Muskego Police Department | Motorola | M01UGM6PW6BN | 722ABE1362 | MCS-2000 Model II | 9.01 |
| Muskego | Muskego Police Department | Motorola | M21URM9PW2AN | 624CJK1068 | XTL-2500RB | 0.33 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM5185 | APX-6500 Mobile | 91.99 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM5186 | APX-6500 Mobile | 0.22 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM5188 | APX-6500 Mobile | 1,137.62 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM3425 | APX-6500 Mobile | 78.91 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM3427 | APX-6500 Mobile | 198.03 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM3428 | APX-6500 Mobile | 104.23 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM3429 | APX-6500 Mobile | 158.08 |
| Muskego | Muskego Police Department | Motorola | M25URS9PW1AN | 527CQM3421 | APX-6500 Mobile | 283.87 |
| | Muskego Police Department Total | | | | | 2,925.34 |
| Muskego | Muskego Public Works Department | Motorola | H46UCF9PW6BN | 205CJF0523 | XTS-2500 Model II FM | 0.66 |
| Muskego | Muskego Public Works Department | Motorola | H46UCF9PW6BN | 205CJF0525 | XTS-2500 Model II FM | 0.07 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0326 | XTL-2500RB | 0.32 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0325 | XTL-2500RB | 0.33 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0322 | XTL-2500RB | 0.10 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0321 | XTL-2500RB | 0.13 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0320 | XTL-2500RB | 0.44 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0317 | XTL-2500RB | 2.99 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0335 | XTL-2500RB | 0.74 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0329 | XTL-2500RB | 0.46 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0315 | XTL-2500RB | 0.13 |
| Muskego | Muskego Public Works Department | Motorola | M21URM9PW2AN | 624CJX0331 | XTL-2500RB | 0.67 |
| Muskego | Muskego Public Works Department | Motorola | M22URS9PW1AN | 471CQM1978 | APX-4500 Mobile | 0.48 |
| Muskego | Muskego Public Works Department | Motorola | M28URS9PW1AN | 775TGN1718 | XTL-1500 Mobile | 0.07 |
| Muskego | Muskego Public Works Department | Motorola | M28URS9PW1AN | 775TGN1709 | XTL-1500 Mobile | 0.59 |
| | Muskego Public Works Department Total | | | | | 8.18 |
| Muskego | Muskego Utilities | Motorola | M21URM9PW2AN | 624CJX0340 | XTL-2500RB | 0.29 |
| Muskego | Muskego Utilities | Motorola | M21URM9PW2AN | 624CJX0342 | XTL-2500RB | 0.20 |
| Muskego | Muskego Utilities | Motorola | M21URM9PW2AN | 624CJX0338 | XTL-2500RB | 0.05 |
| | Muskego Utilities Total | | | | | 0.54 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABE5033 | MTS-2000 Model I | 0.25 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEE0424 | MTS-2000 Model I | 0.70 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------|------------------------------|----------|--------------|------------|----------------------|-------|
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466AWC2504 | MTS-2000 Model I | 0.05 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3022 | MTS-2000 Model I | 0.80 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3028 | MTS-2000 Model I | 0.39 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CDE1778 | MTS-2000 Model I FM | 0.04 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CDE1797 | MTS-2000 Model I FM | 0.05 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2917 | MTS-2000 Model I | 0.50 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2901 | MTS-2000 Model I | 0.25 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS2911 | MTS-2000 Model I | 0.33 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABS3023 | MTS-2000 Model I | 0.08 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CCU0819 | MTS-2000 Model I | 1.57 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEL0439 | MTS-2000 Model I | 0.21 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466ABE5025 | MTS-2000 Model I | 0.11 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEL0441 | MTS-2000 Model I | 0.54 |
| Muskego | Tess Corners Fire Department | Motorola | H01UCD6PW1BN | 466CEL0442 | MTS-2000 Model I | 0.04 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2025 | XTS-2500 Model II FM | 0.05 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2021 | XTS-2500 Model II FM | 0.17 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2028 | XTS-2500 Model II FM | 1.56 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6AN | 205CFV2023 | XTS-2500 Model II FM | 0.76 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6BN | 205CJR7329 | XTS-2500 Model II FM | 0.29 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6BN | 205CJR7328 | XTS-2500 Model II FM | 0.48 |
| Muskego | Tess Corners Fire Department | Motorola | H46UCF9PW6BN | 205CFV2024 | XTS-2500 Model II FM | 0.85 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CQM2208 | APX-6000XE Model 2.5 | 1.52 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CQP2109 | APX-6000 Model 2.5 | 23.25 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CQM2209 | APX-6000XE Model 2.5 | 0.08 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CQM2207 | APX-6000XE Model 2.5 | 0.25 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CQM2210 | APX-6000XE Model 2.5 | 0.11 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CQP2110 | APX-6000 Model 2.5 | 7.96 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CPX0498 | APX-6000XE Model 2.5 | 0.05 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0259 | APX-6000 Model 2.5 | 3.60 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0257 | APX-6000 Model 2.5 | 1.29 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0260 | APX-6000 Model 2.5 | 2.23 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0261 | APX-6000 Model 2.5 | 0.18 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0262 | APX-6000 Model 2.5 | 0.79 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0264 | APX-6000 Model 2.5 | 4.26 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CPD1233 | APX-6000 Model 2.5 | 0.67 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------|--|--------------|-----------------|-----------------|----------------------|-----------------|
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 481CNR0256 | APX-6000 Model 2.5 | 1.35 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CPX0503 | APX-6000XE Model 2.5 | 0.17 |
| Muskego | Tess Corners Fire Department | Motorola | H98UCF9PW6AN | 756CPX0505 | APX-6000XE Model 2.5 | 1.18 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722AWE0929 | MCS-2000 Model II | 0.04 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722CEE0520 | MCS-2000 Model II | 1.60 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722ABE1421 | MCS-2000 Model II | 1.77 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722ABE1420 | MCS-2000 Model II | 0.22 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722ABE1397 | MCS-2000 Model II | 0.54 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6AN | 722ACG0721 | MCS-2000 Model II | 0.01 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGM6PW6BN | 722ACE1792 | MCS-2000 Model II | 0.30 |
| Muskego | Tess Corners Fire Department | Motorola | M01UGN6PW6BN | 722ABS0340 | MCS-2000 Model III | 0.96 |
| Muskego | Tess Corners Fire Department | Motorola | M01UJM6PW6AN | 722AXA1581 | MCS-2000 Model II | 1.09 |
| Muskego | Tess Corners Fire Department | Motorola | M20URS9PW1AN | 500CJR1818 | XTL-5000 Mobile | 0.87 |
| Muskego | Tess Corners Fire Department | Motorola | M20URS9PW1AN | 500CFV2620 | XTL-5000 Mobile | 1.52 |
| Muskego | Tess Corners Fire Department | Motorola | M25URS9PW1AN | 527CQM2561 | APX-6500 Mobile | 41.45 |
| Muskego | Tess Corners Fire Department | Motorola | M25URS9PW1AN | 527CQM2540 | APX-6500 Mobile | 0.70 |
| Muskego | Tess Corners Fire Department | Motorola | M25URS9PW1AN | 527CQM2576 | APX-6500 Mobile | 0.33 |
| Muskego | Tess Corners Fire Department | Motorola | M25URS9PW1AN | 527CPD1342 | APX-6500 Mobile | 1.52 |
| Muskego | Tess Corners Fire Department | Motorola | M25URS9PW1AN | 527CPD1343 | APX-6500 Mobile | 20.87 |
| Muskego | Tess Corners Fire Department | Motorola | M30TSS9PW1AN | 656CQM1298 | APX-7500 Mobile | 3.07 |
| | Tess Corners Fire Department Total | | | | | 135.87 |
| Muskego Total | | | | | | 3,074.18 |
| Nashotah | Nashotah Fire Department | Motorola | H01UCD6PW1BN | 466ABE1364 | MTS-2000 Model I | 0.34 |
| Nashotah | Nashotah Fire Department | Motorola | M01UGM6PW6BN | 722ABS1450 | MCS-2000 Model II | 0.30 |
| Nashotah | Nashotah Fire Department | Motorola | M21URM9PW2AN | 624CJP0947 | XTL-2500RB | 0.27 |
| | Nashotah Fire Department Total | | | | | 0.91 |
| Nashotah | Nashotah Police Department | Motorola | H01UCD6PW1BN | 466ABS3052 | MTS-2000 Model I | 0.11 |
| Nashotah | Nashotah Police Department | Motorola | H18UCF9PW6AN | 721CJF1295 | XTS-5000 Model II FM | 0.30 |
| Nashotah | Nashotah Police Department | Motorola | H49TGD9PW1AN | 562CQM1367 | APX-7000XE Model 3.5 | 15.38 |
| Nashotah | Nashotah Police Department | Motorola | M30TSS9PW1AN | 656CQM1122 | APX-7500 Mobile | 5.99 |
| | Nashotah Police Department Total | | | | | 21.78 |
| Nashotah Total | | | | | | 22.69 |
| New Berlin | New Berlin Emergency Government | Motorola | M20URS9PW1AN | 500CJH0689 | XTL-5000 Mobile | 0.60 |
| | New Berlin Emergency Government Total | | | | | 0.60 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720261 | VP600 Model 2 | 1.16 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------|----------------------------|--------------|-----------------|-----------------|----------------------|-------|
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001308120435 | VP600 Model 2 | 0.96 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001231220222 | VP600 Model 2 | 0.85 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720759 | VP600 Model 2 | 0.11 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720524 | VP600 Model 2 | 11.53 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720367 | VP600 Model 2 | 0.31 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720332 | VP600 Model 2 | 6.85 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720259 | VP600 Model 2 | 1.27 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720183 | VP600 Model 2 | 5.53 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720180 | VP600 Model 2 | 3.40 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001226120617 | VP600 Model 2 | 8.76 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720346 | VP600 Model 2 | 0.09 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720169 | VP600 Model 2 | 8.01 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001226120732 | VP600 Model 2 | 0.25 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001226120747 | VP600 Model 2 | 14.11 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720149 | VP600 Model 2 | 0.29 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720137 | VP600 Model 2 | 20.07 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720148 | VP600 Model 2 | 1.08 |
| New Berlin | New Berlin Fire Department | E.F. Johnson | 242-577B-753J08 | 517001229720095 | VP600 Model 2 | 1.55 |
| New Berlin | New Berlin Fire Department | Motorola | H46UCF9PW6BN | 205CMD1789 | XTS-2500 Model II FM | 0.28 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0715 | XTL-5000 Mobile | 18.17 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0712 | XTL-5000 Mobile | 11.02 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0707 | XTL-5000 Mobile | 6.93 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0713 | XTL-5000 Mobile | 1.30 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0711 | XTL-5000 Mobile | 1.06 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0716 | XTL-5000 Mobile | 1.32 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0717 | XTL-5000 Mobile | 0.59 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0719 | XTL-5000 Mobile | 32.78 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0720 | XTL-5000 Mobile | 0.70 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0705 | XTL-5000 Mobile | 1.36 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0718 | XTL-5000 Mobile | 0.09 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0691 | XTL-5000 Mobile | 1.87 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0695 | XTL-5000 Mobile | 3.28 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0703 | XTL-5000 Mobile | 8.12 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0768 | XTL-5000 Mobile | 14.05 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0693 | XTL-5000 Mobile | 0.71 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------|--|----------|--------------|------------|----------------------|---------------|
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0696 | XTL-5000 Mobile | 5.27 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0700 | XTL-5000 Mobile | 12.46 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0698 | XTL-5000 Mobile | 0.56 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0699 | XTL-5000 Mobile | 0.76 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0697 | XTL-5000 Mobile | 2.05 |
| New Berlin | New Berlin Fire Department | Motorola | M20URS9PW1AN | 500CJH0702 | XTL-5000 Mobile | 0.50 |
| | New Berlin Fire Department Total | | | | | 211.41 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0745 | XTL-5000 Mobile | 0.15 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0744 | XTL-5000 Mobile | 0.12 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0743 | XTL-5000 Mobile | 1.12 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0723 | XTL-5000 Mobile | 2.58 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0728 | XTL-5000 Mobile | 0.40 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0731 | XTL-5000 Mobile | 0.09 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0722 | XTL-5000 Mobile | 0.08 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0737 | XTL-5000 Mobile | 1.36 |
| New Berlin | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0736 | XTL-5000 Mobile | 0.69 |
| | New Berlin Park and Recreation Department Total | | | | | 6.59 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3480 | XTS-5000 Model II FM | 23.39 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3499 | XTS-5000 Model II FM | 14.30 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3488 | XTS-5000 Model II FM | 12.73 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3497 | XTS-5000 Model II FM | 6.13 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3495 | XTS-5000 Model II FM | 43.72 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3494 | XTS-5000 Model II FM | 1.36 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3491 | XTS-5000 Model II FM | 5.64 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3481 | XTS-5000 Model II FM | 1.96 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3482 | XTS-5000 Model II FM | 25.28 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3483 | XTS-5000 Model II FM | 8.70 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3486 | XTS-5000 Model II FM | 9.86 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3484 | XTS-5000 Model II FM | 35.21 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3485 | XTS-5000 Model II FM | 2.02 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3492 | XTS-5000 Model II FM | 14.26 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3377 | XTS-5000 Model II FM | 0.07 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3467 | XTS-5000 Model II FM | 0.58 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3421 | XTS-5000 Model II FM | 2.09 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3419 | XTS-5000 Model II FM | 9.89 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------|------------------------------|----------|--------------|------------|----------------------|-------|
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3418 | XTS-5000 Model II FM | 0.13 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3417 | XTS-5000 Model II FM | 2.40 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3416 | XTS-5000 Model II FM | 16.57 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3415 | XTS-5000 Model II FM | 10.75 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3413 | XTS-5000 Model II FM | 16.65 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3412 | XTS-5000 Model II FM | 23.39 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3411 | XTS-5000 Model II FM | 20.83 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3410 | XTS-5000 Model II FM | 25.18 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3409 | XTS-5000 Model II FM | 36.00 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3424 | XTS-5000 Model II FM | 33.52 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3379 | XTS-5000 Model II FM | 15.68 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3425 | XTS-5000 Model II FM | 18.40 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3376 | XTS-5000 Model II FM | 1.73 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3375 | XTS-5000 Model II FM | 33.37 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3374 | XTS-5000 Model II FM | 1.21 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3373 | XTS-5000 Model II FM | 11.03 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3372 | XTS-5000 Model II FM | 35.60 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3371 | XTS-5000 Model II FM | 15.33 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0902 | XTS-5000 Model II | 0.10 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0889 | XTS-5000 Model II | 0.26 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0880 | XTS-5000 Model II | 0.06 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0888 | XTS-5000 Model II | 0.48 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0898 | XTS-5000 Model II | 0.36 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CFC0881 | XTS-5000 Model II | 0.82 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3380 | XTS-5000 Model II FM | 18.97 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3521 | XTS-5000 Model II FM | 0.59 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3475 | XTS-5000 Model II FM | 3.32 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3474 | XTS-5000 Model II FM | 1.01 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3473 | XTS-5000 Model II FM | 0.22 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3472 | XTS-5000 Model II FM | 22.85 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3471 | XTS-5000 Model II FM | 18.71 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3470 | XTS-5000 Model II FM | 18.38 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3469 | XTS-5000 Model II FM | 33.35 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3468 | XTS-5000 Model II FM | 0.42 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3466 | XTS-5000 Model II FM | 17.31 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------|------------------------------|----------|--------------|------------|----------------------|--------|
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3489 | XTS-5000 Model II FM | 13.52 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3525 | XTS-5000 Model II FM | 0.06 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3524 | XTS-5000 Model II FM | 18.00 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3423 | XTS-5000 Model II FM | 0.51 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3522 | XTS-5000 Model II FM | 32.12 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3477 | XTS-5000 Model II FM | 10.50 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3518 | XTS-5000 Model II FM | 12.55 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3517 | XTS-5000 Model II FM | 8.45 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3516 | XTS-5000 Model II FM | 18.60 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3514 | XTS-5000 Model II FM | 1.71 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3513 | XTS-5000 Model II FM | 2.98 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3512 | XTS-5000 Model II FM | 23.62 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3511 | XTS-5000 Model II FM | 17.31 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3509 | XTS-5000 Model II FM | 28.72 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3508 | XTS-5000 Model II FM | 8.64 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3507 | XTS-5000 Model II FM | 3.23 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3428 | XTS-5000 Model II FM | 0.06 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3426 | XTS-5000 Model II FM | 1.77 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3523 | XTS-5000 Model II FM | 1.01 |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3487 | XTS-5000 Model II FM | 0.08 |
| New Berlin | New Berlin Police Department | Motorola | M01UGM6PW6BN | 722ABE1310 | MCS-2000 Model II | 10.17 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0780 | XTL-5000 Mobile | 59.17 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0779 | XTL-5000 Mobile | 33.33 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJD1854 | XTL-5000 Mobile | 1.40 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0778 | XTL-5000 Mobile | 0.15 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0781 | XTL-5000 Mobile | 166.30 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0777 | XTL-5000 Mobile | 118.90 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0776 | XTL-5000 Mobile | 7.67 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0782 | XTL-5000 Mobile | 8.64 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0783 | XTL-5000 Mobile | 187.13 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0784 | XTL-5000 Mobile | 190.26 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0786 | XTL-5000 Mobile | 1.04 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0769 | XTL-5000 Mobile | 13.91 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0751 | XTL-5000 Mobile | 7.92 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJD1855 | XTL-5000 Mobile | 0.76 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------|---|----------|--------------|------------|----------------------|-----------------|
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0747 | XTL-5000 Mobile | 77.77 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0748 | XTL-5000 Mobile | 82.19 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0770 | XTL-5000 Mobile | 12.25 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0785 | XTL-5000 Mobile | 2.65 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0750 | XTL-5000 Mobile | 81.85 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0787 | XTL-5000 Mobile | 61.94 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0752 | XTL-5000 Mobile | 95.84 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0772 | XTL-5000 Mobile | 119.17 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0773 | XTL-5000 Mobile | 5.13 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0753 | XTL-5000 Mobile | 81.71 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0754 | XTL-5000 Mobile | 8.24 |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0749 | XTL-5000 Mobile | 131.66 |
| | New Berlin Police Department Total | | | | | 2,442.76 |
| New Berlin | New Berlin Street Department | Motorola | H18UCF9PW6AN | 721CJD3846 | XTS-5000 Model II FM | 0.19 |
| New Berlin | New Berlin Street Department | Motorola | H18UCF9PW6AN | 721CJD3504 | XTS-5000 Model II FM | 1.54 |
| New Berlin | New Berlin Street Department | Motorola | H18UCF9PW6AN | 721CJD3847 | XTS-5000 Model II FM | 2.42 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0761 | XTL-5000 Mobile | 0.41 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0834 | XTL-5000 Mobile | 3.04 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0833 | XTL-5000 Mobile | 4.33 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0832 | XTL-5000 Mobile | 5.50 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0829 | XTL-5000 Mobile | 2.68 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0828 | XTL-5000 Mobile | 2.29 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0826 | XTL-5000 Mobile | 1.75 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0821 | XTL-5000 Mobile | 1.27 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0818 | XTL-5000 Mobile | 7.92 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0755 | XTL-5000 Mobile | 0.45 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0756 | XTL-5000 Mobile | 4.80 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0758 | XTL-5000 Mobile | 0.09 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0764 | XTL-5000 Mobile | 0.52 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0760 | XTL-5000 Mobile | 0.22 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0741 | XTL-5000 Mobile | 0.72 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0817 | XTL-5000 Mobile | 0.28 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0815 | XTL-5000 Mobile | 1.21 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0814 | XTL-5000 Mobile | 0.60 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0763 | XTL-5000 Mobile | 0.18 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------------------|---|----------|--------------|------------|----------------------|-----------------|
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0811 | XTL-5000 Mobile | 1.52 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0810 | XTL-5000 Mobile | 1.50 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0799 | XTL-5000 Mobile | 0.00 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0795 | XTL-5000 Mobile | 0.34 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0794 | XTL-5000 Mobile | 1.13 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0790 | XTL-5000 Mobile | 0.48 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0789 | XTL-5000 Mobile | 0.08 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0759 | XTL-5000 Mobile | 0.08 |
| New Berlin | New Berlin Street Department | Motorola | M20URS9PW1AN | 500CJH0793 | XTL-5000 Mobile | 0.16 |
| | New Berlin Street Department Total | | | | | 47.70 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0836 | XTL-5000 Mobile | 0.12 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0869 | XTL-5000 Mobile | 0.35 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0868 | XTL-5000 Mobile | 0.11 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0865 | XTL-5000 Mobile | 0.27 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0863 | XTL-5000 Mobile | 0.21 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0861 | XTL-5000 Mobile | 0.03 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0856 | XTL-5000 Mobile | 0.88 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0854 | XTL-5000 Mobile | 0.10 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0849 | XTL-5000 Mobile | 0.70 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0844 | XTL-5000 Mobile | 0.20 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0841 | XTL-5000 Mobile | 2.72 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0839 | XTL-5000 Mobile | 0.08 |
| New Berlin | New Berlin Water and Waste Water Utility | Motorola | M20URS9PW1AN | 500CJH0837 | XTL-5000 Mobile | 0.61 |
| | New Berlin Water and Waste Water Utility Total | | | | | 6.38 |
| New Berlin Total | | | | | | 2,715.44 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H46UCF9PW6BN | 205CKD1850 | XTS-2500 Model II | 0.11 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H46UCF9PW6BN | 205CKD1845 | XTS-2500 Model II | 0.05 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H46UCF9PW6BN | 205CKD1847 | XTS-2500 Model II | 0.49 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H98UCF9PW6AN | 756CQM1636 | APX-6000XE Model 2.5 | 0.16 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H98UCF9PW6AN | 756CQM1637 | APX-6000XE Model 2.5 | 1.19 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H98UCF9PW6AN | 756CQM1639 | APX-6000XE Model 2.5 | 2.12 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H98UCF9PW6AN | 756CQM1640 | APX-6000XE Model 2.5 | 5.13 |
| North Lake Fire Department | North Lake Fire Department | Motorola | H98UCF9PW6AN | 756CQM1641 | APX-6000XE Model 2.5 | 2.30 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1302 | MCS-2000 Model II | 0.73 |
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1303 | MCS-2000 Model II | 1.33 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---|--|----------|--------------|------------|-----------------------|--------------|
| North Lake Fire Department | North Lake Fire Department | Motorola | M01UGM6PW6BN | 722ABL1296 | MCS-2000 Model II | 2.66 |
| | North Lake Fire Department Total | | | | | 16.27 |
| North Lake Fire Department Total | | | | | | 16.27 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1750 | XTS-5000 Model III | 3.00 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1733 | XTS-5000 Model III | 1.93 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1745 | XTS-5000 Model III | 0.93 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1731 | XTS-5000 Model III | 0.92 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1726 | XTS-5000 Model III | 0.38 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1725 | XTS-5000 Model III | 0.54 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1737 | XTS-5000 Model III | 1.03 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1739 | XTS-5000 Model III | 0.08 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1748 | XTS-5000 Model III | 0.87 |
| North Prairie | North Prairie Fire Department | Motorola | H18UCH9PW7AN | 721CHF1746 | XTS-5000 Model III | 0.25 |
| North Prairie | North Prairie Fire Department | Motorola | H97TGD9PW1AN | 655CQP3971 | APX-7000 Model 3.5 | 0.48 |
| North Prairie | North Prairie Fire Department | Motorola | M01UGM6PW6AN | 722AXS0640 | MCS-2000 Model II | 1.50 |
| North Prairie | North Prairie Fire Department | Motorola | M20URS9PW1AN | 500CHF1129 | XTL-5000 Mobile | 0.37 |
| North Prairie | North Prairie Fire Department | Motorola | M20URS9PW1AN | 500CHF4346 | XTL-5000 Dual Control | 4.04 |
| North Prairie | North Prairie Fire Department | Motorola | M21URM9PW2AN | 624CJK0813 | XTL-2500RB | 0.08 |
| | North Prairie Fire Department Total | | | | | 16.40 |
| North Prairie | North Prairie Police Department | Motorola | H18UCF9PW6AN | 721CJD4161 | XTS-5000 Model II FM | 1.07 |
| North Prairie | North Prairie Police Department | Motorola | H18UCF9PW6AN | 721CJD4160 | XTS-5000 Model II FM | 5.74 |
| North Prairie | North Prairie Police Department | Motorola | H97TGD9PW1AN | 655CQP3973 | APX-7000 Model 3.5 | 0.23 |
| North Prairie | North Prairie Police Department | Motorola | M01UGM6PW6BN | 722ABS1444 | MCS-2000 Model II | 5.37 |
| North Prairie | North Prairie Police Department | Motorola | M01UGM6PW6BN | 722ABS1446 | MCS-2000 Model II | 17.05 |
| | North Prairie Police Department Total | | | | | 29.46 |
| North Prairie Total | | | | | | 45.86 |
| North Shore | North Shore Fire Department | Motorola | H18UCF9PW6AN | 721CHB0738 | XTS-5000 Model II | 0.05 |
| | North Shore Fire Department Total | | | | | 0.05 |
| North Shore Total | | | | | | 0.05 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4853 | MTS-2000 Model I | 0.59 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4856 | MTS-2000 Model I | 9.83 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4872 | MTS-2000 Model I | 0.43 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4847 | MTS-2000 Model I | 2.28 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4889 | MTS-2000 Model I | 3.30 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | H01UCD6PW1BN | 466ABE4850 | MTS-2000 Model I | 0.06 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------------------|--|----------|--------------|------------|----------------------|--------------|
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AXY0618 | MCS-2000 Model II | 35.03 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M01UJM6PW6AN | 722AYE2613 | MCS-2000 Model II | 39.27 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M21URM9PW2AN | 624CJX0409 | XTL-2500RB | 6.50 |
| Oconomowoc Lake | Oconomowoc Lake Police Department | Motorola | M21URM9PW2AN | 624CJX0408 | XTL-2500RB | 0.30 |
| | Oconomowoc Lake Police Department Total | | | | | 97.59 |
| Oconomowoc Lake Total | | | | | | 97.59 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H46UCF9PW6BN | 205CJF0514 | XTS-2500 Model II FM | 1.24 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | H46UCF9PW6BN | 205CJF0403 | XTS-2500 Model II FM | 3.15 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0359 | XTL-2500RB | 0.81 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0354 | XTL-2500RB | 8.43 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0352 | XTL-2500RB | 2.00 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0351 | XTL-2500RB | 1.12 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0357 | XTL-2500RB | 0.10 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0358 | XTL-2500RB | 0.37 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0356 | XTL-2500RB | 0.69 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0368 | XTL-2500RB | 0.42 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0349 | XTL-2500RB | 0.23 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0361 | XTL-2500RB | 1.77 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M21URM9PW2AN | 624CJX0362 | XTL-2500RB | 0.09 |
| Oconomowoc, City | Oconomowoc City DPW | Motorola | M28URS9PW1AN | 775CJF0432 | XTL-1500 Mobile | 0.11 |
| | Oconomowoc City DPW Total | | | | | 20.53 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2332 | MTS-2000 Model I | 1.02 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2329 | MTS-2000 Model I | 1.16 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0304 | MTS-2000 Model I FM | 1.92 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2333 | MTS-2000 Model I | 0.00 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2323 | MTS-2000 Model I | 0.83 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2320 | MTS-2000 Model I | 1.02 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2318 | MTS-2000 Model I | 3.42 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0303 | MTS-2000 Model I FM | 1.78 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE1368 | MTS-2000 Model I | 0.05 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE2335 | MTS-2000 Model I | 0.59 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0300 | MTS-2000 Model I FM | 0.28 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466ABE5031 | MTS-2000 Model I | 0.30 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H01UCD6PW1BN | 466CFH0298 | MTS-2000 Model I FM | 4.63 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H18UCF9PW6AN | 721CFC0904 | XTS-5000 Model II | 0.19 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|-----------------------|---------------|
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H18UCF9PW6AN | 721CFC0895 | XTS-5000 Model II | 3.16 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H18UCF9PW6AN | 721CFC0897 | XTS-5000 Model II | 17.43 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1977 | XTS-2500 Model II | 4.06 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1978 | XTS-2500 Model II | 5.02 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1983 | XTS-2500 Model II | 6.81 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1972 | XTS-2500 Model II | 24.54 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1973 | XTS-2500 Model II | 3.43 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1974 | XTS-2500 Model II | 6.74 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1982 | XTS-2500 Model II | 13.61 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1980 | XTS-2500 Model II | 0.45 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1979 | XTS-2500 Model II | 20.23 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1975 | XTS-2500 Model II | 5.97 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1984 | XTS-2500 Model II | 2.30 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1976 | XTS-2500 Model II | 1.89 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1981 | XTS-2500 Model II | 0.12 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H46UCF9PW6BN | 205CKF1971 | XTS-2500 Model II | 0.62 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1452 | APX-7000 Model 3.5 | 0.05 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1453 | APX-7000 Model 3.5 | 0.16 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1454 | APX-7000 Model 3.5 | 0.29 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1457 | MCS-2000 Model II | 4.51 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1799 | MCS-2000 Model II | 1.84 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1798 | MCS-2000 Model II | 26.33 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1375 | MCS-2000 Model II | 0.78 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1422 | MCS-2000 Model II | 2.21 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1373 | MCS-2000 Model II | 11.74 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1401 | MCS-2000 Model II | 9.66 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722CFH1797 | MCS-2000 Model II | 11.77 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UGM6PW6BN | 722ABS1436 | MCS-2000 Model II | 22.11 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UJM6PW6AN | 722AYE2223 | MCS-2000 Model II | 79.70 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M01UJM6PW6AN | 722AXY0630 | MCS-2000 Model II | 1.89 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M20URS9PW1AN | 500CJD0832 | XTL-5000 Mobile | 14.98 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M20URS9PW1AN | 500CMF0510 | XTL-5000 Mobile | 7.45 |
| Oconomowoc, City | Oconomowoc City Fire Department | Motorola | M21URM9PW1AN | 514CMF2346 | XTL-2500 Control Base | 0.41 |
| | Oconomowoc City Fire Department Total | | | | | 329.45 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | H46UCF9PW6BN | 205CJF0512 | XTS-2500 Model II FM | 0.91 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|------------------------------------|----------|--------------|------------|-----------------------|-------------|
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0382 | XTL-2500RB | 1.44 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0372 | XTL-2500RB | 0.07 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0373 | XTL-2500RB | 0.62 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0376 | XTL-2500RB | 0.74 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0378 | XTL-2500RB | 0.05 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0379 | XTL-2500RB | 1.34 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0381 | XTL-2500RB | 0.19 |
| Oconomowoc, City | Oconomowoc City Parks | Motorola | M21URM9PW2AN | 624CJX0380 | XTL-2500RB | 1.09 |
| | Oconomowoc City Parks Total | | | | | 6.45 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4918 | MTS-2000 Model I | 13.70 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4919 | MTS-2000 Model I | 66.52 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1365 | MTS-2000 Model I | 9.28 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE5011 | MTS-2000 Model I | 34.94 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE5028 | MTS-2000 Model I | 11.18 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2322 | MTS-2000 Model I | 10.53 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2303 | MTS-2000 Model I | 43.86 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1362 | MTS-2000 Model I | 0.11 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE1373 | MTS-2000 Model I | 30.89 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2298 | MTS-2000 Model I | 22.14 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE2306 | MTS-2000 Model I | 26.55 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H01UCD6PW1BN | 466ABE4929 | MTS-2000 Model I | 6.85 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H18UCF9PW6AN | 721CFC0887 | XTS-5000 Model II | 1.40 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H18UCF9PW6AN | 721CFC0882 | XTS-5000 Model II | 0.38 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H46UCF9PW6BN | 205CLT5891 | XTS-2500 Model II FM | 2.14 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | H46UCF9PW6BN | 205CLT5892 | XTS-2500 Model II FM | 1.03 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1389 | MCS-2000 Model II | 138.71 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M01UGM6PW6BN | 722ABS1360 | MCS-2000 Model II | 0.38 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M20URS9PW1AN | 500CJD0831 | XTL-5000 Mobile | 7.36 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M21URM9PW2AN | 624CJX1056 | XTL-2500RB | 0.35 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775CJF0426 | XTL-1500 Control Base | 7.55 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775CJF0417 | XTL-1500 Control Base | 90.07 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775CJF0424 | XTL-1500 Control Base | 0.23 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775THY3733 | XTL-1500 Control Base | 1.33 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775THY3734 | XTL-1500 Control Base | 2.28 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775THY4034 | XTL-1500 Control Base | 1,044.27 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|------------------|--|----------|--------------|------------|-----------------------|-----------------|
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775THY4033 | XTL-1500 Control Base | 1.79 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M28URS9PW1AN | 775CJF0434 | XTL-1500 Control Base | 129.09 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1464 | APX-7500 Mobile | 167.81 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1457 | APX-7500 Mobile | 0.78 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1458 | APX-7500 Mobile | 134.88 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1459 | APX-7500 Mobile | 99.24 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1460 | APX-7500 Mobile | 156.89 |
| Oconomowoc, City | Oconomowoc City Police Department | Motorola | M30TSS9PW1AN | 656CQM1461 | APX-7500 Mobile | 83.45 |
| | Oconomowoc City Police Department Total | | | | | 2,347.96 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2934 | XTS-2500 Model II | 6.08 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2928 | XTS-2500 Model II | 2.01 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2929 | XTS-2500 Model II | 10.55 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2932 | XTS-2500 Model II | 0.71 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2926 | XTS-2500 Model II | 2.81 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2931 | XTS-2500 Model II | 7.80 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2922 | XTS-2500 Model II | 5.83 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2927 | XTS-2500 Model II | 0.18 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CJF0543 | XTS-2500 Model II FM | 0.63 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2925 | XTS-2500 Model II | 2.56 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CHR2930 | XTS-2500 Model II | 2.58 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CJF0546 | XTS-2500 Model II FM | 0.76 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CJF0545 | XTS-2500 Model II FM | 8.39 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CJF0544 | XTS-2500 Model II FM | 1.83 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | H46UCF9PW6BN | 205CJF0547 | XTS-2500 Model II FM | 0.57 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M01UJM6PW6AN | 722AXY0626 | MCS-2000 Model II | 1.00 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M01UJM6PW6AN | 722AYE2565 | MCS-2000 Model II | 1.79 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0394 | XTL-2500RB | 0.56 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0395 | XTL-2500RB | 4.36 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0397 | XTL-2500RB | 0.08 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0398 | XTL-2500RB | 1.08 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0392 | XTL-2500RB | 0.64 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0401 | XTL-2500RB | 0.33 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0391 | XTL-2500RB | 1.55 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0402 | XTL-2500RB | 0.47 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0400 | XTL-2500RB | 0.49 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|--|--------------|----------------|-----------------|----------------------|-----------------|
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0389 | XTL-2500RB | 0.65 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0388 | XTL-2500RB | 0.48 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0387 | XTL-2500RB | 0.14 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0386 | XTL-2500RB | 0.86 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0385 | XTL-2500RB | 0.04 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0384 | XTL-2500RB | 2.68 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJP0383 | XTL-2500RB | 0.17 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0390 | XTL-2500RB | 2.73 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M21URM9PW2AN | 624CJX0393 | XTL-2500RB | 5.15 |
| Oconomowoc, City | Oconomowoc City Utilities | Motorola | M28URS9PW1AN | 775TGA1715 | XTL-1500 Mobile | 1.24 |
| | Oconomowoc City Utilities Total | | | | | 79.78 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | H46UCF9PW6BN | 205CJF0410 | XTS-2500 Model II FM | 0.71 |
| Oconomowoc, City | Oconomowoc City Wastewater | Motorola | M21URM9PW2AN | 624CJX0405 | XTL-2500RB | 0.26 |
| | Oconomowoc City Wastewater Total | | | | | 0.97 |
| Oconomowoc, City Total | | | | | | 2,785.14 |
| Oconomowoc, Town | Oconomowoc Town Police Department | E.F. Johnson | 242-577B-953I8 | 517001229720507 | VP600 Model 2 | 8.37 |
| Oconomowoc, Town | Oconomowoc Town Police Department | E.F. Johnson | 242-577B-953I8 | 517001226120700 | VP600 Model 2 | 0.08 |
| Oconomowoc, Town | Oconomowoc Town Police Department | E.F. Johnson | 242-577B-953I8 | 517001226120566 | VP600 Model 2 | 5.09 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2993 | MTS-2000 Model I | 0.15 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2982 | MTS-2000 Model I | 14.43 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2981 | MTS-2000 Model I | 10.28 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H01UCD6PW1BN | 466ABS2895 | MTS-2000 Model I | 6.42 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H97TGD9PW1AN | 655CQM1796 | APX-7000 Model 3.5 | 0.76 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H97TGD9PW1AN | 655CQM1795 | APX-7000 Model 3.5 | 13.26 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H97TGD9PW1AN | 655CQM1794 | APX-7000 Model 3.5 | 28.45 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H97TGD9PW1AN | 655CQM1793 | APX-7000 Model 3.5 | 0.31 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | H97TGD9PW1AN | 655CQM1788 | APX-7000 Model 3.5 | 13.46 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1394 | MCS-2000 Model II | 35.88 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M01UGM6PW6BN | 722ABS1393 | MCS-2000 Model II | 40.44 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M21URM9PW2AN | 624CJP0444 | XTL-2500RB | 3.97 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M25URS9PW1AN | 527CQM3647 | APX-6500 Mobile | 70.18 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M25URS9PW1AN | 527CQM3648 | APX-6500 Mobile | 82.67 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M25URS9PW1AN | 527CQM3649 | APX-6500 Mobile | 5.77 |
| Oconomowoc, Town | Oconomowoc Town Police Department | Motorola | M25URS9PW1AN | 527CQM3652 | APX-6500 Mobile | 2.84 |
| | Oconomowoc Town Police Department Total | | | | | 342.81 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|---|----------|--------------|------------|----------------------|---------------|
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0453 | XTL-2500RB | 1.65 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0454 | XTL-2500RB | 1.58 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0452 | XTL-2500RB | 1.16 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0451 | XTL-2500RB | 0.85 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0449 | XTL-2500RB | 0.73 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0448 | XTL-2500RB | 3.02 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0447 | XTL-2500RB | 2.65 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M21URM9PW2AN | 624CJP0445 | XTL-2500RB | 0.95 |
| Oconomowoc, Town | Oconomowoc Town Public Works | Motorola | M28URS9PW1AN | 775TGA2016 | XTL-1500 Mobile | 3.05 |
| | Oconomowoc Town Public Works Total | | | | | 15.64 |
| Oconomowoc, Town Total | | | | | | 358.45 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3001 | MTS-2000 Model I | 0.34 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3032 | MTS-2000 Model I | 0.12 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3030 | MTS-2000 Model I | 0.50 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3044 | MTS-2000 Model I | 0.28 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCD6PW1BN | 466ABS3000 | MTS-2000 Model I | 3.64 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H01UCH6PW1BN | 466abc0151 | MTS-2000 Model III | 6.53 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6115 | XTS-5000 Model II FM | 0.15 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6101 | XTS-5000 Model II FM | 0.21 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6110 | XTS-5000 Model II FM | 0.25 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6103 | XTS-5000 Model II FM | 3.82 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6104 | XTS-5000 Model II FM | 0.28 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H18UCF9PW6AN | 721CJF6117 | XTS-5000 Model II FM | 0.09 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CHT3039 | XTS-2500 Model II FM | 1.12 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CHB0343 | XTS-2500 Model II FM | 6.04 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CKH4106 | XTS-2500 Model II | 1.12 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CKH4107 | XTS-2500 Model II | 3.65 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CKV7559 | XTS-2500 Model II FM | 0.05 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CPF2240 | XTS-2500 Model II FM | 0.05 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CNZ2078 | XTS-2500 Model II FM | 5.35 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CMV1460 | XTS-2500 Model II FM | 0.05 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | H46UCF9PW6BN | 205CPF2239 | XTS-2500 Model II FM | 0.23 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UGM6PW6BN | 722ABE1333 | MCS-2000 Model II | 6.32 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0637 | MCS-2000 Model II | 0.47 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0634 | MCS-2000 Model II | 0.46 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------------------------------------|---------------------------------------|--------------|-----------------|-----------------|----------------------|--------------|
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0633 | MCS-2000 Model II | 1.00 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M01UJM6PW6AN | 722AXY0636 | MCS-2000 Model II | 0.13 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M30TSS9PW1AN | 656CRH0524 | APX-7500 Mobile | 1.24 |
| Okauchee Fire Department | Okauchee Fire Department | Motorola | M30TSS9PW1AN | 656CRH0522 | APX-7500 Mobile | 1.31 |
| | Okauchee Fire Department Total | | | | | 44.80 |
| Okauchee Fire Department Total | | | | | | 44.80 |
| Pewaukee Fire Department | Pewaukee Fire Department | E.F. Johnson | 242-577B-753J08 | 517001226120620 | VP600 Model 2 | 4.41 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H18UCF9PW6AN | 721CFC0894 | XTS-5000 Model II | 0.19 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0637 | APX-7000XE Model 3.5 | 0.15 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0638 | APX-7000XE Model 3.5 | 1.74 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0639 | APX-7000XE Model 3.5 | 8.02 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0640 | APX-7000XE Model 3.5 | 0.84 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0641 | APX-7000XE Model 3.5 | 5.17 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0645 | APX-7000XE Model 3.5 | 2.98 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0643 | APX-7000XE Model 3.5 | 18.31 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0644 | APX-7000XE Model 3.5 | 4.29 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H49TGD9PW1AN | 562CQP0642 | APX-7000XE Model 3.5 | 4.06 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2764 | APX-6000XE Model 2.5 | 4.14 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2765 | APX-6000XE Model 2.5 | 2.30 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2754 | APX-6000XE Model 2.5 | 11.42 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2762 | APX-6000XE Model 2.5 | 3.31 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2761 | APX-6000XE Model 2.5 | 8.66 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2760 | APX-6000XE Model 2.5 | 0.62 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2759 | APX-6000XE Model 2.5 | 2.45 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2758 | APX-6000XE Model 2.5 | 4.83 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2757 | APX-6000XE Model 2.5 | 2.55 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2756 | APX-6000XE Model 2.5 | 7.79 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2763 | APX-6000XE Model 2.5 | 1.67 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | H98UCF9PW6AN | 756CQP2755 | APX-6000XE Model 2.5 | 5.57 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0464 | XTL-2500RB | 0.36 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0459 | XTL-2500RB | 15.00 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0457 | XTL-2500RB | 1.68 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJK1058 | XTL-2500RB | 1.66 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP1023 | XTL-2500RB | 1.93 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP1020 | XTL-2500RB | 4.69 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------------------------------------|---|----------|--------------|------------|----------------------|---------------|
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0467 | XTL-2500RB | 2.39 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP1022 | XTL-2500RB | 1.82 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0465 | XTL-2500RB | 0.11 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0468 | XTL-2500RB | 3.43 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0470 | XTL-2500RB | 14.27 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0473 | XTL-2500RB | 0.93 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0927 | XTL-2500RB | 1.87 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M21URM9PW2AN | 624CJP0928 | XTL-2500RB | 20.03 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M30TSS9PW1AN | 656CQT2017 | APX-7500 Mobile | 1.89 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M30TSS9PW1AN | 656CQT2018 | APX-7500 Mobile | 2.88 |
| Pewaukee Fire Department | Pewaukee Fire Department | Motorola | M30TSS9PW1AN | 656CRD0298 | APX-7500 Mobile | 0.90 |
| | Pewaukee Fire Department Total | | | | | 181.31 |
| Pewaukee Fire Department Total | | | | | | 181.31 |
| Pewaukee, City | Pewaukee City Parks Department | Motorola | M21URM9PW2AN | 624CJK1047 | XTL-2500RB | 0.05 |
| | Pewaukee City Parks Department Total | | | | | 0.05 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | H46UCF9PW6BN | 205CJF0404 | XTS-2500 Model II FM | 0.28 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0413 | XTL-2500RB | 0.09 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0417 | XTL-2500RB | 0.75 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0423 | XTL-2500RB | 0.23 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0425 | XTL-2500RB | 0.22 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0427 | XTL-2500RB | 0.23 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0428 | XTL-2500RB | 0.18 |
| Pewaukee, City | Pewaukee City Public Works Department | Motorola | M21URM9PW2AN | 624CJX0412 | XTL-2500RB | 1.14 |
| | Pewaukee City Public Works Department Total | | | | | 3.12 |
| Pewaukee, City | Pewaukee City Sewer and Water Department | Motorola | H46UCF9PW6BN | 205CJF0406 | XTS-2500 Model II FM | 0.45 |
| | Pewaukee City Sewer and Water Department Total | | | | | 0.45 |
| Pewaukee, City Total | | | | | | 3.62 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1223 | APX-7000 Model 3.5 | 16.69 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1214 | APX-7000 Model 3.5 | 3.47 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1228 | APX-7000 Model 3.5 | 8.44 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1216 | APX-7000 Model 3.5 | 11.63 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1226 | APX-7000 Model 3.5 | 7.45 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1225 | APX-7000 Model 3.5 | 7.28 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1217 | APX-7000 Model 3.5 | 26.46 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1212 | APX-7000 Model 3.5 | 7.82 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--------------------------------|--|----------|--------------|------------|----------------------|---------------|
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1224 | APX-7000 Model 3.5 | 8.78 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1227 | APX-7000 Model 3.5 | 2.36 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1222 | APX-7000 Model 3.5 | 15.48 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1221 | APX-7000 Model 3.5 | 13.80 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1220 | APX-7000 Model 3.5 | 26.05 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1219 | APX-7000 Model 3.5 | 19.96 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1218 | APX-7000 Model 3.5 | 4.10 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1211 | APX-7000 Model 3.5 | 16.89 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | H97TGD9PW1AN | 655CQM1213 | APX-7000 Model 3.5 | 5.49 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1411 | MCS-2000 Model II | 16.98 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1383 | MCS-2000 Model II | 10.46 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M01UGM6PW6BN | 722ABS1397 | MCS-2000 Model II | 160.64 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1265 | APX-7500 Mobile | 75.57 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1257 | APX-7500 Mobile | 78.44 |
| Pewaukee, Village | Pewaukee Village Police Department | Motorola | M30TSS9PW1AN | 656CQM1258 | APX-7500 Mobile | 27.48 |
| | Pewaukee Village Police Department Total | | | | | 571.72 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | H46UCF9PW6BN | 205CJF0501 | XTS-2500 Model II FM | 0.14 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0220 | XTL-2500RB | 1.23 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0214 | XTL-2500RB | 0.17 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0210 | XTL-2500RB | 1.66 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0211 | XTL-2500RB | 0.57 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJP1014 | XTL-2500RB | 7.85 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0205 | XTL-2500RB | 2.28 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0207 | XTL-2500RB | 0.27 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0208 | XTL-2500RB | 1.80 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0209 | XTL-2500RB | 0.45 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0213 | XTL-2500RB | 0.26 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0227 | XTL-2500RB | 3.77 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0221 | XTL-2500RB | 0.20 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0212 | XTL-2500RB | 2.67 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0229 | XTL-2500RB | 0.96 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0228 | XTL-2500RB | 0.65 |
| Pewaukee, Village | Pewaukee Village Public Works Departments | Motorola | M21URM9PW2AN | 624CJX0223 | XTL-2500RB | 1.31 |
| | Pewaukee Village Public Works Departments Total | | | | | 26.24 |
| Pewaukee, Village Total | | | | | | 597.96 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------------|--|--------------|-----------------|-----------------|-----------------------|--------------|
| ProHealth Care | Mukwonago Clinic Emergency Department | E.F. Johnson | 242567G20VBBL28 | 587011502230048 | VM600 Mobile | 0.15 |
| | Mukwonago Clinic Emergency Department Total | | | | | 0.15 |
| ProHealth Care | Oconomowoc Memorial Hospital | Motorola | H46UCF9PW6BN | 205CJB4046 | XTS-2500 Model II | 0.11 |
| ProHealth Care | Oconomowoc Memorial Hospital | Motorola | M25URS9PW1AN | 527CQK2064 | APX-6500 Mobile | 7.43 |
| | Oconomowoc Memorial Hospital Total | | | | | 7.54 |
| ProHealth Care | Waukesha Memorial Hospital | Motorola | H46UCF9PW6BN | 205CJB4044 | XTS-2500 Model II | 1.03 |
| ProHealth Care | Waukesha Memorial Hospital | Motorola | M25URS9PW1AN | 527CNR0336 | APX-6500 Mobile | 3.46 |
| | Waukesha Memorial Hospital Total | | | | | 4.49 |
| ProHealth Care Total | | | | | | 12.18 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0654 | XTS-2500 Model II FM | 1.16 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0656 | XTS-2500 Model II FM | 0.55 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0649 | XTS-2500 Model II FM | 0.38 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0657 | XTS-2500 Model II FM | 1.58 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0655 | XTS-2500 Model II FM | 1.57 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0639 | XTS-2500 Model II FM | 2.38 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0659 | XTS-2500 Model II FM | 0.21 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0648 | XTS-2500 Model II FM | 0.38 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0636 | XTS-2500 Model II FM | 2.63 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0637 | XTS-2500 Model II FM | 3.64 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0638 | XTS-2500 Model II FM | 1.22 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0650 | XTS-2500 Model II FM | 0.25 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0645 | XTS-2500 Model II FM | 1.90 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0653 | XTS-2500 Model II FM | 0.11 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0640 | XTS-2500 Model II FM | 3.84 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0642 | XTS-2500 Model II FM | 1.27 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0644 | XTS-2500 Model II FM | 0.29 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCF9PW6BN | 205CJF0652 | XTS-2500 Model II FM | 0.42 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCH9PW7AN | 205CFP1186 | XTS-2500 Model III FM | 10.49 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H46UCH9PW7AN | 205CFP1185 | XTS-2500 Model III FM | 18.92 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H97TGD9PW1AN | 655CNK0820 | APX-7000 Model 3.5 | 0.99 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H97TGD9PW1AN | 655CNV2145 | APX-7000 Model 3.5 | 8.63 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | H97TGD9PW1AN | 655CMM2810 | APX-7000 Model 3.5 | 28.83 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW1AN | 514CJR1464 | XTL-2500 Mobile | 14.51 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0844 | XTL-2500RB | 0.39 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0845 | XTL-2500RB | 0.94 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---|---|----------|--------------|------------|----------------------|---------------|
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0843 | XTL-2500RB | 3.16 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0842 | XTL-2500RB | 2.84 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0841 | XTL-2500RB | 4.62 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0848 | XTL-2500RB | 0.64 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0846 | XTL-2500RB | 0.55 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0840 | XTL-2500RB | 2.79 |
| Stone Bank Fire Department | Stone Bank Fire Department | Motorola | M21URM9PW2AN | 624CJK0847 | XTL-2500RB | 0.81 |
| | Stone Bank Fire Department Total | | | | | 122.89 |
| Stone Bank Fire Department Total | | | | | | 122.89 |
| Summit | Summit Highway Department | Motorola | H18UCF9PW6AN | 721CJD4345 | XTS-5000 Model II FM | 0.90 |
| Summit | Summit Highway Department | Motorola | H46UCF9PW6BN | 205CHB0886 | XTS-2500 Model II | 0.44 |
| Summit | Summit Highway Department | Motorola | M21URM9PW1AN | 624CJK1045 | XTL-2500 Mobile | 5.88 |
| Summit | Summit Highway Department | Motorola | M21URM9PW2AN | 624CJK1046 | XTL-2500RB | 1.29 |
| Summit | Summit Highway Department | Motorola | M21URM9PW2AN | 624CJK1048 | XTL-2500RB | 4.80 |
| | Summit Highway Department Total | | | | | 13.31 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CEA4981 | XTS-5000 Model II | 12.67 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4351 | XTS-5000 Model II FM | 14.15 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4350 | XTS-5000 Model II FM | 17.67 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0886 | XTS-5000 Model II | 5.80 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0884 | XTS-5000 Model II | 28.52 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0885 | XTS-5000 Model II | 4.10 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CFC0883 | XTS-5000 Model II | 20.07 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4348 | XTS-5000 Model II FM | 4.55 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4352 | XTS-5000 Model II FM | 2.90 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4347 | XTS-5000 Model II FM | 11.64 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4346 | XTS-5000 Model II FM | 5.69 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4354 | XTS-5000 Model II FM | 1.95 |
| Summit | Summit Police Department | Motorola | H18UCF9PW6AN | 721CJD4344 | XTS-5000 Model II FM | 6.17 |
| Summit | Summit Police Department | Motorola | M21URM9PW1AN | 624CJK1066 | XTL-2500 Mobile | 3.83 |
| Summit | Summit Police Department | Motorola | M25URS9PW1AN | 527CQM3761 | APX-6500 Mobile | 104.51 |
| Summit | Summit Police Department | Motorola | M25URS9PW1AN | 527CQM3758 | APX-6500 Mobile | 12.01 |
| Summit | Summit Police Department | Motorola | M25URS9PW1AN | 527CQM3759 | APX-6500 Mobile | 151.32 |
| Summit | Summit Police Department | Motorola | M25URS9PW1AN | 527CQM3760 | APX-6500 Mobile | 1.46 |
| Summit | Summit Police Department | Motorola | M25URS9PW1AN | 527CQM3762 | APX-6500 Mobile | 77.41 |
| | Summit Police Department Total | | | | | 486.42 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|---------------------|-------------------------------------|----------|--------------|------------|-----------------------|---------------|
| Summit Total | | | | | | 499.73 |
| Sussex | Sussex Fire Department | Motorola | H01UCF6PW1BN | 466ABS3392 | MTS-2000 Model II | 12.53 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0114 | APX-6000 Li Model 2.5 | 0.42 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0115 | APX-6000 Li Model 2.5 | 0.07 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0116 | APX-6000 Li Model 2.5 | 1.11 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0117 | APX-6000 Li Model 2.5 | 0.16 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0112 | APX-6000 Li Model 2.5 | 0.33 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0122 | APX-6000 Li Model 2.5 | 2.92 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0118 | APX-6000 Li Model 2.5 | 0.22 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0130 | APX-6000 Li Model 2.5 | 2.49 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0131 | APX-6000 Li Model 2.5 | 1.44 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0132 | APX-6000 Li Model 2.5 | 0.85 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0119 | APX-6000 Li Model 2.5 | 2.84 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0099 | APX-6000 Li Model 2.5 | 4.24 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0108 | APX-6000 Li Model 2.5 | 6.12 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0107 | APX-6000 Li Model 2.5 | 3.53 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0106 | APX-6000 Li Model 2.5 | 1.06 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0104 | APX-6000 Li Model 2.5 | 2.54 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0103 | APX-6000 Li Model 2.5 | 4.91 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0102 | APX-6000 Li Model 2.5 | 4.44 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0101 | APX-6000 Li Model 2.5 | 2.06 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0098 | APX-6000 Li Model 2.5 | 0.12 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0100 | APX-6000 Li Model 2.5 | 3.74 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0121 | APX-6000 Li Model 2.5 | 0.68 |
| Sussex | Sussex Fire Department | Motorola | H98UCF9PW6AN | 755CPB0109 | APX-6000 Li Model 2.5 | 0.11 |
| Sussex | Sussex Fire Department | Motorola | M01UGM6PW6BN | 722ABS1459 | MCS-2000 Model II | 16.46 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1032 | XTL-5000 Mobile | 5.79 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1035 | XTL-5000 Mobile | 5.05 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1024 | XTL-5000 Mobile | 3.44 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1030 | XTL-5000 Mobile | 0.60 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1029 | XTL-5000 Mobile | 33.45 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1028 | XTL-5000 Mobile | 1.03 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1037 | XTL-5000 Mobile | 7.21 |
| Sussex | Sussex Fire Department | Motorola | M20URS9PW1AN | 500CJK1031 | XTL-5000 Mobile | 1.92 |
| | Sussex Fire Department Total | | | | | 133.88 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|---|----------|--------------|------------|----------------------|---------------|
| Sussex | Sussex Public Works Department | Motorola | M21URM9PW2AN | 624CJP0978 | XTL-2500RB | 0.82 |
| | Sussex Public Works Department Total | | | | | 0.82 |
| Sussex Total | | | | | | 134.70 |
| Vernon | Vernon Fire Department | Motorola | H46UCF9PW6BN | 205CMH1789 | XTS-2500 Model II FM | 0.43 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0473 | APX-7000XE Model 3.5 | 0.62 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0488 | APX-7000XE Model 3.5 | 1.09 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0485 | APX-7000XE Model 3.5 | 5.03 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0482 | APX-7000XE Model 3.5 | 0.85 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0479 | APX-7000XE Model 3.5 | 1.40 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0477 | APX-7000XE Model 3.5 | 0.37 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0475 | APX-7000XE Model 3.5 | 0.99 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0478 | APX-7000XE Model 3.5 | 0.72 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0474 | APX-7000XE Model 3.5 | 0.71 |
| Vernon | Vernon Fire Department | Motorola | H49TGD9PW1AN | 562CQP0471 | APX-7000XE Model 3.5 | 1.58 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2544 | APX-6000XE Model 2.5 | 0.67 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2545 | APX-6000XE Model 2.5 | 2.06 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2552 | APX-6000XE Model 2.5 | 0.30 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2551 | APX-6000XE Model 2.5 | 5.70 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2549 | APX-6000XE Model 2.5 | 4.34 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2548 | APX-6000XE Model 2.5 | 0.15 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2547 | APX-6000XE Model 2.5 | 1.90 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 756CQP2543 | APX-6000XE Model 2.5 | 0.37 |
| Vernon | Vernon Fire Department | Motorola | H98UCF9PW6AN | 481CPMD143 | APX-6000 Model 2.5 | 0.18 |
| Vernon | Vernon Fire Department | Motorola | M01UJM6PW6AN | 722AYE2094 | MCS-2000 Model II | 0.39 |
| Vernon | Vernon Fire Department | Motorola | M21URM9PW1AN | 514CLX0473 | XTL-2500 Mobile | 2.20 |
| Vernon | Vernon Fire Department | Motorola | M21URM9PW1AN | 514CLX0474 | XTL-2500 Mobile | 0.09 |
| Vernon | Vernon Fire Department | Motorola | M21URM9PW1AN | 514CMH1239 | XTL-2500 Mobile | 1.72 |
| Vernon | Vernon Fire Department | Motorola | M21URM9PW2AN | 624CJK0819 | XTL-2500RB | 5.18 |
| Vernon | Vernon Fire Department | Motorola | M21URM9PW2AN | 624CJK0827 | XTL-2500RB | 1.75 |
| Vernon | Vernon Fire Department | Motorola | M30TSS9PW1AN | 656CQM1485 | APX-7500 Mobile | 0.42 |
| Vernon | Vernon Fire Department | Motorola | M30TSS9PW1AN | 656CPD0663 | APX-7500 Mobile | 7.47 |
| Vernon | Vernon Fire Department | Motorola | M30TSS9PW1AN | 656CQF0158 | APX-7500 Mobile | 0.94 |
| | Vernon Fire Department Total | | | | | 49.62 |
| Vernon Total | | | | | | 49.62 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466CCQ0703 | MTS-2000 Model II | 0.06 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-------------------------------|-------------------------------|----------|--------------|------------|----------------------|-------|
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3232 | MTS-2000 Model II | 0.39 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3220 | MTS-2000 Model II | 0.10 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3159 | MTS-2000 Model II | 0.70 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3174 | MTS-2000 Model II | 1.21 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466ABL3181 | MTS-2000 Model II | 0.28 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466AZY5344 | MTS-2000 Model II | 0.19 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H01UCF6PW1BN | 466AZY7573 | MTS-2000 Model II | 0.75 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQM1380 | APX-7000XE Model 3.5 | 0.15 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQM1379 | APX-7000XE Model 3.5 | 32.42 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQM1378 | APX-7000XE Model 3.5 | 3.52 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1284 | APX-7000XE Model 3.5 | 1.62 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1280 | APX-7000XE Model 3.5 | 0.07 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1293 | APX-7000XE Model 3.5 | 22.71 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1281 | APX-7000XE Model 3.5 | 5.20 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1283 | APX-7000XE Model 3.5 | 0.34 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1278 | APX-7000XE Model 3.5 | 1.57 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1287 | APX-7000XE Model 3.5 | 0.21 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1288 | APX-7000XE Model 3.5 | 0.11 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1289 | APX-7000XE Model 3.5 | 0.11 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1290 | APX-7000XE Model 3.5 | 7.89 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1292 | APX-7000XE Model 3.5 | 1.37 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1294 | APX-7000XE Model 3.5 | 2.89 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1277 | APX-7000XE Model 3.5 | 0.28 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1291 | APX-7000XE Model 3.5 | 4.26 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1262 | APX-7000XE Model 3.5 | 2.26 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1276 | APX-7000XE Model 3.5 | 0.50 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1264 | APX-7000XE Model 3.5 | 2.52 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1265 | APX-7000XE Model 3.5 | 2.22 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1266 | APX-7000XE Model 3.5 | 1.82 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1267 | APX-7000XE Model 3.5 | 0.42 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1270 | APX-7000XE Model 3.5 | 2.94 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1279 | APX-7000XE Model 3.5 | 0.24 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1272 | APX-7000XE Model 3.5 | 0.22 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | H49TGD9PW1AN | 562CQZ1273 | APX-7000XE Model 3.5 | 0.09 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABY0250 | MCS-2000 Model II | 6.08 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--|--|----------|--------------|------------|--------------------|---------------|
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1339 | MCS-2000 Model II | 15.43 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1304 | MCS-2000 Model II | 2.47 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1328 | MCS-2000 Model II | 0.67 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1322 | MCS-2000 Model II | 13.39 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1301 | MCS-2000 Model II | 2.03 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M01UGM6PW6BN | 722ABL1342 | MCS-2000 Model II | 5.06 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M30TSS9PW1AN | 656CQZ1748 | APX-7500 Mobile | 1.50 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M30TSS9PW1AN | 656CQZ1747 | APX-7500 Mobile | 0.24 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M30TSS9PW1AN | 656CQZ1745 | APX-7500 Mobile | 1.88 |
| Wales/Genesee Fire Department | Wales/Genesee Fire Department | Motorola | M30TSS9PW1AN | 656CQZ1743 | APX-7500 Mobile | 4.19 |
| | Wales/Genesee Fire Department Total | | | | | 154.57 |
| Wales/Genesee Fire Department Total | | | | | | 154.57 |
| Waukesha County | Flight for Life | Motorola | H18UCH9PW7AN | 721CJK2529 | XTS-5000 Model III | 4.27 |
| Waukesha County | Flight for Life | Motorola | H18UCH9PW7AN | 721CJK2530 | XTS-5000 Model III | 0.68 |
| Waukesha County | Flight for Life | Motorola | H18UCH9PW7AN | 721CNR0138 | XTS-5000 Model III | 32.44 |
| Waukesha County | Flight for Life | Motorola | H18UCH9PW7AN | 721CKX2490 | XTS-5000 Model III | 0.05 |
| Waukesha County | Flight for Life | Motorola | M20URS9PW1AN | 500CHV0878 | XTL-5000 Mobile | 35.64 |
| | Flight for Life Total | | | | | 73.08 |
| Waukesha County | Waukesha County Airport | Motorola | H18UCF9PW6AN | 721CEA4983 | XTS-5000 Model II | 0.67 |
| | Waukesha County Airport Total | | | | | 0.67 |
| Waukesha County | Waukesha County Communications | Motorola | H97TGD9PW1AN | 655CQM1966 | APX-7000 Model 3.5 | 0.08 |
| Waukesha County | Waukesha County Communications | Motorola | H97TGD9PW1AN | 655CQM1965 | APX-7000 Model 3.5 | 0.10 |
| Waukesha County | Waukesha County Communications | Motorola | H97TGD9PW1AN | 655CQM1968 | APX-7000 Model 3.5 | 0.12 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722ABA0537 | MCS-2000 Model I | 117.05 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722CEC0629 | MCS-2000 Model I | 7.27 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722ABA0536 | MCS-2000 Model I | 0.93 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722ABY2779 | MCS-2000 Model I | 0.50 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722ABA0535 | MCS-2000 Model I | 0.50 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGL6PW4BN | 722CEC0628 | MCS-2000 Model I | 0.12 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGM6PW6BN | 722CEC0654 | MCS-2000 Model II | 0.04 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGM6PW6BN | 722CEC0659 | MCS-2000 Model II | 0.08 |
| Waukesha County | Waukesha County Communications | Motorola | M01UGM6PW6BN | 722CEC0649 | MCS-2000 Model II | 0.77 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759203 | None | 0.36 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758601 | None | 7.20 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758602 | None | 2.19 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|--------------------------------|----------|---------|----------|------|----------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758603 | None | 0.31 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759515 | None | 6.14 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759212 | None | 0.04 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759213 | None | 0.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758604 | None | 3.59 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758607 | None | 53.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758708 | None | 8.67 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759207 | None | 101.82 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758675 | None | 0.17 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759201 | None | 0.47 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759145 | None | 0.15 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759144 | None | 0.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759215 | None | 2.61 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759128 | None | 1.12 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759115 | None | 1.19 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759208 | None | 7.59 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759508 | None | 41.38 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758503 | None | 0.10 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758501 | None | 1.91 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758628 | None | 2.13 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758509 | None | 0.08 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759536 | None | 1.10 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758545 | None | 18.39 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758928 | None | 1,238.77 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759600 | None | 635.17 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759507 | None | 2.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758636 | None | 0.89 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758608 | None | 145.61 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758702 | None | 0.57 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759112 | None | 0.16 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759528 | None | 4.81 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759544 | None | 11.92 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758508 | None | 2,209.07 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759545 | None | 127.48 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758555 | None | 0.04 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|--------------------------------|----------|---------|----------|------|----------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758826 | None | 0.26 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759103 | None | 0.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758915 | None | 1.40 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758914 | None | 0.13 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758908 | None | 0.64 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758907 | None | 0.15 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758845 | None | 13.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758844 | None | 10.94 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758842 | None | 0.13 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758836 | None | 0.28 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758925 | None | 0.17 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758827 | None | 1.24 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758926 | None | 59.87 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758825 | None | 0.42 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758815 | None | 7.62 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758809 | None | 2.67 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758808 | None | 11.48 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758807 | None | 62.27 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758804 | None | 4.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758803 | None | 2.28 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758802 | None | 0.09 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758801 | None | 3.29 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758828 | None | 149.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759226 | None | 0.21 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759107 | None | 1,528.77 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758609 | None | 0.18 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759045 | None | 2.19 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759044 | None | 3.95 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759028 | None | 20.06 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758644 | None | 132.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758645 | None | 7.80 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759026 | None | 0.16 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759016 | None | 0.37 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758924 | None | 0.23 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759009 | None | 1.16 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|--------------------------------|----------|---------|----------|------|----------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759108 | None | 0.88 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758712 | None | 0.17 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758715 | None | 0.81 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758744 | None | 1,860.39 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759008 | None | 0.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759007 | None | 12.03 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758945 | None | 0.39 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758930 | None | 0.09 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758929 | None | 0.27 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758927 | None | 0.34 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759015 | None | 1.71 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758615 | None | 13.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758236 | None | 0.28 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758215 | None | 2.18 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759504 | None | 5.68 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758208 | None | 1.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758207 | None | 1.06 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759502 | None | 1.63 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759328 | None | 0.23 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759429 | None | 1.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758629 | None | 0.10 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759428 | None | 0.12 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759415 | None | 0.98 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758204 | None | 23.24 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759408 | None | 0.19 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759345 | None | 0.38 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759344 | None | 0.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759501 | None | 2.29 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758515 | None | 7.95 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758355 | None | 0.02 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758345 | None | 239.84 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758344 | None | 29.80 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758342 | None | 0.13 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758336 | None | 2.09 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758328 | None | 0.75 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|----------------------|------------------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759228 | None | 0.83 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758309 | None | 2.66 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758245 | None | 3,276.52 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758544 | None | 0.91 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758707 | None | 0.22 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758308 | None | 52.20 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758307 | None | 6.97 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758304 | None | 27.48 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758301 | None | 3.17 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758244 | None | 1.30 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758315 | None | 14.52 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759307 | None | 13.21 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759244 | None | 6.62 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759303 | None | 1.49 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759308 | None | 0.23 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758104 | None | 0.48 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758115 | None | 0.45 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758126 | None | 0.05 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758136 | None | 0.93 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758142 | None | 0.57 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758145 | None | 2.26 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759315 | None | 2.82 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758165 | None | 0.20 |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759245 | None | 0.09 |
| | Waukesha County Communications Total | | | | | 12,424.26 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H18UCF9PW6AN | 721CEA4987 | XTS-5000 Model II | 1.95 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H18UCF9PW6AN | 721CJH0373 | XTS-5000 Model II FM | 0.94 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H18UCF9PW6AN | 721CJH0370 | XTS-5000 Model II FM | 1.15 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H97TGD9PW1AN | 655CQM0912 | APX-7000 Model 3.5 | 0.11 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H97TGD9PW1AN | 655CQM0913 | APX-7000 Model 3.5 | 0.08 |
| Waukesha County | Waukesha County Department of Human Services | Motorola | H98UCF9PW6AN | 481CQM6956 | APX-6000 Model 2.5 | 0.05 |
| | Waukesha County Department of Human Services Total | | | | | 4.28 |
| Waukesha County | Waukesha County Emergency Management | Motorola | M01UGM6PW6BN | 722ABE1293 | MCS-2000 Model II | 47.92 |
| | Waukesha County Emergency Management Total | | | | | 47.92 |
| Waukesha County | Waukesha County Fleet Maintenance | Motorola | H98UCF9PW6AN | 481CQP2405 | APX-6000 Model 2.5 | 0.22 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|--|----------|--------------|------------|----------------------|-------------|
| | Waukesha County Fleet Maintenance Total | | | | | 0.22 |
| Waukesha County | Waukesha County Jail | Motorola | H46UCF9PW6BN | 205CJF0696 | XTS-2500 Model II FM | 6.54 |
| | Waukesha County Jail Total | | | | | 6.54 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3026 | MTS-2000 Model I | 4.87 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3038 | MTS-2000 Model I | 0.77 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3039 | MTS-2000 Model I | 0.99 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3050 | MTS-2000 Model I | 13.34 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3040 | MTS-2000 Model I | 14.33 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H01UCD6PW1BN | 466ABS3037 | MTS-2000 Model I | 3.81 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0690 | XTS-2500 Model II FM | 7.86 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0683 | XTS-2500 Model II FM | 13.70 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0665 | XTS-2500 Model II FM | 4.19 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0684 | XTS-2500 Model II FM | 1.63 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0686 | XTS-2500 Model II FM | 1.89 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0687 | XTS-2500 Model II FM | 8.40 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0688 | XTS-2500 Model II FM | 2.05 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0666 | XTS-2500 Model II FM | 1.70 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0667 | XTS-2500 Model II FM | 4.86 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0682 | XTS-2500 Model II FM | 3.44 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0669 | XTS-2500 Model II FM | 2.93 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0693 | XTS-2500 Model II FM | 1.01 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0694 | XTS-2500 Model II FM | 15.72 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0692 | XTS-2500 Model II FM | 6.74 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0672 | XTS-2500 Model II FM | 2.34 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0673 | XTS-2500 Model II FM | 0.09 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0678 | XTS-2500 Model II FM | 0.81 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0675 | XTS-2500 Model II FM | 0.84 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0677 | XTS-2500 Model II FM | 5.39 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0668 | XTS-2500 Model II FM | 1.02 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0699 | XTS-2500 Model II FM | 7.39 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0680 | XTS-2500 Model II FM | 7.24 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0681 | XTS-2500 Model II FM | 0.28 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0698 | XTS-2500 Model II FM | 1.61 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0695 | XTS-2500 Model II FM | 5.19 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H46UCF9PW6BN | 205CJF0662 | XTS-2500 Model II FM | 1.72 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|----------------------|---------------|
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1655 | APX-6000 Model 2.5 | 11.08 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1668 | APX-6000 Model 2.5 | 7.13 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1667 | APX-6000 Model 2.5 | 2.20 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1637 | APX-6000 Model 2.5 | 6.71 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1638 | APX-6000 Model 2.5 | 7.90 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1639 | APX-6000 Model 2.5 | 26.96 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1640 | APX-6000 Model 2.5 | 7.54 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1666 | APX-6000 Model 2.5 | 8.63 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1665 | APX-6000 Model 2.5 | 19.58 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1664 | APX-6000 Model 2.5 | 28.52 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1642 | APX-6000 Model 2.5 | 0.58 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1653 | APX-6000 Model 2.5 | 4.14 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1660 | APX-6000 Model 2.5 | 0.25 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1647 | APX-6000 Model 2.5 | 7.83 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1636 | APX-6000 Model 2.5 | 6.53 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1643 | APX-6000 Model 2.5 | 8.19 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1634 | APX-6000 Model 2.5 | 0.95 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1644 | APX-6000 Model 2.5 | 0.20 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1652 | APX-6000 Model 2.5 | 5.67 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1645 | APX-6000 Model 2.5 | 36.47 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1650 | APX-6000 Model 2.5 | 5.99 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1646 | APX-6000 Model 2.5 | 14.36 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1649 | APX-6000 Model 2.5 | 0.50 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1648 | APX-6000 Model 2.5 | 2.02 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1663 | APX-6000 Model 2.5 | 10.42 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1628 | APX-6000 Model 2.5 | 19.30 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1641 | APX-6000 Model 2.5 | 4.74 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1629 | APX-6000 Model 2.5 | 2.56 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1630 | APX-6000 Model 2.5 | 7.20 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1631 | APX-6000 Model 2.5 | 24.90 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1632 | APX-6000 Model 2.5 | 11.66 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1633 | APX-6000 Model 2.5 | 12.77 |
| Waukesha County | Waukesha County Maintenance Department | Motorola | H98UCF9PW6AN | 481CQP1635 | APX-6000 Model 2.5 | 5.63 |
| | Waukesha County Maintenance Department Total | | | | | 467.26 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0437 | XTS-2500 Model II FM | 0.56 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|----------------------|--------------|
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0479 | XTS-2500 Model II FM | 1.65 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0477 | XTS-2500 Model II FM | 0.12 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0469 | XTS-2500 Model II FM | 2.81 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0467 | XTS-2500 Model II FM | 2.82 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0465 | XTS-2500 Model II FM | 1.21 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0457 | XTS-2500 Model II FM | 0.70 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0453 | XTS-2500 Model II FM | 0.64 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0428 | XTS-2500 Model II FM | 0.53 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0445 | XTS-2500 Model II FM | 0.05 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0439 | XTS-2500 Model II FM | 0.42 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0703 | XTS-2500 Model II FM | 1.33 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2166 | APX-6000XE Model 2.5 | 0.69 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2163 | APX-6000XE Model 2.5 | 0.38 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2153 | APX-6000XE Model 2.5 | 0.43 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2142 | APX-6000XE Model 2.5 | 0.11 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2147 | APX-6000XE Model 2.5 | 0.11 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2146 | APX-6000XE Model 2.5 | 0.59 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2100 | APX-6000XE Model 2.5 | 0.05 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2092 | APX-6000XE Model 2.5 | 0.36 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2103 | APX-6000XE Model 2.5 | 0.21 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2099 | APX-6000XE Model 2.5 | 0.11 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2097 | APX-6000XE Model 2.5 | 0.04 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2093 | APX-6000XE Model 2.5 | 0.15 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2171 | APX-6000XE Model 2.5 | 0.19 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2091 | APX-6000XE Model 2.5 | 0.05 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2078 | APX-6000XE Model 2.5 | 0.07 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2188 | APX-6000XE Model 2.5 | 0.32 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2181 | APX-6000XE Model 2.5 | 0.05 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H98UCF9PW6AN | 756CQM2175 | APX-6000XE Model 2.5 | 0.29 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M21URM9PW2AN | 624CJP0982 | XTL-2500RB | 1.48 |
| | Waukesha County Parks and Land Use Total | | | | | 18.52 |
| Waukesha County | Waukesha County Radio Services | Motorola | H49TGD9PW1AN | 562CQP0319 | APX-7000XE Model 3.5 | 0.05 |
| Waukesha County | Waukesha County Radio Services | Motorola | H97TGD9PW1AN | 655CNZ2355 | APX-7000 Model 3.5 | 0.05 |
| | Waukesha County Radio Services Total | | | | | 0.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1037 | APX-7000XE Model 3.5 | 26.76 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1032 | APX-7000XE Model 3.5 | 13.99 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1045 | APX-7000XE Model 3.5 | 2.67 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1046 | APX-7000XE Model 3.5 | 2.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1047 | APX-7000XE Model 3.5 | 16.50 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1048 | APX-7000XE Model 3.5 | 11.37 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1041 | APX-7000XE Model 3.5 | 10.86 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1295 | APX-7000XE Model 3.5 | 8.04 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1284 | APX-7000XE Model 3.5 | 4.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1285 | APX-7000XE Model 3.5 | 0.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1286 | APX-7000XE Model 3.5 | 0.31 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1287 | APX-7000XE Model 3.5 | 12.70 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1288 | APX-7000XE Model 3.5 | 6.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1289 | APX-7000XE Model 3.5 | 6.60 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1290 | APX-7000XE Model 3.5 | 10.87 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1291 | APX-7000XE Model 3.5 | 8.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1292 | APX-7000XE Model 3.5 | 4.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1340 | APX-7000XE Model 3.5 | 1.84 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1294 | APX-7000XE Model 3.5 | 13.87 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1280 | APX-7000XE Model 3.5 | 33.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1296 | APX-7000XE Model 3.5 | 18.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1298 | APX-7000XE Model 3.5 | 6.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1300 | APX-7000XE Model 3.5 | 11.96 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1301 | APX-7000XE Model 3.5 | 16.90 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1302 | APX-7000XE Model 3.5 | 6.58 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1303 | APX-7000XE Model 3.5 | 2.93 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1305 | APX-7000XE Model 3.5 | 9.57 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1307 | APX-7000XE Model 3.5 | 4.17 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1308 | APX-7000XE Model 3.5 | 11.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1310 | APX-7000XE Model 3.5 | 0.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1293 | APX-7000XE Model 3.5 | 9.57 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1268 | APX-7000XE Model 3.5 | 20.59 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1064 | APX-7000XE Model 3.5 | 0.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1317 | APX-7000XE Model 3.5 | 3.06 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1318 | APX-7000XE Model 3.5 | 6.78 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1320 | APX-7000XE Model 3.5 | 42.96 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1322 | APX-7000XE Model 3.5 | 4.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1325 | APX-7000XE Model 3.5 | 10.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1326 | APX-7000XE Model 3.5 | 15.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1328 | APX-7000XE Model 3.5 | 20.79 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1333 | APX-7000XE Model 3.5 | 8.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1334 | APX-7000XE Model 3.5 | 4.85 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1283 | APX-7000XE Model 3.5 | 16.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1267 | APX-7000XE Model 3.5 | 46.47 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1282 | APX-7000XE Model 3.5 | 12.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1269 | APX-7000XE Model 3.5 | 0.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1270 | APX-7000XE Model 3.5 | 0.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1271 | APX-7000XE Model 3.5 | 6.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1273 | APX-7000XE Model 3.5 | 42.09 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1274 | APX-7000XE Model 3.5 | 10.82 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1275 | APX-7000XE Model 3.5 | 74.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1276 | APX-7000XE Model 3.5 | 22.32 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1278 | APX-7000XE Model 3.5 | 14.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1279 | APX-7000XE Model 3.5 | 20.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1313 | APX-7000XE Model 3.5 | 10.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1352 | APX-7000XE Model 3.5 | 11.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1353 | APX-7000XE Model 3.5 | 5.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1311 | APX-7000XE Model 3.5 | 0.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1339 | APX-7000XE Model 3.5 | 9.59 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1341 | APX-7000XE Model 3.5 | 12.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1342 | APX-7000XE Model 3.5 | 6.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1343 | APX-7000XE Model 3.5 | 10.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1344 | APX-7000XE Model 3.5 | 8.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1345 | APX-7000XE Model 3.5 | 13.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1346 | APX-7000XE Model 3.5 | 3.09 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1347 | APX-7000XE Model 3.5 | 6.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1348 | APX-7000XE Model 3.5 | 4.21 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1338 | APX-7000XE Model 3.5 | 16.98 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1350 | APX-7000XE Model 3.5 | 15.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1337 | APX-7000XE Model 3.5 | 1.31 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1354 | APX-7000XE Model 3.5 | 1.90 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1355 | APX-7000XE Model 3.5 | 12.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1356 | APX-7000XE Model 3.5 | 11.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1359 | APX-7000XE Model 3.5 | 8.17 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1360 | APX-7000XE Model 3.5 | 6.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1362 | APX-7000XE Model 3.5 | 42.50 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1363 | APX-7000XE Model 3.5 | 6.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1364 | APX-7000XE Model 3.5 | 6.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1365 | APX-7000XE Model 3.5 | 2.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1366 | APX-7000XE Model 3.5 | 20.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1349 | APX-7000XE Model 3.5 | 8.50 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1319 | APX-7000XE Model 3.5 | 11.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1038 | APX-7000XE Model 3.5 | 2.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1314 | APX-7000XE Model 3.5 | 12.43 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1315 | APX-7000XE Model 3.5 | 19.62 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1316 | APX-7000XE Model 3.5 | 16.33 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1021 | APX-7000XE Model 3.5 | 11.46 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1027 | APX-7000XE Model 3.5 | 5.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1030 | APX-7000XE Model 3.5 | 6.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1036 | APX-7000XE Model 3.5 | 4.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1053 | APX-7000XE Model 3.5 | 0.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1056 | APX-7000XE Model 3.5 | 9.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1075 | APX-7000XE Model 3.5 | 25.86 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1066 | APX-7000XE Model 3.5 | 4.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1312 | APX-7000XE Model 3.5 | 2.80 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1321 | APX-7000XE Model 3.5 | 4.85 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1323 | APX-7000XE Model 3.5 | 1.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1324 | APX-7000XE Model 3.5 | 11.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1327 | APX-7000XE Model 3.5 | 11.93 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1329 | APX-7000XE Model 3.5 | 10.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1330 | APX-7000XE Model 3.5 | 8.46 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1331 | APX-7000XE Model 3.5 | 6.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1332 | APX-7000XE Model 3.5 | 32.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1335 | APX-7000XE Model 3.5 | 19.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1336 | APX-7000XE Model 3.5 | 10.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1061 | APX-7000XE Model 3.5 | 23.79 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0983 | APX-7000XE Model 3.5 | 16.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0995 | APX-7000XE Model 3.5 | 8.95 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0994 | APX-7000XE Model 3.5 | 11.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1008 | APX-7000XE Model 3.5 | 0.41 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1001 | APX-7000XE Model 3.5 | 18.89 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0968 | APX-7000XE Model 3.5 | 32.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0989 | APX-7000XE Model 3.5 | 13.59 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0988 | APX-7000XE Model 3.5 | 0.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0967 | APX-7000XE Model 3.5 | 23.98 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0987 | APX-7000XE Model 3.5 | 4.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0999 | APX-7000XE Model 3.5 | 0.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0985 | APX-7000XE Model 3.5 | 0.25 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1006 | APX-7000XE Model 3.5 | 0.11 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0982 | APX-7000XE Model 3.5 | 3.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0981 | APX-7000XE Model 3.5 | 4.74 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0980 | APX-7000XE Model 3.5 | 16.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0979 | APX-7000XE Model 3.5 | 3.61 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0978 | APX-7000XE Model 3.5 | 0.79 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0975 | APX-7000XE Model 3.5 | 4.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0972 | APX-7000XE Model 3.5 | 14.30 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0971 | APX-7000XE Model 3.5 | 13.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0970 | APX-7000XE Model 3.5 | 0.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0969 | APX-7000XE Model 3.5 | 8.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0986 | APX-7000XE Model 3.5 | 16.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1016 | APX-7000XE Model 3.5 | 0.10 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1074 | APX-7000XE Model 3.5 | 13.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1072 | APX-7000XE Model 3.5 | 38.20 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1069 | APX-7000XE Model 3.5 | 5.03 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1070 | APX-7000XE Model 3.5 | 14.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1018 | APX-7000XE Model 3.5 | 8.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1033 | APX-7000XE Model 3.5 | 17.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1071 | APX-7000XE Model 3.5 | 16.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1013 | APX-7000XE Model 3.5 | 14.70 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1073 | APX-7000XE Model 3.5 | 12.30 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1014 | APX-7000XE Model 3.5 | 14.79 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|-----------------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM0990 | APX-7000XE Model 3.5 | 20.55 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1015 | APX-7000XE Model 3.5 | 0.20 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1029 | APX-7000XE Model 3.5 | 3.99 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1020 | APX-7000XE Model 3.5 | 0.71 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1028 | APX-7000XE Model 3.5 | 10.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1044 | APX-7000XE Model 3.5 | 9.21 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1034 | APX-7000XE Model 3.5 | 6.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1035 | APX-7000XE Model 3.5 | 8.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1040 | APX-7000XE Model 3.5 | 3.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1065 | APX-7000XE Model 3.5 | 0.17 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1031 | APX-7000XE Model 3.5 | 13.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H49TGD9PW1AN | 562CQM1050 | APX-7000XE Model 3.5 | 1.01 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H97TGD9PW1AN | 655CMH1140 | APX-7000 Model 1.5 | 20.74 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H97TGD9PW1AN | 655CMH1139 | APX-7000 Model 1.5 | 18.04 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H97TGD9PW1AN | 655CMH1138 | APX-7000 Model 1.5 | 15.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H97TGD9PW1AN | 655CMH1141 | APX-7000 Model 1.5 | 13.87 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1446 | MCS-2000 Model II DES | 20.70 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABS1463 | MCS-2000 Model II DES | 0.12 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1278 | MCS-2000 Model II | 3.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1437 | MCS-2000 Model II DES | 31.01 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1315 | MCS-2000 Model II | 5.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1280 | MCS-2000 Model II | 35.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1441 | MCS-2000 Model II DES | 6.77 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1282 | MCS-2000 Model II | 76.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1443 | MCS-2000 Model II DES | 15.90 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1285 | MCS-2000 Model II | 18.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1439 | MCS-2000 Model II DES | 8.89 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1272 | MCS-2000 Model II | 18.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1453 | MCS-2000 Model II DES | 0.05 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1444 | MCS-2000 Model II | 35.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1450 | MCS-2000 Model II DES | 2.23 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1267 | MCS-2000 Model II | 17.55 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UJM6PW6AN | 722AYE2516 | MCS-2000 Model II | 24.91 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M20URS9PW1AN | 500CJV0578 | XTL-5000 Mobile | 0.47 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M20URS9PW1AN | 500CLK0563 | XTL-5000 Mobile | 40.45 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|------------------------------------|----------|--------------|------------|-----------------|--------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1838 | APX-6500 Mobile | 61.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1837 | APX-6500 Mobile | 57.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1836 | APX-6500 Mobile | 80.07 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1835 | APX-6500 Mobile | 138.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1823 | APX-6500 Mobile | 130.69 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1824 | APX-6500 Mobile | 1.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1825 | APX-6500 Mobile | 0.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1831 | APX-6500 Mobile | 15.81 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1828 | APX-6500 Mobile | 0.83 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1818 | APX-6500 Mobile | 0.63 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1829 | APX-6500 Mobile | 0.99 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1830 | APX-6500 Mobile | 5.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1844 | APX-6500 Mobile | 94.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1843 | APX-6500 Mobile | 160.74 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1841 | APX-6500 Mobile | 104.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1840 | APX-6500 Mobile | 172.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1826 | APX-6500 Mobile | 0.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1851 | APX-6500 Mobile | 50.45 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1858 | APX-6500 Mobile | 16.82 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1857 | APX-6500 Mobile | 116.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1856 | APX-6500 Mobile | 104.36 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1834 | APX-6500 Mobile | 115.60 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1854 | APX-6500 Mobile | 24.09 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1859 | APX-6500 Mobile | 141.13 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1852 | APX-6500 Mobile | 26.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1855 | APX-6500 Mobile | 57.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1850 | APX-6500 Mobile | 48.65 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1849 | APX-6500 Mobile | 22.32 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1848 | APX-6500 Mobile | 130.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1847 | APX-6500 Mobile | 116.02 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1846 | APX-6500 Mobile | 93.85 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1845 | APX-6500 Mobile | 23.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1820 | APX-6500 Mobile | 4.36 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1819 | APX-6500 Mobile | 0.53 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1853 | APX-6500 Mobile | 37.68 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|--------------------|-----------------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1839 | APX-6500 Mobile | 72.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1860 | APX-6500 Mobile | 31.21 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1821 | APX-6500 Mobile | 1.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1817 | APX-6500 Mobile | 6.18 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1816 | APX-6500 Mobile | 2.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1815 | APX-6500 Mobile | 1.27 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1812 | APX-6500 Mobile | 1.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1810 | APX-6500 Mobile | 117.39 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1809 | APX-6500 Mobile | 8.62 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1807 | APX-6500 Mobile | 0.06 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1806 | APX-6500 Mobile | 7.15 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1805 | APX-6500 Mobile | 4.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1814 | APX-6500 Mobile | 1.00 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M25URS9PW1AN | 527CQM1833 | APX-6500 Mobile | 37.20 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0797 | APX-7500 Mobile | 0.35 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0814 | APX-7500 Mobile | 2.19 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0815 | APX-7500 Mobile | 0.67 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0817 | APX-7500 Mobile | 2.88 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0819 | APX-7500 Mobile | 25.80 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0790 | APX-7500 Mobile | 20.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0793 | APX-7500 Mobile | 22.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0795 | APX-7500 Mobile | 66.74 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0799 | APX-7500 Mobile | 2.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M30TSS9PW1AN | 656CQM0794 | APX-7500 Mobile | 17.72 |
| | Waukesha County Sheriff Department Total | | | | | 4,725.99 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H98UCF9PW6AN | 481CQP2172 | APX-6000 Model 2.5 | 2.39 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H98UCF9PW6AN | 481CQP2171 | APX-6000 Model 2.5 | 0.44 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H98UCF9PW6AN | 481CQP2169 | APX-6000 Model 2.5 | 0.67 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H98UCF9PW6AN | 481CQP2162 | APX-6000 Model 2.5 | 0.10 |
| Waukesha County | Waukesha County Transportation Department | Motorola | H98UCF9PW6AN | 481CQP2163 | APX-6000 Model 2.5 | 0.71 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M01UGM6PW6BN | 722ABS1451 | MCS-2000 Model II | 4.63 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3256 | APX-6500 Mobile | 0.59 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3184 | APX-6500 Mobile | 1.40 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3236 | APX-6500 Mobile | 0.45 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3201 | APX-6500 Mobile | 0.43 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|-----------------|-------|
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3200 | APX-6500 Mobile | 0.59 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3199 | APX-6500 Mobile | 0.02 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3196 | APX-6500 Mobile | 0.38 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3195 | APX-6500 Mobile | 0.47 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3194 | APX-6500 Mobile | 0.37 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3192 | APX-6500 Mobile | 0.41 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3191 | APX-6500 Mobile | 0.09 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3174 | APX-6500 Mobile | 0.95 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3186 | APX-6500 Mobile | 5.00 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3240 | APX-6500 Mobile | 0.30 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3183 | APX-6500 Mobile | 1.65 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3182 | APX-6500 Mobile | 3.22 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3273 | APX-6500 Mobile | 0.28 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3272 | APX-6500 Mobile | 0.97 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3270 | APX-6500 Mobile | 2.62 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3269 | APX-6500 Mobile | 5.71 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3268 | APX-6500 Mobile | 1.73 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3267 | APX-6500 Mobile | 0.26 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3266 | APX-6500 Mobile | 0.64 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3265 | APX-6500 Mobile | 1.02 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3189 | APX-6500 Mobile | 1.59 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3221 | APX-6500 Mobile | 3.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3172 | APX-6500 Mobile | 0.33 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3178 | APX-6500 Mobile | 1.55 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3259 | APX-6500 Mobile | 0.96 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3262 | APX-6500 Mobile | 6.59 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3263 | APX-6500 Mobile | 0.55 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3264 | APX-6500 Mobile | 0.86 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3227 | APX-6500 Mobile | 0.89 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3226 | APX-6500 Mobile | 0.89 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3225 | APX-6500 Mobile | 2.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3224 | APX-6500 Mobile | 0.63 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3238 | APX-6500 Mobile | 11.15 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3222 | APX-6500 Mobile | 2.13 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3239 | APX-6500 Mobile | 3.56 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------|---|----------|--------------|------------|-----------------|-------|
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3220 | APX-6500 Mobile | 0.48 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3219 | APX-6500 Mobile | 2.29 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3255 | APX-6500 Mobile | 0.53 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3251 | APX-6500 Mobile | 1.15 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3247 | APX-6500 Mobile | 0.19 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3246 | APX-6500 Mobile | 1.14 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3245 | APX-6500 Mobile | 0.71 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3242 | APX-6500 Mobile | 0.08 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3241 | APX-6500 Mobile | 0.52 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3168 | APX-6500 Mobile | 0.48 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3223 | APX-6500 Mobile | 5.03 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3150 | APX-6500 Mobile | 0.36 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3159 | APX-6500 Mobile | 0.13 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3229 | APX-6500 Mobile | 0.53 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3147 | APX-6500 Mobile | 5.96 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3230 | APX-6500 Mobile | 1.29 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3231 | APX-6500 Mobile | 1.63 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3232 | APX-6500 Mobile | 1.44 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3148 | APX-6500 Mobile | 6.36 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3157 | APX-6500 Mobile | 3.60 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3156 | APX-6500 Mobile | 1.25 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3154 | APX-6500 Mobile | 1.89 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3152 | APX-6500 Mobile | 4.63 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3151 | APX-6500 Mobile | 2.78 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3228 | APX-6500 Mobile | 3.31 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3163 | APX-6500 Mobile | 11.49 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3143 | APX-6500 Mobile | 4.24 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3146 | APX-6500 Mobile | 0.40 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3165 | APX-6500 Mobile | 0.09 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3164 | APX-6500 Mobile | 0.20 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3145 | APX-6500 Mobile | 0.49 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3162 | APX-6500 Mobile | 1.58 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3144 | APX-6500 Mobile | 0.80 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3158 | APX-6500 Mobile | 1.69 |
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3142 | APX-6500 Mobile | 1.32 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--|--|----------|--------------|------------|----------------------|------------------|
| Waukesha County | Waukesha County Transportation Department | Motorola | M25URS9PW1AN | 527CQM3149 | APX-6500 Mobile | 1.64 |
| | Waukesha County Transportation Department Total | | | | | 148.25 |
| Waukesha County Total | | | | | | 17,917.09 |
| Waukesha County Emergency Support & Rehab, Inc. | Waukesha County Emergency Support & Rehab, Inc. | Motorola | H01UCD6PW1BN | 466ABS2918 | MTS-2000 Model I | 1.04 |
| | Waukesha County Emergency Support & Rehab, Inc. Total | | | | | 1.04 |
| Waukesha County Emergency Support & Rehab, Inc. Total | | | | | | 1.04 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2210 | XTS-2500 Model II FM | 28.39 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2214 | XTS-2500 Model II FM | 7.46 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2216 | XTS-2500 Model II FM | 60.06 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2217 | XTS-2500 Model II FM | 17.34 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2211 | XTS-2500 Model II FM | 44.44 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2212 | XTS-2500 Model II FM | 42.35 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2215 | XTS-2500 Model II FM | 39.65 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2221 | XTS-2500 Model II FM | 7.33 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2213 | XTS-2500 Model II FM | 23.12 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2220 | XTS-2500 Model II FM | 24.83 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H46UCF9PW6BN | 205CGX2219 | XTS-2500 Model II FM | 24.36 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7205 | APX-4000 Model 2 | 2.47 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7204 | APX-4000 Model 2 | 0.48 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7202 | APX-4000 Model 2 | 0.51 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7203 | APX-4000 Model 2 | 1.49 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7207 | APX-4000 Model 2 | 0.84 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7206 | APX-4000 Model 2 | 1.62 |
| Waukesha County Technical College | Waukesha County Technical College | Motorola | H51UCF9PW6AN | 426CRF7208 | APX-4000 Model 2 | 0.94 |
| | Waukesha County Technical College Total | | | | | 327.68 |
| Waukesha County Technical College Total | | | | | | 327.68 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H01UCD6PW1BN | 466ABQ0930 | MTS-2000 Model I | 0.92 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H01UCD6PW1BN | 466ABQ0776 | MTS-2000 Model I | 0.20 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H18UCF9PW6AN | 721CJK4322 | XTS-5000 Model II FM | 1.60 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H18UCF9PW6AN | 721CJK4320 | XTS-5000 Model II FM | 0.12 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | H18UCF9PW6AN | 721CJF0012 | XTS-5000 Model II FM | 0.20 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M21URM9PW2AN | 624CJV0128 | XTL-2500RB | 0.15 |
| Waukesha, City | Waukesha City Engineering Department | Motorola | M21URM9PW2AN | 624CJV0130 | XTL-2500RB | 0.40 |
| | Waukesha City Engineering Department Total | | | | | 3.59 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJD2818 | XTS-5000 Model II FM | 0.15 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|-------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0029 | XTS-5000 Model II FM | 5.19 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJD2817 | XTS-5000 Model II FM | 0.90 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0019 | XTS-5000 Model II FM | 0.13 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1245 | APX-7000XE Model 3.5 | 8.21 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1242 | APX-7000XE Model 3.5 | 15.96 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1246 | APX-7000XE Model 3.5 | 22.24 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1235 | APX-7000XE Model 3.5 | 35.93 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1244 | APX-7000XE Model 3.5 | 4.00 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1234 | APX-7000XE Model 3.5 | 21.87 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1236 | APX-7000XE Model 3.5 | 5.56 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1237 | APX-7000XE Model 3.5 | 21.08 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1238 | APX-7000XE Model 3.5 | 3.47 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1243 | APX-7000XE Model 3.5 | 12.84 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H49TGD9PW1AN | 562CQM1240 | APX-7000XE Model 3.5 | 6.64 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1734 | APX-7000 Model 3.5 | 6.62 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1737 | APX-7000 Model 3.5 | 5.64 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1736 | APX-7000 Model 3.5 | 4.96 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1741 | APX-7000 Model 3.5 | 2.56 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H97TGD9PW1AN | 655CQM1739 | APX-7000 Model 3.5 | 0.25 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2638 | APX-6000XE Model 2.5 | 5.13 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2628 | APX-6000XE Model 2.5 | 0.29 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2637 | APX-6000XE Model 2.5 | 4.85 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2633 | APX-6000XE Model 2.5 | 3.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2629 | APX-6000XE Model 2.5 | 0.73 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2630 | APX-6000XE Model 2.5 | 4.11 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2639 | APX-6000XE Model 2.5 | 3.13 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2616 | APX-6000XE Model 2.5 | 0.75 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2647 | APX-6000XE Model 2.5 | 0.76 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2631 | APX-6000XE Model 2.5 | 0.10 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2640 | APX-6000XE Model 2.5 | 0.25 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2641 | APX-6000XE Model 2.5 | 5.23 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2643 | APX-6000XE Model 2.5 | 0.05 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2618 | APX-6000XE Model 2.5 | 0.67 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2648 | APX-6000XE Model 2.5 | 10.70 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2612 | APX-6000XE Model 2.5 | 0.03 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|--|----------|--------------|------------|----------------------|---------------|
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2611 | APX-6000XE Model 2.5 | 0.69 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2623 | APX-6000XE Model 2.5 | 0.41 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2649 | APX-6000XE Model 2.5 | 4.17 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2617 | APX-6000XE Model 2.5 | 0.19 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2620 | APX-6000XE Model 2.5 | 1.46 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2619 | APX-6000XE Model 2.5 | 0.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H98UCF9PW6AN | 756CQP2642 | APX-6000XE Model 2.5 | 0.45 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CFA0321 | MCS-2000 Model II | 1.64 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1040 | XTL-5000 Mobile | 32.65 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1047 | XTL-5000 Mobile | 26.22 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1055 | XTL-5000 Mobile | 50.13 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1054 | XTL-5000 Mobile | 31.22 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1052 | XTL-5000 Mobile | 25.01 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1050 | XTL-5000 Mobile | 28.50 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1038 | XTL-5000 Mobile | 60.08 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1048 | XTL-5000 Mobile | 1.04 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGT0271 | XTL-5000 Mobile | 34.99 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1043 | XTL-5000 Mobile | 38.86 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1039 | XTL-5000 Mobile | 0.18 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1036 | XTL-5000 Mobile | 17.00 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1034 | XTL-5000 Mobile | 31.01 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1032 | XTL-5000 Mobile | 0.33 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1031 | XTL-5000 Mobile | 0.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGR0351 | XTL-5000 Mobile | 5.07 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGR0352 | XTL-5000 Mobile | 18.72 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1049 | XTL-5000 Mobile | 0.55 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M25URS9PW1AN | 527CQM3898 | APX-6500 Mobile | 0.46 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M28URS9PW1AN | 775CJM1410 | XTL-1500 Mobile | 5.90 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M28URS9PW1AN | 775CJM1411 | XTL-1500 Mobile | 5.32 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M28URS9PW1AN | 775CKF0277 | XTL-1500 Mobile | 1.70 |
| | Waukesha City Fire Department Total | | | | | 648.41 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H18UCF9PW6AN | 721CJD2814 | XTS-5000 Model II FM | 16.50 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H18UCF9PW6AN | 721CJD2820 | XTS-5000 Model II FM | 97.44 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H18UCF9PW6AN | 721CJF0027 | XTS-5000 Model II FM | 76.09 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H18UCF9PW6AN | 721CJF0008 | XTS-5000 Model II FM | 0.92 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|------------------------------------|----------|--------------|------------|----------------------|--------|
| Waukesha, City | Waukesha City Metro Transit System | Motorola | H18UCF9PW6AN | 721CJF0014 | XTS-5000 Model II FM | 64.71 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0147 | XTL-2500RB | 170.34 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0136 | XTL-2500RB | 37.11 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0141 | XTL-2500RB | 55.90 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0142 | XTL-2500RB | 9.07 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0143 | XTL-2500RB | 24.28 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0144 | XTL-2500RB | 50.81 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0139 | XTL-2500RB | 64.58 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0146 | XTL-2500RB | 51.83 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0138 | XTL-2500RB | 0.30 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0148 | XTL-2500RB | 31.90 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0149 | XTL-2500RB | 0.24 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0150 | XTL-2500RB | 70.84 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0152 | XTL-2500RB | 81.10 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0153 | XTL-2500RB | 56.50 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0154 | XTL-2500RB | 17.43 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0156 | XTL-2500RB | 0.51 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0145 | XTL-2500RB | 59.06 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0162 | XTL-2500RB | 38.01 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0169 | XTL-2500RB | 44.88 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0168 | XTL-2500RB | 52.38 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0167 | XTL-2500RB | 22.36 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0166 | XTL-2500RB | 0.37 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0165 | XTL-2500RB | 32.33 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0140 | XTL-2500RB | 69.16 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0163 | XTL-2500RB | 59.18 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0161 | XTL-2500RB | 28.12 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0135 | XTL-2500RB | 33.80 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0159 | XTL-2500RB | 4.50 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0137 | XTL-2500RB | 67.65 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0158 | XTL-2500RB | 54.89 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0157 | XTL-2500RB | 50.17 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0132 | XTL-2500RB | 48.14 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0133 | XTL-2500RB | 40.54 |
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0160 | XTL-2500RB | 19.46 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|---|----------|--------------|------------|----------------------|-----------------|
| Waukesha, City | Waukesha City Metro Transit System | Motorola | M21URM9PW2AN | 624CJV0164 | XTL-2500RB | 47.06 |
| | Waukesha City Metro Transit System Total | | | | | 1,750.46 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJD2819 | XTS-5000 Model II FM | 4.73 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJD2816 | XTS-5000 Model II FM | 0.06 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJF0040 | XTS-5000 Model II FM | 0.35 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJD2827 | XTS-5000 Model II FM | 0.91 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJD2232 | XTS-5000 Model II FM | 2.59 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H18UCF9PW6AN | 721CJD2234 | XTS-5000 Model II FM | 3.88 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0182 | XTL-2500RB | 0.54 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0202 | XTL-2500RB | 0.90 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0209 | XTL-2500RB | 0.43 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0195 | XTL-2500RB | 0.59 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0190 | XTL-2500RB | 0.27 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0189 | XTL-2500RB | 1.45 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0186 | XTL-2500RB | 0.60 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0184 | XTL-2500RB | 1.82 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0193 | XTL-2500RB | 2.02 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0199 | XTL-2500RB | 1.55 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0179 | XTL-2500RB | 0.32 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0204 | XTL-2500RB | 0.23 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0205 | XTL-2500RB | 1.33 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0206 | XTL-2500RB | 0.30 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0170 | XTL-2500RB | 1.48 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0172 | XTL-2500RB | 1.91 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0177 | XTL-2500RB | 0.38 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0178 | XTL-2500RB | 1.33 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M21URM9PW2AN | 624CJV0198 | XTL-2500RB | 0.86 |
| | Waukesha City Park and Recreation Department Total | | | | | 30.83 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4902 | MTS-2000 Model I DES | 9.14 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4896 | MTS-2000 Model I | 2.01 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4799 | MTS-2000 Model I | 6.50 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4875 | MTS-2000 Model I | 0.11 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4880 | MTS-2000 Model I | 0.09 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4891 | MTS-2000 Model I | 0.58 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4936 | MTS-2000 Model I | 2.61 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|---------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0053 | XTS-5000 Model II FM | 0.20 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0075 | XTS-5000 Model II FM | 0.62 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0063 | XTS-5000 Model II FM | 59.63 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0062 | XTS-5000 Model II FM | 5.40 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0061 | XTS-5000 Model II FM | 41.95 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0060 | XTS-5000 Model II FM | 52.88 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0059 | XTS-5000 Model II FM | 0.08 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0057 | XTS-5000 Model II FM | 36.49 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0056 | XTS-5000 Model II FM | 9.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0054 | XTS-5000 Model II FM | 39.54 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLV0254 | XTS-5000 Model II | 0.11 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0052 | XTS-5000 Model II FM | 32.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0049 | XTS-5000 Model II FM | 1.25 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0048 | XTS-5000 Model II FM | 1.81 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0047 | XTS-5000 Model II FM | 3.08 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0045 | XTS-5000 Model II FM | 40.68 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0044 | XTS-5000 Model II FM | 2.88 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0055 | XTS-5000 Model II FM | 0.59 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0091 | XTS-5000 Model II FM | 17.19 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3408 | XTS-5000 Model II | 31.09 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3407 | XTS-5000 Model II | 50.85 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3406 | XTS-5000 Model II | 2.42 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3405 | XTS-5000 Model II | 0.09 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3404 | XTS-5000 Model II | 2.95 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3403 | XTS-5000 Model II | 6.07 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3401 | XTS-5000 Model II | 1.23 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3400 | XTS-5000 Model II | 0.27 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0092 | XTS-5000 Model II FM | 2.84 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0076 | XTS-5000 Model II FM | 33.43 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0090 | XTS-5000 Model II FM | 35.14 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0081 | XTS-5000 Model II FM | 47.88 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0088 | XTS-5000 Model II FM | 6.73 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0086 | XTS-5000 Model II FM | 42.66 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0085 | XTS-5000 Model II FM | 40.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0084 | XTS-5000 Model II FM | 8.83 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|---------------------------------|----------|--------------|------------|----------------------|-------|
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0083 | XTS-5000 Model II FM | 1.37 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0089 | XTS-5000 Model II FM | 30.06 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0077 | XTS-5000 Model II FM | 44.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJM3399 | XTS-5000 Model II | 26.08 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0078 | XTS-5000 Model II FM | 34.68 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0080 | XTS-5000 Model II FM | 20.50 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0079 | XTS-5000 Model II FM | 44.67 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2371 | XTS-5000 Model II | 39.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2368 | XTS-5000 Model II | 37.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2372 | XTS-5000 Model II | 3.51 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2370 | XTS-5000 Model II | 2.47 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0438 | XTS-5000 Model II | 53.43 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2369 | XTS-5000 Model II | 55.72 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0439 | XTS-5000 Model II | 2.19 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0441 | XTS-5000 Model II | 5.97 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0442 | XTS-5000 Model II | 81.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0444 | XTS-5000 Model II | 1.97 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0443 | XTS-5000 Model II | 45.13 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2373 | XTS-5000 Model II | 17.27 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0445 | XTS-5000 Model II | 12.28 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0437 | XTS-5000 Model II | 0.55 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0433 | XTS-5000 Model II | 15.46 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0440 | XTS-5000 Model II | 0.23 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0434 | XTS-5000 Model II | 0.87 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0436 | XTS-5000 Model II | 10.65 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2374 | XTS-5000 Model II | 0.09 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2381 | XTS-5000 Model II | 0.28 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2380 | XTS-5000 Model II | 52.55 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2379 | XTS-5000 Model II | 2.98 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2378 | XTS-5000 Model II | 0.84 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2377 | XTS-5000 Model II | 7.37 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2376 | XTS-5000 Model II | 0.37 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CLF2375 | XTS-5000 Model II | 14.96 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CKT0435 | XTS-5000 Model II | 37.83 |
| Waukesha, City | Waukesha City Police Department | Motorola | H98UCF9PW6AN | 481CQP1680 | APX-6000 Model 2.5 | 0.07 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|---------------------------------|----------|--------------|------------|-------------------|----------|
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0571 | MCS-2000 Model I | 0.53 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0569 | MCS-2000 Model I | 3.96 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0572 | MCS-2000 Model I | 1.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UJM6PW6AN | 722AYE2212 | MCS-2000 Model II | 17.65 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0439 | XTL-2500 Mobile | 2,787.60 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0441 | XTL-2500 Mobile | 391.44 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0440 | XTL-2500 Mobile | 1.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0942 | XTL-2500RB | 115.14 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0967 | XTL-2500RB | 3.97 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0968 | XTL-2500RB | 2.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0969 | XTL-2500RB | 7.47 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0970 | XTL-2500RB | 10.59 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0973 | XTL-2500RB | 4.27 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0934 | XTL-2500RB | 0.20 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0935 | XTL-2500RB | 14.73 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0936 | XTL-2500RB | 4.98 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0937 | XTL-2500RB | 16.51 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0938 | XTL-2500RB | 5.30 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0939 | XTL-2500RB | 7.84 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0941 | XTL-2500RB | 21.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0944 | XTL-2500RB | 13.74 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0945 | XTL-2500RB | 1.10 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0946 | XTL-2500RB | 0.33 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0943 | XTL-2500RB | 4.80 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0940 | XTL-2500RB | 2.58 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2510 | APX-6500 Mobile | 40.44 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2504 | APX-6500 Mobile | 79.05 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2507 | APX-6500 Mobile | 187.58 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2516 | APX-6500 Mobile | 9.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2515 | APX-6500 Mobile | 150.25 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2514 | APX-6500 Mobile | 6.15 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2513 | APX-6500 Mobile | 0.25 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2511 | APX-6500 Mobile | 108.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2509 | APX-6500 Mobile | 210.47 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2508 | APX-6500 Mobile | 109.99 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|--|----------|--------------|------------|----------------------|-----------------|
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2502 | APX-6500 Mobile | 172.99 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2503 | APX-6500 Mobile | 27.99 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2512 | APX-6500 Mobile | 51.67 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2494 | APX-6500 Mobile | 191.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2505 | APX-6500 Mobile | 102.05 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2501 | APX-6500 Mobile | 0.20 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2493 | APX-6500 Mobile | 168.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2495 | APX-6500 Mobile | 7.55 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2496 | APX-6500 Mobile | 82.95 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2498 | APX-6500 Mobile | 23.56 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2500 | APX-6500 Mobile | 196.69 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2492 | APX-6500 Mobile | 6.39 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQM2499 | APX-6500 Mobile | 37.89 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQK1982 | APX-6500 Mobile | 33.71 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CRP0924 | APX-6500 Mobile | 4.75 |
| Waukesha, City | Waukesha City Police Department | Motorola | M25URS9PW1AN | 527CQK1981 | APX-6500 Mobile | 109.32 |
| | Waukesha City Police Department Total | | | | | 6,947.72 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0023 | XTS-5000 Model II FM | 35.52 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0039 | XTS-5000 Model II FM | 25.45 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJD2812 | XTS-5000 Model II FM | 0.20 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0034 | XTS-5000 Model II FM | 0.26 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0026 | XTS-5000 Model II FM | 16.01 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJD2815 | XTS-5000 Model II FM | 6.63 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0020 | XTS-5000 Model II FM | 2.19 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJD2808 | XTS-5000 Model II FM | 8.15 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H18UCF9PW6AN | 721CJF0005 | XTS-5000 Model II FM | 0.09 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H98UCF9PW6AN | 481CQM6767 | APX-6000 Model 2.5 | 3.73 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | H98UCF9PW6AN | 481CQM6768 | APX-6000 Model 2.5 | 16.64 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW1AN | 514CMV0427 | XTL-2500 Mobile | 1.02 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0230 | XTL-2500RB | 2.50 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0213 | XTL-2500RB | 0.11 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0237 | XTL-2500RB | 5.84 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0235 | XTL-2500RB | 1.14 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0233 | XTL-2500RB | 0.56 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0231 | XTL-2500RB | 31.47 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|----------------|---------------------------------------|----------|--------------|------------|------------|-------|
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0229 | XTL-2500RB | 2.63 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0228 | XTL-2500RB | 0.57 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0227 | XTL-2500RB | 2.21 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0226 | XTL-2500RB | 4.81 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0225 | XTL-2500RB | 21.41 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0224 | XTL-2500RB | 1.97 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0217 | XTL-2500RB | 0.74 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0211 | XTL-2500RB | 1.43 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0210 | XTL-2500RB | 16.51 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0251 | XTL-2500RB | 1.40 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0222 | XTL-2500RB | 23.89 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0275 | XTL-2500RB | 4.79 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0243 | XTL-2500RB | 1.65 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0255 | XTL-2500RB | 0.22 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0245 | XTL-2500RB | 7.83 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0247 | XTL-2500RB | 1.38 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0249 | XTL-2500RB | 2.12 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0286 | XTL-2500RB | 0.50 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0285 | XTL-2500RB | 2.73 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0284 | XTL-2500RB | 0.94 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0283 | XTL-2500RB | 8.84 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0282 | XTL-2500RB | 1.33 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0281 | XTL-2500RB | 2.56 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0280 | XTL-2500RB | 0.25 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0242 | XTL-2500RB | 7.00 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0278 | XTL-2500RB | 0.14 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0244 | XTL-2500RB | 3.20 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0274 | XTL-2500RB | 3.71 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0271 | XTL-2500RB | 0.12 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0270 | XTL-2500RB | 3.29 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0269 | XTL-2500RB | 1.23 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0268 | XTL-2500RB | 5.64 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0266 | XTL-2500RB | 11.72 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0265 | XTL-2500RB | 4.90 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0263 | XTL-2500RB | 1.11 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|-----------------------------|---|--------------|--------------|-----------------|----------------------|-----------------|
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0262 | XTL-2500RB | 1.74 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0260 | XTL-2500RB | 2.10 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0257 | XTL-2500RB | 1.43 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0256 | XTL-2500RB | 4.89 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0279 | XTL-2500RB | 0.17 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0253 | XTL-2500RB | 4.92 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0241 | XTL-2500RB | 4.33 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0239 | XTL-2500RB | 0.90 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0252 | XTL-2500RB | 0.31 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0250 | XTL-2500RB | 2.55 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M28URS9PW1AN | 775TFS0152 | XTL-1500 Mobile | 1.58 |
| | Waukesha City Public Works Department Total | | | | | 337.20 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | E.F. Johnson | 5170ES | 5170F3811C37557 | 51XX Portable | 0.52 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4811 | MTS-2000 Model I | 3.37 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4802 | MTS-2000 Model I | 3.47 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4801 | MTS-2000 Model I | 0.21 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4806 | MTS-2000 Model I | 3.26 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4815 | MTS-2000 Model I | 0.91 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4996 | MTS-2000 Model I | 0.24 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4803 | MTS-2000 Model I | 0.25 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4818 | MTS-2000 Model I | 2.35 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4824 | MTS-2000 Model I | 0.25 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H01UCD6PW1BN | 466ABE4817 | MTS-2000 Model I | 0.71 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H46UCF9PW6BN | 205CKF4696 | XTS-2500 Model II FM | 7.09 |
| Waukesha, City | Waukesha City Wastewater Treatment Plant | Motorola | H46UCF9PW6BN | 205CKF4695 | XTS-2500 Model II FM | 5.14 |
| | Waukesha City Wastewater Treatment Plant Total | | | | | 27.77 |
| Waukesha, City | Waukesha City Water Utility | Motorola | M21URM9PW2AN | 624CJV0303 | XTL-2500RB | 0.09 |
| | Waukesha City Water Utility Total | | | | | 0.09 |
| Waukesha, City Total | | | | | | 9,746.07 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2969 | MTS-2000 Model I FM | 0.36 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2929 | MTS-2000 Model I FM | 0.16 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466CEG0406 | MTS-2000 Model I FM | 0.05 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466CEG0404 | MTS-2000 Model I FM | 0.11 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2964 | MTS-2000 Model I FM | 0.12 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2937 | MTS-2000 Model I FM | 2.84 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--|--|--------------|-----------------|-----------------|-----------------------|--------------|
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2926 | MTS-2000 Model I FM | 0.10 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2965 | MTS-2000 Model I FM | 4.61 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2947 | MTS-2000 Model I FM | 1.77 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H01UCD6PW1BN | 466ABS2944 | MTS-2000 Model I FM | 0.48 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0030 | APX-7000XE Model 3.5 | 8.93 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0034 | APX-7000XE Model 3.5 | 7.87 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0033 | APX-7000XE Model 3.5 | 8.90 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0031 | APX-7000XE Model 3.5 | 1.39 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0029 | APX-7000XE Model 3.5 | 2.95 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0028 | APX-7000XE Model 3.5 | 0.59 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0027 | APX-7000XE Model 3.5 | 7.55 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0025 | APX-7000XE Model 3.5 | 1.00 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | H49TGD9PW1AN | 562CRD0032 | APX-7000XE Model 3.5 | 1.02 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1461 | MCS-2000 Model II | 10.24 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1452 | MCS-2000 Model II | 1.39 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1454 | MCS-2000 Model II | 1.28 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1448 | MCS-2000 Model II | 5.25 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1425 | MCS-2000 Model II | 0.85 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1456 | MCS-2000 Model II | 4.95 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M01UGM6PW6BN | 722ABS1462 | MCS-2000 Model II | 0.61 |
| Waukesha, Town | Waukesha Town Fire Department | Motorola | M30TSS9PW1AN | 656CRD0059 | APX-7500 Mobile | 21.80 |
| | Waukesha Town Fire Department Total | | | | | 97.17 |
| Waukesha, Town Total | | | | | | 97.17 |
| Wheaton Franciscan Healthcare | Elmbrook Memorial Hospital | Motorola | H46UCF9PW6BN | 205CJZ3593 | XTS-2500 Model II | 0.48 |
| | Elmbrook Memorial Hospital Total | | | | | 0.48 |
| Wheaton Franciscan Healthcare Total | | | | | | 0.48 |
| Wisconsin, State of | Wisconsin State Patrol | E.F. Johnson | 242-527B-840JE6 | 23348 | 51XX Portable | 0.05 |
| Wisconsin, State of | Wisconsin State Patrol | E.F. Johnson | 242-527B-840JE6 | 29052 | 51XX Portable | 0.05 |
| Wisconsin, State of | Wisconsin State Patrol | E.F. Johnson | 2425AACA53QR8 | 513021333020011 | VP900 Model 3 | 6.34 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | H01UCF6PW1BN | 466ABQ3784 | MTS-2000 Model II | 4.40 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | H01UCF6PW1BN | 466ABQ3787 | MTS-2000 Model II | 2.52 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | M01UJN6PW6BN | 722CEA0634 | MCS-2000 | 0.11 |
| Wisconsin, State of | Wisconsin State Patrol | Motorola | M01UJN6PW6BN | 722ABQ1719 | MCS-2000 Control Base | 0.13 |
| | Wisconsin State Patrol Total | | | | | 13.60 |
| Wisconsin, State of Total | | | | | | 13.60 |

**December, 2015
Trunked Radio Usage**

| | | | | | | |
|--------------------|--|--|--|--|--|------------------|
| | | | | | | |
| Grand Total | | | | | | 53,672.25 |