

**September, 2008  
Trunked Radio Usage**

| Parent agency                           | Department                                   | Make     | Model Number | Serial Number | Type            | Airtime Minutes |
|---|--|----------|--------------|---------------|-----------------|-----------------|
| Ashippun Fire Department                | Ashippun Fire Department                     | Motorola | H01UCF6PW1BN | 466ABW4180    | MTS-2000 Mode   | 1.38            |
|   | <b>Ashippun Fire Department Total</b>        |          |              |               |                 | <b>1.38</b>     |
| <b>Ashippun Fire Department Total</b>   |  |          |              |               |                 | <b>1.38</b>     |
| Big Bend                                | Big Bend Police Department                   | Motorola | M21URM9PW2AN | 624CJP0976    | XTL-2500RB      | 1.32            |
|   | <b>Big Bend Police Department Total</b>      |          |              |               |                 | <b>1.32</b>     |
| <b>Big Bend Total</b>                   |  |          |              |               |                 | <b>1.32</b>     |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2312    | MTS-2000 Mode   | 1.1             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2295    | MTS-2000 Mode   | 1.3             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2315    | MTS-2000 Mode   | 2.06            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2327    | MTS-2000 Mode   | 2.14            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE4920    | MTS-2000 Mode   | 2.34            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE5013    | MTS-2000 Mode   | 3.68            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2294    | MTS-2000 Mode   | 4.3             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2287    | MTS-2000 Mode   | 4.54            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2297    | MTS-2000 Mode   | 4.8             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2325    | MTS-2000 Mode   | 5.62            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE4930    | MTS-2000 Mode   | 8.72            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCD6PW1BN | 466ABE2299    | MTS-2000 Mode   | 9.36            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | H01UCH6PW1BN | 466AAE3942    | MTS-2000 Mode   | 3.4             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0824    | XTL-2500RB      | 3.26            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0817    | XTL-2500RB      | 3.26            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0825    | XTL-2500RB      | 4.52            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0829    | XTL-2500RB      | 6.54            |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0815    | XTL-2500RB      | 7.6             |
| Big Bend/Vernon Fire Dept.              | Big Bend/Vernon Fire Department              | Motorola | M21URM9PW2AN | 624CJK0827    | XTL-2500RB      | 8.18            |
|   | <b>Big Bend/Vernon Fire Department Total</b> |          |              |               |                 | <b>86.72</b>    |
| <b>Big Bend/Vernon Fire Dept. Total</b> |  |          |              |               |                 | <b>86.72</b>    |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678sby7423    | LTS-2000 w/o sc | 1.1             |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX61    | LTS-2000 w/o sc | 4.36            |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYEB67    | LTS-2000 w/o sc | 4.46            |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX09    | LTS-2000 w/o sc | 6.54            |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX62    | LTS-2000 w/o sc | 7.32            |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX55    | LTS-2000 w/o sc | 12.08           |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX07    | LTS-2000 w/o sc | 13.56           |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SEW0629    | LTS-2000 w/o sc | 22.26           |
| Brookfield, City                        | Brookfield City Engineering Department       | Motorola | H10UCH6DC5BN | 678SAYDX22    | LTS-2000 w/o sc | 63.2            |

## September, 2008 Trunked Radio Usage

|                  |   |          |              |            |               |               |
|------------------|---|----------|--------------|------------|---------------|---------------|
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0559 | XTS-2500 Mode | 1.1           |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0557 | XTS-2500 Mode | 4.36          |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0548 | XTS-2500 Mode | 4.46          |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0555 | XTS-2500 Mode | 6.54          |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0558 | XTS-2500 Mode | 7.32          |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0556 | XTS-2500 Mode | 12.08         |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0553 | XTS-2500 Mode | 13.56         |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0560 | XTS-2500 Mode | 22.26         |
| Brookfield, City | Brookfield City Engineering Department              | Motorola | H46UCF9PW6BN | 205CJF0551 | XTS-2500 Mode | 63.2          |
|                  | <b>Brookfield City Engineering Department Total</b> |          |              |            |               | <b>269.76</b> |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1914 | MTS-2000 Mode | 1.06          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1874 | MTS-2000 Mode | 1.08          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1881 | MTS-2000 Mode | 1.08          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1888 | MTS-2000 Mode | 1.1           |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1905 | MTS-2000 Mode | 1.1           |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABQ0728 | MTS-2000 Mode | 1.16          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABQ0727 | MTS-2000 Mode | 1.28          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABQ0731 | MTS-2000 Mode | 1.3           |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1867 | MTS-2000 Mode | 1.38          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABQ0735 | MTS-2000 Mode | 2.6           |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1898 | MTS-2000 Mode | 3.68          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1908 | MTS-2000 Mode | 4.56          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1895 | MTS-2000 Mode | 12.34         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1894 | MTS-2000 Mode | 12.56         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1907 | MTS-2000 Mode | 13.8          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1890 | MTS-2000 Mode | 21.04         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGL6PW4BN | 722ABJ0514 | MCS-2000 Mode | 20.36         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1314 | MCS-2000 Mode | 2.38          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1287 | MCS-2000 Mode | 3.14          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1292 | MCS-2000 Mode | 9.16          |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1294 | MCS-2000 Mode | 22.56         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1296 | MCS-2000 Mode | 35.06         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1302 | MCS-2000 Mode | 40.24         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1289 | MCS-2000 Mode | 49.56         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1291 | MCS-2000 Mode | 59.92         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UGM6PW6BN | 722ABE1301 | MCS-2000 Mode | 62.34         |
| Brookfield, City | Brookfield City Fire Department                     | Motorola | M01UJM6PW6BN | 722CDC0319 | MCS-2000 Mode | 25.12         |

**September, 2008  
Trunked Radio Usage**

|                  |  |          |              |            |                 |               |
|------------------|--|----------|--------------|------------|-----------------|---------------|
|                  | <b>Brookfield City Fire Department Total</b> |          |              |            |                 | <b>410.96</b> |
| Brookfield, City | Brookfield City Fleet Division               | Motorola | M10UGD6DC5BN | 760SCL0539 | LCS-2000 w/sca  | 2.02          |
|                  | <b>Brookfield City Fleet Division Total</b>  |          |              |            |                 | <b>2.02</b>   |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDX13 | LTS-2000 w/o sc | 1.48          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDX59 | LTS-2000 w/o sc | 1.54          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDY41 | LTS-2000 w/o sc | 2.4           |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAW1556 | LTS-2000 w/o sc | 4.16          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDW44 | LTS-2000 w/o sc | 5.04          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDX52 | LTS-2000 w/o sc | 7.02          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAW2319 | LTS-2000 w/o sc | 8.44          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H10UCH6DC5BN | 678SAYDX65 | LTS-2000 w/o sc | 12.14         |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0583 | XTS-2500 Mode   | 1.48          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0580 | XTS-2500 Mode   | 1.54          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0589 | XTS-2500 Mode   | 2.4           |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0592 | XTS-2500 Mode   | 4.16          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0587 | XTS-2500 Mode   | 5.04          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0581 | XTS-2500 Mode   | 7.02          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0590 | XTS-2500 Mode   | 8.44          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | H46UCF9PW6BN | 205CJF0595 | XTS-2500 Mode   | 12.14         |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFF35 | LCS-2000 w/o sc | 1.02          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFG77 | LCS-2000 w/o sc | 1.06          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFF34 | LCS-2000 w/o sc | 1.08          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SBA0435 | LCS-2000 w/o sc | 1.12          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFJ36 | LCS-2000 w/o sc | 1.24          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFF57 | LCS-2000 w/o sc | 1.28          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SBA0434 | LCS-2000 w/o sc | 1.28          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFB73 | LCS-2000 w/o sc | 1.36          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ93 | LCS-2000 w/o sc | 2.04          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ19 | LCS-2000 w/o sc | 2.2           |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFA39 | LCS-2000 w/o sc | 2.3           |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ70 | LCS-2000 w/o sc | 2.34          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFC13 | LCS-2000 w/o sc | 2.36          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ12 | LCS-2000 w/o sc | 2.38          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ23 | LCS-2000 w/o sc | 3.04          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYFC06 | LCS-2000 w/o sc | 3.06          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ26 | LCS-2000 w/o sc | 3.14          |
| Brookfield, City | Brookfield City Highway Department           | Motorola | M10UGD6DC5BN | 760SAYEZ43 | LCS-2000 w/o sc | 3.3           |

**September, 2008  
Trunked Radio Usage**

|                  |  |          |              |            |                 |               |
|------------------|--|----------|--------------|------------|-----------------|---------------|
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYEZ18 | LCS-2000 w/o sc | 3.5           |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYFF60 | LCS-2000 w/o sc | 3.54          |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYFB95 | LCS-2000 w/o sc | 4.04          |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYFA47 | LCS-2000 w/o sc | 4.26          |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYEZ61 | LCS-2000 w/o sc | 4.52          |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYFA52 | LCS-2000 w/o sc | 6.18          |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SAYFG07 | LCS-2000 w/o sc | 12.22         |
| Brookfield, City | Brookfield City Highway Department                           | Motorola | M10UGD6DC5BN | 760SBA0423 | LCS-2000 w/o sc | 13.42         |
|                  | <b>Brookfield City Highway Department Total</b>              |          |              |            |                 | <b>171.72</b> |
| Brookfield, City | Brookfield City Inspection Services                          | Motorola | H10UCH6DC5BN | 678SAYDV93 | LTS-2000 w/o sc | 8.42          |
| Brookfield, City | Brookfield City Inspection Services                          | Motorola | H46UCF9PW6BN | 205CJF0486 | XTS-2500 Mode   | 8.42          |
| Brookfield, City | Brookfield City Inspection Services                          | Motorola | M10UGD6DC5BN | 760SAYFB64 | LCS-2000 w/o sc | 2.16          |
|                  | <b>Brookfield City Inspection Services Total</b>             |          |              |            |                 | <b>19</b>     |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H10UCH6DC5BN | 678SAYDX19 | LTS-2000 w/o sc | 1.08          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H10UCH6DC5BN | 678SAW2408 | LTS-2000 w/o sc | 9.1           |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H10UCH6DC5BN | 678SAYDX04 | LTS-2000 w/o sc | 12.52         |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H46UCF9PW6BN | 205CJF0565 | XTS-2500 Mode   | 1.08          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H46UCF9PW6BN | 205CJF0561 | XTS-2500 Mode   | 9.1           |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | H46UCF9PW6BN | 205CJF0564 | XTS-2500 Mode   | 12.52         |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFF83 | LCS-2000 w/o sc | 1.28          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFE62 | LCS-2000 w/o sc | 2.18          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYEY94 | LCS-2000 w/o sc | 2.58          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFD11 | LCS-2000 w/o sc | 4.06          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFF06 | LCS-2000 w/o sc | 4.1           |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFD12 | LCS-2000 w/o sc | 5.48          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFF48 | LCS-2000 w/o sc | 6.32          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFC74 | LCS-2000 w/o sc | 7.24          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFC76 | LCS-2000 w/o sc | 7.34          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYEY60 | LCS-2000 w/o sc | 9.46          |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYEZ51 | LCS-2000 w/o sc | 10            |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYEY62 | LCS-2000 w/o sc | 10            |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYFD14 | LCS-2000 w/o sc | 10.24         |
| Brookfield, City | Brookfield City Parks and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAYEZ98 | LCS-2000 w/o sc | 10.52         |
|                  | <b>Brookfield City Parks and Recreation Department Total</b> |          |              |            |                 | <b>136.2</b>  |
| Brookfield, City | Brookfield City Police Department                            | Motorola | H01UCF6PW1BN | 466ABE1850 | MTS-2000 Mode   | 1.04          |
| Brookfield, City | Brookfield City Police Department                            | Motorola | H01UCF6PW1BN | 466ABE1830 | MTS-2000 Mode   | 1.16          |
| Brookfield, City | Brookfield City Police Department                            | Motorola | H01UCF6PW1BN | 466ABE1816 | MTS-2000 Mode   | 1.2           |

## September, 2008 Trunked Radio Usage

|                  |                                   |          |              |            |               |       |
|------------------|-----------------------------------|----------|--------------|------------|---------------|-------|
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1846 | MTS-2000 Mode | 1.34  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1857 | MTS-2000 Mode | 1.4   |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1818 | MTS-2000 Mode | 2.52  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1822 | MTS-2000 Mode | 3.18  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1827 | MTS-2000 Mode | 4.2   |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1825 | MTS-2000 Mode | 4.66  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1838 | MTS-2000 Mode | 7.36  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1837 | MTS-2000 Mode | 9.02  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1835 | MTS-2000 Mode | 9.5   |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1861 | MTS-2000 Mode | 9.5   |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1853 | MTS-2000 Mode | 15.04 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1849 | MTS-2000 Mode | 15.48 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1856 | MTS-2000 Mode | 16.16 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1843 | MTS-2000 Mode | 16.56 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1855 | MTS-2000 Mode | 17.26 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1836 | MTS-2000 Mode | 17.3  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1823 | MTS-2000 Mode | 19.76 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1841 | MTS-2000 Mode | 21.14 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1821 | MTS-2000 Mode | 26.06 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1854 | MTS-2000 Mode | 26.24 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1845 | MTS-2000 Mode | 26.48 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1813 | MTS-2000 Mode | 26.54 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1859 | MTS-2000 Mode | 29.34 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1848 | MTS-2000 Mode | 32.08 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1833 | MTS-2000 Mode | 40.44 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1832 | MTS-2000 Mode | 40.66 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1820 | MTS-2000 Mode | 41.5  |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1829 | MTS-2000 Mode | 41.58 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1819 | MTS-2000 Mode | 45.22 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1824 | MTS-2000 Mode | 49.88 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1815 | MTS-2000 Mode | 53.14 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1831 | MTS-2000 Mode | 55.32 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1842 | MTS-2000 Mode | 56.18 |
| Brookfield, City | Brookfield City Police Department | Motorola | H01UCF6PW1BN | 466ABE1817 | MTS-2000 Mode | 56.18 |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1326 | MCS-2000 Mode | 1.14  |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1347 | MCS-2000 Mode | 2.38  |
| Brookfield, City | Brookfield City Police Department | Motorola | M01UGM6PW6BN | 722ABE1323 | MCS-2000 Mode | 3.18  |

## September, 2008 Trunked Radio Usage

|                  |  |          |              |            |                 |                |
|------------------|--|----------|--------------|------------|-----------------|----------------|
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1349 | MCS-2000 Mode   | 3.32           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1324 | MCS-2000 Mode   | 4.44           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1340 | MCS-2000 Mode   | 5.48           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1269 | MCS-2000 Mode   | 6.18           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1327 | MCS-2000 Mode   | 9.12           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1350 | MCS-2000 Mode   | 13.22          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1338 | MCS-2000 Mode   | 16.22          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1322 | MCS-2000 Mode   | 17.48          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1333 | MCS-2000 Mode   | 52.6           |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1348 | MCS-2000 Mode   | 78.72          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1328 | MCS-2000 Mode   | 95.42          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1332 | MCS-2000 Mode   | 101.1          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGm6PW6BN | 722ABJ0546 | MCS-2000 Mode   | 101.48         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1335 | MCS-2000 Mode   | 105.34         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1330 | MCS-2000 Mode   | 108.44         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1329 | MCS-2000 Mode   | 112.6          |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1319 | MCS-2000 Mode   | 117.98         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1339 | MCS-2000 Mode   | 134.08         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1321 | MCS-2000 Mode   | 135.68         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1336 | MCS-2000 Mode   | 140.12         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1297 | MCS-2000 Mode   | 147.72         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1331 | MCS-2000 Mode   | 181.18         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1320 | MCS-2000 Mode   | 183.56         |
| Brookfield, City | Brookfield City Police Department              | Motorola | M01UGM6PW6BN | 722ABE1353 | MCS-2000 Mode   | 200.72         |
|                  | <b>Brookfield City Police Department Total</b> |          |              |            |                 | <b>2920.52</b> |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H10UCH6DC5BN | 678SAYDX18 | LTS-2000 w/o sc | 2.52           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H10UCH6DC5BN | 678SAYDX83 | LTS-2000 w/o sc | 3.42           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H10UCH6DC5BN | 678SAYDX96 | LTS-2000 w/o sc | 9.3            |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H46UCF9PW6BN | 205CJF0542 | XTS-2500 Mode   | 2.52           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H46UCF9PW6BN | 205CJF0541 | XTS-2500 Mode   | 3.42           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | H46UCF9PW6BN | 205CJF0538 | XTS-2500 Mode   | 9.3            |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYEZ42 | LCS-2000 w/o sc | 1.22           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYFD09 | LCS-2000 w/o sc | 1.34           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYFC69 | LCS-2000 w/o sc | 1.58           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYFC75 | LCS-2000 w/o sc | 2.58           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYEZ45 | LCS-2000 w/o sc | 4.06           |
| Brookfield, City | Brookfield City Sewer Utility                  | Motorola | M10UGD6DC5BN | 760SAYEZ41 | LCS-2000 w/o sc | 8.1            |

## September, 2008 Trunked Radio Usage

|                  |  |          |              |            |                 |               |
|------------------|--|----------|--------------|------------|-----------------|---------------|
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M10UGD6DC5BN | 760SAYFD10 | LCS-2000 w/o sc | 13.08         |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M10UGD6DC5BN | 760SAYFG83 | LCS-2000 w/o sc | 20.32         |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0323 | XTL-2500RB      | 1.22          |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0317 | XTL-2500RB      | 1.34          |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0320 | XTL-2500RB      | 1.58          |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0315 | XTL-2500RB      | 2.58          |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0319 | XTL-2500RB      | 4.06          |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0322 | XTL-2500RB      | 8.1           |
| Brookfield, City | Brookfield City Sewer Utility              | Motorola | M21URM9PW2AN | 624CJV0316 | XTL-2500RB      | 13.08         |
|                  | <b>Brookfield City Sewer Utility Total</b> |          |              |            |                 | <b>114.72</b> |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0828 | LTS-2000 w/o sc | 1.22          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SAYDX12 | LTS-2000 w/o sc | 1.46          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0831 | LTS-2000 w/o sc | 6.56          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0832 | LTS-2000 w/o sc | 11.44         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0822 | LTS-2000 w/o sc | 12.44         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0827 | LTS-2000 w/o sc | 13.18         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SAYDY42 | LTS-2000 w/o sc | 15.2          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0837 | LTS-2000 w/o sc | 15.28         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0835 | LTS-2000 w/o sc | 15.36         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0845 | LTS-2000 w/o sc | 17.42         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0857 | LTS-2000 w/o sc | 23.32         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0830 | LTS-2000 w/o sc | 39.52         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SAW1552 | LTS-2000 w/o sc | 54.2          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H10UCH6DC5BN | 678SBE0850 | LTS-2000 w/o sc | 58.52         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0608 | XTS-2500 Mode   | 1.22          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0616 | XTS-2500 Mode   | 1.46          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0612 | XTS-2500 Mode   | 6.56          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0613 | XTS-2500 Mode   | 11.44         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0607 | XTS-2500 Mode   | 12.44         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0610 | XTS-2500 Mode   | 13.18         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0615 | XTS-2500 Mode   | 15.2          |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0611 | XTS-2500 Mode   | 15.28         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0602 | XTS-2500 Mode   | 15.36         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0605 | XTS-2500 Mode   | 17.42         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0603 | XTS-2500 Mode   | 23.32         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0606 | XTS-2500 Mode   | 39.52         |
| Brookfield, City | Brookfield City Water Utility              | Motorola | H46UCF9PW6BN | 205CJF0617 | XTS-2500 Mode   | 54.2          |

## September, 2008 Trunked Radio Usage

|                               |  |          |              |            |                 |                |
|-------------------------------|--|----------|--------------|------------|-----------------|----------------|
| Brookfield, City              | Brookfield City Water Utility                | Motorola | H46UCF9PW6BN | 205CJF0604 | XTS-2500 Mode   | 58.52          |
| Brookfield, City              | Brookfield City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYFB90 | LCS-2000 w/o sc | 12.02          |
|                               | <b>Brookfield City Water Utility Total</b>   |          |              |            |                 | <b>582.26</b>  |
| <b>Brookfield, City Total</b> |  |          |              |            |                 | <b>4627.16</b> |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3227 | MTS-2000 Mode   | 1.28           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3197 | MTS-2000 Mode   | 1.3            |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3158 | MTS-2000 Mode   | 1.58           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3208 | MTS-2000 Mode   | 2.24           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3210 | MTS-2000 Mode   | 4.82           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | H01UCF6PW1BN | 466abl3209 | MTS-2000 Mode   | 18.1           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1299 | MCS-2000 Mode   | 1.14           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1327 | MCS-2000 Mode   | 1.26           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1309 | MCS-2000 Mode   | 2.76           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1389 | MCS-2000 Mode   | 4.28           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722AWL1066 | MCS-2000 Mode   | 4.58           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1341 | MCS-2000 Mode   | 6.38           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1388 | MCS-2000 Mode   | 8.04           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722AWL1097 | MCS-2000 Mode   | 37.2           |
| Brookfield, Town              | Brookfield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1332 | MCS-2000 Mode   | 44.38          |
|                               | <b>Brookfield Town Fire Department Total</b> |          |              |            |                 | <b>139.34</b>  |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3234 | MTS-2000 Mode   | 1.38           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3230 | MTS-2000 Mode   | 2.16           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3244 | MTS-2000 Mode   | 2.48           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3222 | MTS-2000 Mode   | 4.14           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3218 | MTS-2000 Mode   | 6              |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3229 | MTS-2000 Mode   | 6.5            |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3242 | MTS-2000 Mode   | 8.54           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3217 | MTS-2000 Mode   | 9.58           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3235 | MTS-2000 Mode   | 16.3           |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3231 | MTS-2000 Mode   | 16.38          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3226 | MTS-2000 Mode   | 16.46          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3243 | MTS-2000 Mode   | 17.44          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3224 | MTS-2000 Mode   | 21.84          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3237 | MTS-2000 Mode   | 21.92          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3215 | MTS-2000 Mode   | 22.44          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3241 | MTS-2000 Mode   | 24.88          |
| Brookfield, Town              | Brookfield Town Police Department            | Motorola | H01UCF6PW1BN | 466abl3216 | MTS-2000 Mode   | 36.46          |

## September, 2008 Trunked Radio Usage

|                               |  |          |              |            |                 |               |
|-------------------------------|--|----------|--------------|------------|-----------------|---------------|
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | H18UCF9PW6AN | 721CEG0202 | XTS-5000 Mode   | 23.52         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1336 | MCS-2000 Mode   | 1.2           |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | m01ugm6pw6bn | 722abl1329 | MCS-2000 Mode   | 18.66         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1335 | MCS-2000 Mode   | 45.66         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1317 | MCS-2000 Mode   | 60.46         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1333 | MCS-2000 Mode   | 69.34         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1343 | MCS-2000 Mode   | 151.9         |
| Brookfield, Town              | Brookfield Town Police Department              | Motorola | M01UGM6PW6BN | 722abl1321 | MCS-2000 Mode   | 248.66        |
|                               | <b>Brookfield Town Police Department Total</b> |          |              |            |                 | <b>854.3</b>  |
| <b>Brookfield, Town Total</b> |  |          |              |            |                 | <b>993.64</b> |
| Butler                        | Butler Fire Department                         | Motorola | H01UCF6PW1BN | 466cdc1981 | MTS-2000 Mode   | 1.16          |
| Butler                        | Butler Fire Department                         | Motorola | H01UCF6PW1BN | 466cdc1983 | MTS-2000 Mode   | 1.22          |
| Butler                        | Butler Fire Department                         | Motorola | H01UCF6PW1BN | 466cen0314 | MTS-2000 Mode   | 8.16          |
| Butler                        | Butler Fire Department                         | Motorola | H18UCF9PW6AN | 721CFV1371 | XTS-5000 Mode   | 1.28          |
| Butler                        | Butler Fire Department                         | Motorola | H18UCF9PW6AN | 721CFV1383 | XTS-5000 Mode   | 6.58          |
| Butler                        | Butler Fire Department                         | Motorola | H18UCF9PW6AN | 721CFV1384 | XTS-5000 Mode   | 7.4           |
| Butler                        | Butler Fire Department                         | Motorola | H18UCF9PW6AN | 721CFV1382 | XTS-5000 Mode   | 8.6           |
| Butler                        | Butler Fire Department                         | Motorola | H18UCF9PW6AN | 721CFV1376 | XTS-5000 Mode   | 19.62         |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0356 | MCS-2000 Mode   | 2.44          |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0352 | MCS-2000 Mode   | 2.56          |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0351 | MCS-2000 Mode   | 4.04          |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0357 | MCS-2000 Mode   | 4.2           |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0350 | MCS-2000 Mode   | 4.88          |
| Butler                        | Butler Fire Department                         | Motorola | M01UGM6PW6BN | 722cen0354 | MCS-2000 Mode   | 11.1          |
|                               | <b>Butler Fire Department Total</b>            |          |              |            |                 | <b>83.24</b>  |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0348 | MTS-2000 Mode   | 9.8           |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0350 | MTS-2000 Mode   | 11            |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0347 | MTS-2000 Mode   | 12.66         |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0353 | MTS-2000 Mode   | 12.92         |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0354 | MTS-2000 Mode   | 13.6          |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0351 | MTS-2000 Mode   | 18.82         |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0349 | MTS-2000 Mode   | 20.68         |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0346 | MTS-2000 Mode   | 23.88         |
| Butler                        | Butler Police Department                       | Motorola | H01UCF6PW1BN | 466CEN0355 | MTS-2000 Mode   | 27.48         |
| Butler                        | Butler Police Department                       | Motorola | M01UGM6PW6BN | 722CEN0540 | MCS-2000 Mode   | 73.32         |
| Butler                        | Butler Police Department                       | Motorola | M01UGM6PW6BN | 722CEN0539 | MCS-2000 Mode   | 167.2         |
| Butler                        | Butler Police Department                       | Motorola | M20URS9PW1AN | 500CFX2015 | XTL-5000 Mobile | 34.3          |

**September, 2008  
Trunked Radio Usage**

|  |   |          |              |            |                 |               |
|--|---|----------|--------------|------------|-----------------|---------------|
|  | <b>Butler Police Department Total</b>                     |          |              |            |                 | <b>425.66</b> |
| <b>Butler Total</b>                      |   |          |              |            |                 | <b>508.9</b>  |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE4989 | MTS-2000 Mode   | 1.14          |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE4840 | MTS-2000 Mode   | 1.4           |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE4836 | MTS-2000 Mode   | 1.4           |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE5016 | MTS-2000 Mode   | 3.2           |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE5018 | MTS-2000 Mode   | 4.14          |
| Chenequa                                 | Chenequa Village Fire Department                          | Motorola | H01UCD6PW1BN | 466ABE5015 | MTS-2000 Mode   | 8.7           |
|  | <b>Chenequa Village Fire Department Total</b>             |          |              |            |                 | <b>19.98</b>  |
| Chenequa                                 | Chenequa Village Highway/Forestry Department              | Motorola | H01UCF6PW1BN | 466ABW5371 | MTS-2000 Mode   | 7.6           |
| Chenequa                                 | Chenequa Village Highway/Forestry Department              | Motorola | H01UCF6PW1BN | 466ABW4506 | MTS-2000 Mode   | 24.5          |
|  | <b>Chenequa Village Highway/Forestry Department Total</b> |          |              |            |                 | <b>32.1</b>   |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | H01UCD6PW1BN | 466ABE4839 | MTS-2000 Mode   | 2.04          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | H01UCD6PW1BN | 466ABE4894 | MTS-2000 Mode   | 2.38          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | H01UCD6PW1BN | 466ABE4903 | MTS-2000 Mode   | 3.1           |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | H01UCD6PW1BN | 466ABE4905 | MTS-2000 Mode   | 5.34          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | H01UCD6PW1BN | 466ABE4906 | MTS-2000 Mode   | 24.06         |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M01UGM6PW6AN | 722AWE1231 | MCS-2000 Mode   | 33.88         |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M01UGM6PW6BN | 722ABS1412 | MCS-2000 Mode   | 1.12          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M01UGM6PW6BN | 722ABS1405 | MCS-2000 Mode   | 15.74         |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M01UGM6PW6BN | 722ABS1390 | MCS-2000 Mode   | 37.62         |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M10UGD6DC5BN | 760SBQ0081 | LCS-2000 w/sca  | 5.12          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M10UGD6DC5BN | 760SBQ0031 | LCS-2000 w/sca  | 15.9          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M20URS9PW1AN | 500CJH1067 | XTL-5000 Mobile | 5.12          |
| Chenequa                                 | Chenequa Village Police Department                        | Motorola | M20URS9PW1AN | 500CJH1068 | XTL-5000 Mobile | 15.9          |
|  | <b>Chenequa Village Police Department Total</b>           |          |              |            |                 | <b>167.32</b> |
| <b>Chenequa Total</b>                    |   |          |              |            |                 | <b>219.4</b>  |
| Community Memorial Hospital              | Community Memorial Hospital                               | Motorola | L04UJH9PW9AN | 761CEW0110 | Base, low power | 14.42         |
|  | <b>Community Memorial Hospital Total</b>                  |          |              |            |                 | <b>14.42</b>  |
| <b>Community Memorial Hospital Total</b> |   |          |              |            |                 | <b>14.42</b>  |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS2959 | MTS-2000 Mode   | 1.16          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS2957 | MTS-2000 Mode   | 1.56          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466abs3067 | MTS-2000 Mode   | 2.28          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS2939 | MTS-2000 Mode   | 2.36          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS2966 | MTS-2000 Mode   | 2.48          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS2945 | MTS-2000 Mode   | 2.48          |
| Delafield, City                          | Delafield City Fire Department                            | Motorola | H01UCD6PW1BN | 466ABS3049 | MTS-2000 Mode   | 3.2           |

## September, 2008 Trunked Radio Usage

|                 |   |          |              |            |               |               |
|-----------------|---|----------|--------------|------------|---------------|---------------|
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2941 | MTS-2000 Mode | 3.5           |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2950 | MTS-2000 Mode | 4.16          |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2955 | MTS-2000 Mode | 4.3           |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2960 | MTS-2000 Mode | 6.28          |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2961 | MTS-2000 Mode | 6.5           |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2952 | MTS-2000 Mode | 6.96          |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2967 | MTS-2000 Mode | 8.12          |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2938 | MTS-2000 Mode | 9.44          |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2948 | MTS-2000 Mode | 11.72         |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2936 | MTS-2000 Mode | 15.28         |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2953 | MTS-2000 Mode | 17.68         |
| Delafield, City | Delafield City Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2956 | MTS-2000 Mode | 25.7          |
| Delafield, City | Delafield City Fire Department              | Motorola | H46UCF9PW6AN | 205CFT2726 | XTS-2500 Mode | 22.18         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2489 | MCS-2000 Mode | 1.16          |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2347 | MCS-2000 Mode | 2.38          |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE3128 | MCS-2000 Mode | 3.6           |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2790 | MCS-2000 Mode | 9.4           |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2312 | MCS-2000 Mode | 12.62         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2378 | MCS-2000 Mode | 13.62         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE3127 | MCS-2000 Mode | 16.24         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2793 | MCS-2000 Mode | 18.5          |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2314 | MCS-2000 Mode | 23.96         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2802 | MCS-2000 Mode | 24.88         |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2803 | MCS-2000 Mode | 36.3          |
| Delafield, City | Delafield City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2396 | MCS-2000 Mode | 41.46         |
|                 | <b>Delafield City Fire Department Total</b> |          |              |            |               | <b>361.46</b> |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4843 | MTS-2000 Mode | 1.58          |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4822 | MTS-2000 Mode | 3.76          |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4886 | MTS-2000 Mode | 9.6           |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4833 | MTS-2000 Mode | 10.3          |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABS2925 | MTS-2000 Mode | 10.96         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4832 | MTS-2000 Mode | 11.18         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4864 | MTS-2000 Mode | 12.18         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4852 | MTS-2000 Mode | 20.52         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4862 | MTS-2000 Mode | 22.92         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4855 | MTS-2000 Mode | 23.94         |
| Delafield, City | Delafield City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4884 | MTS-2000 Mode | 26.12         |

## September, 2008 Trunked Radio Usage

|                              |   |          |              |            |               |                |
|------------------------------|---|----------|--------------|------------|---------------|----------------|
| Delafield, City              | Delafield City Police Department                    | Motorola | H01UCD6PW1BN | 466ABE4881 | MTS-2000 Mode | 26.44          |
| Delafield, City              | Delafield City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2924 | MTS-2000 Mode | 58.6           |
| Delafield, City              | Delafield City Police Department                    | Motorola | H46UCF9PW6BN | 205CGV2123 | XTS-2500 Mode | 12.8           |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE2799 | MCS-2000 Mode | 8.94           |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE2389 | MCS-2000 Mode | 13.88          |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE2783 | MCS-2000 Mode | 37.12          |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE3122 | MCS-2000 Mode | 93.32          |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE2187 | MCS-2000 Mode | 103.52         |
| Delafield, City              | Delafield City Police Department                    | Motorola | M01UJM6PW6AN | 722AYE2504 | MCS-2000 Mode | 129.84         |
|                              | <b>Delafield City Police Department Total</b>       |          |              |            |               | <b>637.52</b>  |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UGM6PW6AN | 722AWC0024 | MCS-2000 Mode | 3.44           |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE2393 | MCS-2000 Mode | 1.02           |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE3120 | MCS-2000 Mode | 1.14           |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE3126 | MCS-2000 Mode | 1.18           |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE2796 | MCS-2000 Mode | 1.48           |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE3123 | MCS-2000 Mode | 2.1            |
| Delafield, City              | Delafield City Public Works Department              | Motorola | M01UJM6PW6AN | 722AYE3119 | MCS-2000 Mode | 3.22           |
|                              | <b>Delafield City Public Works Department Total</b> |          |              |            |               | <b>13.58</b>   |
| <b>Delafield, City Total</b> |   |          |              |            |               | <b>1012.56</b> |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3176 | MTS-2000 Mode | 1.02           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3152 | MTS-2000 Mode | 1.1            |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3148 | MTS-2000 Mode | 1.28           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466CDY1358 | MTS-2000 Mode | 3.14           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466CEY0365 | MTS-2000 Mode | 3.4            |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3172 | MTS-2000 Mode | 3.78           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3150 | MTS-2000 Mode | 3.8            |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3185 | MTS-2000 Mode | 4.12           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3149 | MTS-2000 Mode | 5.48           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3151 | MTS-2000 Mode | 6.12           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3168 | MTS-2000 Mode | 7.94           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3163 | MTS-2000 Mode | 11.08          |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3179 | MTS-2000 Mode | 27.02          |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | H01UCF6PW1BN | 466ABL3186 | MTS-2000 Mode | 39.66          |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | M01UGM6PW6BN | 722ABL1390 | MCS-2000 Mode | 3.04           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | M01UGM6PW6BN | 722ABL1387 | MCS-2000 Mode | 4.74           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | M01UGM6PW6BN | 722ABL1320 | MCS-2000 Mode | 6.16           |
| Delafield, Town              | Delafield Town Fire Department                      | Motorola | M01UGM6PW6BN | 722ABL1381 | MCS-2000 Mode | 7.24           |

## September, 2008 Trunked Radio Usage

|                                      |   |          |              |            |               |               |
|--------------------------------------|---|----------|--------------|------------|---------------|---------------|
| Delafield, Town                      | Delafield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1386 | MCS-2000 Mode | 7.46          |
| Delafield, Town                      | Delafield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1382 | MCS-2000 Mode | 9.6           |
| Delafield, Town                      | Delafield Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1391 | MCS-2000 Mode | 22.86         |
|                                      | <b>Delafield Town Fire Department Total</b> |          |              |            |               | <b>180.04</b> |
| <b>Delafield, Town Total</b>         |   |          |              |            |               | <b>180.04</b> |
| Dousman                              | Dousman Police Department                   | Motorola | H01UCD6PW1BN | 466ABE1383 | MTS-2000 Mode | 2.24          |
| Dousman                              | Dousman Police Department                   | Motorola | H01UCF6PW1BN | 466ABW4235 | MTS-2000 Mode | 1.38          |
| Dousman                              | Dousman Police Department                   | Motorola | H18UCF9PW6AN | 721CEA4982 | XTS-5000 Mode | 6.16          |
| Dousman                              | Dousman Police Department                   | Motorola | H18UCF9PW6AN | 721CEA4981 | XTS-5000 Mode | 8.2           |
| Dousman                              | Dousman Police Department                   | Motorola | M01UGM6PW6BN | 722ABS1449 | MCS-2000 Mode | 15.42         |
| Dousman                              | Dousman Police Department                   | Motorola | M01UGM6PW6BN | 722ABS1415 | MCS-2000 Mode | 27.32         |
|                                      | <b>Dousman Police Department Total</b>      |          |              |            |               | <b>60.72</b>  |
| <b>Dousman Total</b>                 |   |          |              |            |               | <b>60.72</b>  |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3452 | MTS-2000 Mode | 1.02          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3434 | MTS-2000 Mode | 1.02          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3447 | MTS-2000 Mode | 1.18          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3421 | MTS-2000 Mode | 1.4           |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3453 | MTS-2000 Mode | 1.44          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3449 | MTS-2000 Mode | 2.14          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABE1909 | MTS-2000 Mode | 2.38          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3424 | MTS-2000 Mode | 2.58          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3429 | MTS-2000 Mode | 5.62          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3436 | MTS-2000 Mode | 5.96          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3432 | MTS-2000 Mode | 7.4           |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | H01UCF6PW1BN | 466ABS3445 | MTS-2000 Mode | 11.06         |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1381 | MCS-2000 Mode | 1.02          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1404 | MCS-2000 Mode | 1.08          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1364 | MCS-2000 Mode | 3.12          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1395 | MCS-2000 Mode | 4.12          |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1371 | MCS-2000 Mode | 8.2           |
| Dousman Fire Department              | Dousman Fire Department                     | Motorola | M01UGM6PW6BN | 722ABS1410 | MCS-2000 Mode | 20.8          |
|                                      | <b>Dousman Fire Department Total</b>        |          |              |            |               | <b>81.54</b>  |
| <b>Dousman Fire Department Total</b> |   |          |              |            |               | <b>81.54</b>  |
| Eagle Fire District                  | Eagle Fire District                         | Motorola | H18UCF9PW6AN | 721CGZ4330 | XTS-5000 Mode | 1.32          |
| Eagle Fire District                  | Eagle Fire District                         | Motorola | H18UCF9PW6AN | 721CGZ4324 | XTS-5000 Mode | 2.16          |
| Eagle Fire District                  | Eagle Fire District                         | Motorola | H18UCF9PW6AN | 721CGZ4325 | XTS-5000 Mode | 5.4           |
| Eagle Fire District                  | Eagle Fire District                         | Motorola | H18UCF9PW6AN | 721CGZ4331 | XTS-5000 Mode | 8.68          |

## September, 2008 Trunked Radio Usage

|                                  |   |          |              |            |                 |               |
|----------------------------------|---|----------|--------------|------------|-----------------|---------------|
| Eagle Fire District              | Eagle Fire District                               | Motorola | H18UCF9PW6AN | 721CHT0783 | XTS-5000 Mode   | 12.72         |
| Eagle Fire District              | Eagle Fire District                               | Motorola | H46UCF9PW6AN | 205cfz1920 | XTS-2500 Mode   | 1.44          |
| Eagle Fire District              | Eagle Fire District                               | Motorola | H46UCF9PW6AN | 205cfz1910 | XTS-2500 Mode   | 2.12          |
| Eagle Fire District              | Eagle Fire District                               | Motorola | H46UCF9PW6AN | 205cfz1911 | XTS-2500 Mode   | 4.02          |
| Eagle Fire District              | Eagle Fire District                               | Motorola | M20URS9PW1AN | 500CGD0442 | XTL-5000 Dual C | 1.26          |
| Eagle Fire District              | Eagle Fire District                               | Motorola | M20URS9PW1AN | 500CGD0444 | XTL-5000 Dual C | 3.54          |
| Eagle Fire District              | Eagle Fire District                               | Motorola | M20URS9PW1AN | 500CGD0443 | XTL-5000 Dual C | 9.42          |
|                                  | <b>Eagle Fire District Total</b>                  |          |              |            |                 | <b>52.08</b>  |
| <b>Eagle Fire District Total</b> |   |          |              |            |                 | <b>52.08</b>  |
| Eagle, Village                   | Eagle Village DPW                                 | Motorola | H10UCH6DC5BN | 678SAQ2742 | LTS-2000 w/sca  | 3.58          |
| Eagle, Village                   | Eagle Village DPW                                 | Motorola | H18UCF9PW6AN | 721CJH0691 | XTS-5000 Mode   | 3.58          |
|                                  | <b>Eagle Village DPW Total</b>                    |          |              |            |                 | <b>7.16</b>   |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | D35KGA5JC5AK | 604AUE0123 | Spectra         | 72.1          |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | H01UCD6PW1BN | 466ABA1019 | MTS-2000 Mode   | 4.3           |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | H01UCD6PW1BN | 466ABA1021 | MTS-2000 Mode   | 10.94         |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | H01UCD6PW1BN | 466ABA1022 | MTS-2000 Mode   | 15.5          |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | H01UCD6PW1BN | 466ABA1020 | MTS-2000 Mode   | 23.52         |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | M01UGM6PW6AN | 722AWE1640 | MCS-2000 Mode   | 30.38         |
| Eagle, Village                   | Eagle Village Police Department                   | Motorola | M21URM9PW2AN | 624CJP0443 | XTL-2500RB      | 72.1          |
|                                  | <b>Eagle Village Police Department Total</b>      |          |              |            |                 | <b>228.84</b> |
| <b>Eagle, Village Total</b>      |   |          |              |            |                 | <b>236</b>    |
| Elm Grove                        | Elm Grove Emergency Medical Services              | Motorola | H01UCF6PW1BN | 466ABS3368 | MTS-2000 Mode   | 1.12          |
| Elm Grove                        | Elm Grove Emergency Medical Services              | Motorola | M01UGM6PW6BN | 722ABS1432 | MCS-2000 Mode   | 18.22         |
|                                  | <b>Elm Grove Emergency Medical Services Total</b> |          |              |            |                 | <b>19.34</b>  |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3464 | MTS-2000 Mode   | 1.24          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3466 | MTS-2000 Mode   | 1.24          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3475 | MTS-2000 Mode   | 1.4           |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3472 | MTS-2000 Mode   | 2             |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3463 | MTS-2000 Mode   | 2.14          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3470 | MTS-2000 Mode   | 2.24          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3474 | MTS-2000 Mode   | 3.42          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3462 | MTS-2000 Mode   | 3.72          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3457 | MTS-2000 Mode   | 4.44          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3471 | MTS-2000 Mode   | 5.12          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H01UCF6PW1BN | 466ABS3459 | MTS-2000 Mode   | 5.5           |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | H18UCF9PW6AN | 721CGX1246 | XTS-5000 Mode   | 6.06          |
| Elm Grove                        | Elm Grove Fire Department                         | Motorola | M01UGM6PW6BN | 722ABS1427 | MCS-2000 Mode   | 2             |

**September, 2008  
Trunked Radio Usage**

|           |  |          |              |            |                |                |
|-----------|--|----------|--------------|------------|----------------|----------------|
| Elm Grove | Elm Grove Fire Department                | Motorola | M01UGM6PW6BN | 722ABS1377 | MCS-2000 Mode  | 2.08           |
| Elm Grove | Elm Grove Fire Department                | Motorola | M01UGM6PW6BN | 722ABS1367 | MCS-2000 Mode  | 4.2            |
| Elm Grove | Elm Grove Fire Department                | Motorola | M01UGM6PW6BN | 722ABS1430 | MCS-2000 Mode  | 4.4            |
| Elm Grove | Elm Grove Fire Department                | Motorola | M01UGM6PW6BN | 722ABS1426 | MCS-2000 Mode  | 4.54           |
|           | <b>Elm Grove Fire Department Total</b>   |          |              |            |                | <b>55.74</b>   |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3378 | MTS-2000 Mode  | 1.12           |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3382 | MTS-2000 Mode  | 2.06           |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3387 | MTS-2000 Mode  | 6.22           |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3404 | MTS-2000 Mode  | 7.12           |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3398 | MTS-2000 Mode  | 11.32          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3385 | MTS-2000 Mode  | 12.08          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3410 | MTS-2000 Mode  | 12.58          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3403 | MTS-2000 Mode  | 13.28          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3383 | MTS-2000 Mode  | 13.76          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3395 | MTS-2000 Mode  | 14.4           |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3388 | MTS-2000 Mode  | 15.64          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3384 | MTS-2000 Mode  | 16.32          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466CDY1171 | MTS-2000 Mode  | 20.06          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3393 | MTS-2000 Mode  | 24.44          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3389 | MTS-2000 Mode  | 25.62          |
| Elm Grove | Elm Grove Police Department              | Motorola | H01UCF6PW1BN | 466ABS3411 | MTS-2000 Mode  | 27.08          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGL6PW4BN | 722ABE3127 | MCS-2000 Mode  | 15.12          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGL6PW4BN | 722ABE3129 | MCS-2000 Mode  | 23.52          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGL6PW4BN | 722ABE3130 | MCS-2000 Mode  | 349.14         |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1366 | MCS-2000 Mode  | 5.02           |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1370 | MCS-2000 Mode  | 13.24          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1361 | MCS-2000 Mode  | 33.34          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1362 | MCS-2000 Mode  | 126.38         |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1355 | MCS-2000 Mode  | 140.7          |
| Elm Grove | Elm Grove Police Department              | Motorola | M01UGM6PW6BN | 722ABS1419 | MCS-2000 Mode  | 153.7          |
|           | <b>Elm Grove Police Department Total</b> |          |              |            |                | <b>1083.26</b> |
| Elm Grove | Elm Grove Public Works Department        | Motorola | H10UCH6DC5BN | 678SBC1170 | LTS-2000 w/sca | 1.12           |
| Elm Grove | Elm Grove Public Works Department        | Motorola | H46UCF9PW6BN | 205CJF0415 | XTS-2500 Mode  | 1.12           |
| Elm Grove | Elm Grove Public Works Department        | Motorola | M01UGM6PW6BN | 722ABS1374 | MCS-2000 Mode  | 2.54           |
| Elm Grove | Elm Grove Public Works Department        | Motorola | M10UGD6DC5BN | 760SAYER37 | LCS-2000 w/sca | 1.16           |
| Elm Grove | Elm Grove Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW0982 | LCS-2000 w/sca | 1.16           |
| Elm Grove | Elm Grove Public Works Department        | Motorola | M10UGD6DC5BN | 760SAYER10 | LCS-2000 w/sca | 2.02           |

**September, 2008  
Trunked Radio Usage**

|                             |  |          |              |            |                 |               |
|-----------------------------|--|----------|--------------|------------|-----------------|---------------|
| Elm Grove                   | Elm Grove Public Works Department              | Motorola | M21URM9PW2AN | 624CJP1006 | XTL-2500RB      | 1.16          |
| Elm Grove                   | Elm Grove Public Works Department              | Motorola | M21URM9PW2AN | 624CJP1009 | XTL-2500RB      | 1.16          |
| Elm Grove                   | Elm Grove Public Works Department              | Motorola | M21URM9PW2AN | 624CJP1011 | XTL-2500RB      | 2.02          |
|                             | <b>Elm Grove Public Works Department Total</b> |          |              |            |                 | <b>13.46</b>  |
| <b>Elm Grove Total</b>      |  |          |              |            |                 | <b>1171.8</b> |
| Hales Corners,              | Hales Corners Fire Department                  | Motorola | H46UCF9PW6BN | 205CHR1281 | XTS-2500 Mode   | 1.22          |
|                             | <b>Hales Corners Fire Department Total</b>     |          |              |            |                 | <b>1.22</b>   |
| <b>Hales Corners, Total</b> |  |          |              |            |                 | <b>1.22</b>   |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466abs3062 | MTS-2000 Mode   | 1.1           |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466ABL3334 | MTS-2000 Mode   | 2.54          |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466ABL3320 | MTS-2000 Mode   | 8.18          |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466ABL3328 | MTS-2000 Mode   | 9.54          |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466ABL3329 | MTS-2000 Mode   | 18.88         |
| Hartland                    | Hartland Fire Department                       | Motorola | H01UCD6PW1BN | 466ABL3324 | MTS-2000 Mode   | 25.64         |
| Hartland                    | Hartland Fire Department                       | Motorola | H10UCH6DC5BN | 678SBE0974 | LTS-2000 w/o sc | 1.3           |
| Hartland                    | Hartland Fire Department                       | Motorola | H10UCH6DC5BN | 678SBG0156 | LTS-2000 w/sca  | 9.88          |
| Hartland                    | Hartland Fire Department                       | Motorola | H10UCH6DC5BN | 678SBG0074 | LTS-2000 w/sca  | 9.96          |
| Hartland                    | Hartland Fire Department                       | Motorola | H18UCF9PW6AN | 721CJK0279 | XTS-5000 Mode   | 1.3           |
| Hartland                    | Hartland Fire Department                       | Motorola | H18UCF9PW6AN | 721CJK0282 | XTS-5000 Mode   | 9.88          |
| Hartland                    | Hartland Fire Department                       | Motorola | H18UCF9PW6AN | 721CJK0284 | XTS-5000 Mode   | 9.96          |
| Hartland                    | Hartland Fire Department                       | Motorola | M01UGM6PW6BN | 722ABL1325 | MCS-2000 Mode   | 1.5           |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0933 | XTL-5000 Mobile | 1.58          |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0938 | XTL-5000 Mobile | 2.04          |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0936 | XTL-5000 Mobile | 2.08          |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0932 | XTL-5000 Mobile | 3.38          |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0939 | XTL-5000 Mobile | 6.1           |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0934 | XTL-5000 Mobile | 8.4           |
| Hartland                    | Hartland Fire Department                       | Motorola | M20URS9PW1AN | 500CJP0931 | XTL-5000 Mobile | 43.38         |
|                             | <b>Hartland Fire Department Total</b>          |          |              |            |                 | <b>176.62</b> |
| Hartland                    | Hartland Police Department                     | Motorola | H10UCH6DC5BN | 678SBG0161 | LTS-2000 w/sca  | 14.76         |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0288 | XTS-5000 Mode   | 3.4           |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0306 | XTS-5000 Mode   | 6.36          |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0298 | XTS-5000 Mode   | 8.22          |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0308 | XTS-5000 Mode   | 8.84          |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0290 | XTS-5000 Mode   | 12.62         |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0296 | XTS-5000 Mode   | 14.76         |
| Hartland                    | Hartland Police Department                     | Motorola | H18UCF9PW6AN | 721CJK0294 | XTS-5000 Mode   | 18.68         |

**September, 2008  
Trunked Radio Usage**

|                           |   |          |              |            |                 |                |
|---------------------------|---|----------|--------------|------------|-----------------|----------------|
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0299 | XTS-5000 Mode   | 18.7           |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0301 | XTS-5000 Mode   | 22.96          |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0303 | XTS-5000 Mode   | 23.36          |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0305 | XTS-5000 Mode   | 26.4           |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0289 | XTS-5000 Mode   | 26.92          |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0295 | XTS-5000 Mode   | 30.28          |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0302 | XTS-5000 Mode   | 36.76          |
| Hartland                  | Hartland Police Department                    | Motorola | H18UCF9PW6AN | 721CJK0297 | XTS-5000 Mode   | 48.26          |
| Hartland                  | Hartland Police Department                    | Motorola | M10UGD6DC5BN | 760SAS4206 | LCS-2000 w/sca  | 114.6          |
| Hartland                  | Hartland Police Department                    | Motorola | M20URS9PW1AN | 500CJP0941 | XTL-5000 Mobile | 13.24          |
| Hartland                  | Hartland Police Department                    | Motorola | M20URS9PW1AN | 500CJP0946 | XTL-5000 Mobile | 44.02          |
| Hartland                  | Hartland Police Department                    | Motorola | M20URS9PW1AN | 500CJP0945 | XTL-5000 Mobile | 94.3           |
| Hartland                  | Hartland Police Department                    | Motorola | M20URS9PW1AN | 500CJP0944 | XTL-5000 Mobile | 114.6          |
| Hartland                  | Hartland Police Department                    | Motorola | M20URS9PW1AN | 500CJP0943 | XTL-5000 Mobile | 145.14         |
|                           | <b>Hartland Police Department Total</b>       |          |              |            |                 | <b>847.18</b>  |
| Hartland                  | Hartland Public Works Department              | Motorola | H10UCH6DC5BN | 678SBG0159 | LTS-2000 w/sca  | 18.04          |
| Hartland                  | Hartland Public Works Department              | Motorola | H10UCH6DC5BN | 678SBE0961 | LTS-2000 w/o sc | 29.48          |
| Hartland                  | Hartland Public Works Department              | Motorola | H18UCF9PW6AN | 721CJK0274 | XTS-5000 Mode   | 18.04          |
| Hartland                  | Hartland Public Works Department              | Motorola | H18UCF9PW6AN | 721CJK0310 | XTS-5000 Mode   | 29.48          |
| Hartland                  | Hartland Public Works Department              | Motorola | M10UGD6DC5BN | 760SBA0416 | LCS-2000 w/o sc | 1.08           |
| Hartland                  | Hartland Public Works Department              | Motorola | M10UGD6DC5BN | 760SBE0312 | LCS-2000 w/o sc | 1.3            |
| Hartland                  | Hartland Public Works Department              | Motorola | M10UGD6DC5BN | 760SAS0345 | LCS-2000 w/sca  | 3.26           |
| Hartland                  | Hartland Public Works Department              | Motorola | M20URS9PW1AN | 500CJP0966 | XTL-5000 Mobile | 1.08           |
| Hartland                  | Hartland Public Works Department              | Motorola | M20URS9PW1AN | 500CJP0960 | XTL-5000 Mobile | 1.3            |
| Hartland                  | Hartland Public Works Department              | Motorola | M20URS9PW1AN | 500CJP0970 | XTL-5000 Mobile | 3.26           |
|                           | <b>Hartland Public Works Department Total</b> |          |              |            |                 | <b>106.32</b>  |
| <b>Hartland Total</b>     |   |          |              |            |                 | <b>1130.12</b> |
| Lac La Belle              | Lac La Belle Police Department                | Motorola | H01UCF6PW1BN | 466ABE1911 | MTS-2000 Mode   | 4.18           |
| Lac La Belle              | Lac La Belle Police Department                | Motorola | M01UGM6PW6BN | 722ABE1313 | MCS-2000 Mode   | 24.44          |
|                           | <b>Lac La Belle Police Department Total</b>   |          |              |            |                 | <b>28.62</b>   |
| <b>Lac La Belle Total</b> |   |          |              |            |                 | <b>28.62</b>   |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCD6PW1BN | 466ABE4885 | MTS-2000 Mode   | 1.34           |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCF6PW1BN | 466ABE1896 | MTS-2000 Mode   | 2.64           |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCF6PW1BN | 466ABE1915 | MTS-2000 Mode   | 5.04           |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCF6PW1BN | 466ABE1900 | MTS-2000 Mode   | 10.48          |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCH6PW1BN | 466AAL4015 | MTS-2000 Mode   | 2.4            |
| Lisbon                    | Lisbon Fire Department                        | Motorola | H01UCH6PW1BN | 466AAL4026 | MTS-2000 Mode   | 3.12           |

## September, 2008 Trunked Radio Usage

|                     |                                     |          |              |            |                 |               |
|---------------------|-------------------------------------|----------|--------------|------------|-----------------|---------------|
| Lisbon              | Lisbon Fire Department              | Motorola | H01UCH6PW1BN | 466AAL4031 | MTS-2000 Mode   | 3.62          |
| Lisbon              | Lisbon Fire Department              | Motorola | H01UCH6PW1BN | 466AAL4027 | MTS-2000 Mode   | 4.94          |
| Lisbon              | Lisbon Fire Department              | Motorola | H46UCF9PW6AN | 205CGP0258 | XTS-2500 Mode   | 2.46          |
| Lisbon              | Lisbon Fire Department              | Motorola | H46UCF9PW6AN | 205CGP0256 | XTS-2500 Mode   | 3.1           |
| Lisbon              | Lisbon Fire Department              | Motorola | H46UCF9PW6AN | 205CGP0257 | XTS-2500 Mode   | 5.96          |
| Lisbon              | Lisbon Fire Department              | Motorola | H46UCF9PW6AN | 205CGP0259 | XTS-2500 Mode   | 9.02          |
| Lisbon              | Lisbon Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1372 | MCS-2000 Mode   | 15.84         |
| Lisbon              | Lisbon Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1354 | MCS-2000 Mode   | 17.16         |
| Lisbon              | Lisbon Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2110 | MCS-2000 Mode   | 1.58          |
| Lisbon              | Lisbon Fire Department              | Motorola | M10UGD6DC5BN | 760SAW0961 | LCS-2000 w/sca  | 1.14          |
| Lisbon              | Lisbon Fire Department              | Motorola | M21URM9PW1AN | 514CGP0174 | XTL-2500 Mobile | 15.34         |
| Lisbon              | Lisbon Fire Department              | Motorola | M21URM9PW2AN | 624CJP0436 | XTL-2500RB      | 1.14          |
| Lisbon              | Lisbon Fire Department              | Motorola | M21URM9PW2AN | 624CJP0437 | XTL-2500RB      | 1.3           |
| Lisbon              | Lisbon Fire Department              | Motorola | M21URM9PW2AN | 624CJP0434 | XTL-2500RB      | 6.24          |
|                     | <b>Lisbon Fire Department Total</b> |          |              |            |                 | <b>113.86</b> |
| <b>Lisbon Total</b> |                                     |          |              |            |                 | <b>113.86</b> |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1731 | XTS-5000 Mode   | 1.04          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721cgb2403 | XTS-5000 Mode   | 1.06          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1738 | XTS-5000 Mode   | 1.16          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFM2686 | XTS-5000 Mode   | 1.28          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1726 | XTS-5000 Mode   | 1.4           |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1743 | XTS-5000 Mode   | 2.36          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1730 | XTS-5000 Mode   | 2.4           |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1732 | XTS-5000 Mode   | 2.42          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1734 | XTS-5000 Mode   | 2.54          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721cgb2400 | XTS-5000 Mode   | 2.56          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721cgb2401 | XTS-5000 Mode   | 3.14          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1729 | XTS-5000 Mode   | 3.18          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFM2685 | XTS-5000 Mode   | 4.16          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CHF6497 | XTS-5000 Mode   | 4.26          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CHF6499 | XTS-5000 Mode   | 5.42          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1725 | XTS-5000 Mode   | 7.28          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1740 | XTS-5000 Mode   | 8.14          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1736 | XTS-5000 Mode   | 8.28          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFM2683 | XTS-5000 Mode   | 8.58          |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1724 | XTS-5000 Mode   | 11.78         |
| Menomonee Falls     | Menomonee Falls Fire Department     | Motorola | H18UCF9PW6AN | 721CFP1742 | XTS-5000 Mode   | 12.12         |

## September, 2008 Trunked Radio Usage

|                                     |  |          |              |            |                 |               |
|-------------------------------------|--|----------|--------------|------------|-----------------|---------------|
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | H18UCF9PW6AN | 721CHF6498 | XTS-5000 Mode   | 12.48         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | H18UCF9PW6AN | 721CFP1741 | XTS-5000 Mode   | 12.48         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | H18UCF9PW6AN | 721CFM2684 | XTS-5000 Mode   | 14.98         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | H18UCF9PW6AN | 721CFM2687 | XTS-5000 Mode   | 15.26         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AM | 500CGF0765 | XTL-5000 Mobile | 9.14          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0400 | XTL-5000 Mobile | 2.06          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0396 | XTL-5000 Mobile | 2.48          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFX1007 | XTL-5000 Mobile | 6             |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0403 | XTL-5000 Mobile | 6.14          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0401 | XTL-5000 Mobile | 7.76          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFM2835 | XTL-5000 Mobile | 9.28          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0603 | XTL-5000 Mobile | 14.34         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CGM1782 | XTL-5000 Dual C | 17.54         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFM2838 | XTL-5000 Mobile | 28.6          |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0398 | XTL-5000 Mobile | 29.44         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0604 | XTL-5000 Mobile | 34.46         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0393 | XTL-5000 Mobile | 69.12         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFR0605 | XTL-5000 Mobile | 79.88         |
| Menomonee Falls                     | Menomonee Falls Fire Department                | Motorola | M20URS9PW1AN | 500CFM2836 | XTL-5000 Mobile | 290.12        |
|                                     | <b>Menomonee Falls Fire Department Total</b>   |          |              |            |                 | <b>756.12</b> |
| Menomonee Falls                     | Menomonee Falls Police Department              | Motorola | M20URS9PW1AN | 500CHR0358 | XTL-5000 Mobile | 10.5          |
|                                     | <b>Menomonee Falls Police Department Total</b> |          |              |            |                 | <b>10.5</b>   |
| <b>Menomonee Falls Total</b>        |  |          |              |            |                 | <b>766.62</b> |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5479 | XTS-2500 Mode   | 1.46          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5499 | XTS-2500 Mode   | 2.26          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5480 | XTS-2500 Mode   | 2.42          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5475 | XTS-2500 Mode   | 3.22          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5486 | XTS-2500 Mode   | 5.08          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5474 | XTS-2500 Mode   | 5.28          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | H46UCF9PW6BN | 205CJF5485 | XTS-2500 Mode   | 10.74         |
| Merton Fire Department              | Merton Fire Department                         | Motorola | M21URM9PW2AN | 624CJK0834 | XTL-2500RB      | 1.22          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | M21URM9PW2AN | 624CJK0836 | XTL-2500RB      | 1.36          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | M21URM9PW2AN | 624CJK0833 | XTL-2500RB      | 1.46          |
| Merton Fire Department              | Merton Fire Department                         | Motorola | M21URM9PW2AN | 624CJK0835 | XTL-2500RB      | 7.5           |
|                                     | <b>Merton Fire Department Total</b>            |          |              |            |                 | <b>42</b>     |
| <b>Merton Fire Department Total</b> |  |          |              |            |                 | <b>42</b>     |
| Merton, Town                        | Merton Town Highway Department                 | Motorola | M10UGD6DC5BN | 760SBN0118 | LCS-2000 w/o sc | 1.22          |

## September, 2008 Trunked Radio Usage

|                               |   |          |              |            |                 |              |
|-------------------------------|---|----------|--------------|------------|-----------------|--------------|
| Merton, Town                  | Merton Town Highway Department                | Motorola | M10UGD6DC5BN | 760SBN0116 | LCS-2000 w/o sc | 1.46         |
| Merton, Town                  | Merton Town Highway Department                | Motorola | M21URM9PW2AN | 624CJP0961 | XTL-2500RB      | 1.22         |
| Merton, Town                  | Merton Town Highway Department                | Motorola | M21URM9PW2AN | 624CJP0966 | XTL-2500RB      | 1.46         |
| Merton, Town                  | Merton Town Highway Department                | Motorola | M28URS9PW1AN | 775TGA1901 | XTL-1500 Mobile | 2.34         |
|                               | <b>Merton Town Highway Department Total</b>   |          |              |            |                 | <b>7.7</b>   |
| Merton, Town                  | Merton Town Lake Patrol                       | Motorola | H01UCF6PW1BN | 466ABS3455 | MTS-2000 Mode   | 2.54         |
| Merton, Town                  | Merton Town Lake Patrol                       | Motorola | M01UGM6PW6BN | 722ABS1443 | MCS-2000 Mode   | 5.52         |
|                               | <b>Merton Town Lake Patrol Total</b>          |          |              |            |                 | <b>8.06</b>  |
| <b>Merton, Town Total</b>     |   |          |              |            |                 | <b>15.76</b> |
| Milwaukee County              | Milwaukee County Flight for Life              | Motorola | H01UCF6PW1BN | 466ABW3018 | MTS-2000 Mode   | 2            |
|                               | <b>Milwaukee County Flight for Life Total</b> |          |              |            |                 | <b>2</b>     |
| <b>Milwaukee County Total</b> |   |          |              |            |                 | <b>2</b>     |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H01UCF6PW1BN | 466ABW4606 | MTS-2000 Mode   | 1.04         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H01UCF6PW1BN | 466ABW4971 | MTS-2000 Mode   | 1.42         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H01UCF6PW1BN | 466AAE4534 | MTS-2000 Mode   | 3.52         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4303 | XTS-2500 Mode   | 1.1          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4292 | XTS-2500 Mode   | 1.1          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4277 | XTS-2500 Mode   | 1.14         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4283 | XTS-2500 Mode   | 1.18         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4299 | XTS-2500 Mode   | 1.32         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4281 | XTS-2500 Mode   | 1.5          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4286 | XTS-2500 Mode   | 1.56         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4307 | XTS-2500 Mode   | 2.14         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4287 | XTS-2500 Mode   | 2.6          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4296 | XTS-2500 Mode   | 2.8          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4268 | XTS-2500 Mode   | 3.04         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4297 | XTS-2500 Mode   | 3.34         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4290 | XTS-2500 Mode   | 3.88         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4291 | XTS-2500 Mode   | 4.02         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4285 | XTS-2500 Mode   | 4.24         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4272 | XTS-2500 Mode   | 5.44         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4300 | XTS-2500 Mode   | 5.52         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4295 | XTS-2500 Mode   | 7.14         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4289 | XTS-2500 Mode   | 7.7          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4278 | XTS-2500 Mode   | 7.7          |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4304 | XTS-2500 Mode   | 9.16         |
| Mukwonago Fire Department     | Mukwonago Fire Department                     | Motorola | H46UCF9PW6AN | 205CFZ4310 | XTS-2500 Mode   | 16.68        |

**September, 2008  
Trunked Radio Usage**

|  |  |          |              |            |                 |               |
|--|--|----------|--------------|------------|-----------------|---------------|
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M20URS9PW1AN | 500CGF1127 | XTL-5000 Mobile | 22.38         |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M20URS9PW1AN | 500CGF1128 | XTL-5000 Mobile | 25.3          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M20URS9PW1AN | 500CGF1129 | XTL-5000 Mobile | 69.9          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0494 | XTL-2500 Mobile | 1.44          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0483 | XTL-2500 Mobile | 3.18          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0489 | XTL-2500 Mobile | 3.46          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0487 | XTL-2500 Mobile | 5.56          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0491 | XTL-2500 Mobile | 7.58          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0492 | XTL-2500 Mobile | 9             |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0485 | XTL-2500 Mobile | 10.54         |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0490 | XTL-2500 Mobile | 15.2          |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0498 | XTL-2500 Mobile | 43.36         |
| Mukwonago Fire Department              | Mukwonago Fire Department              | Motorola | M21URM9PW1AN | 514CGF0486 | XTL-2500 Mobile | 276.16        |
|  | <b>Mukwonago Fire Department Total</b> |          |              |            |                 | <b>593.34</b> |
| <b>Mukwonago Fire Department Total</b> |  |          |              |            |                 | <b>593.34</b> |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466CDE1786 | MTS-2000 Mode   | 1.38          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466CDE1800 | MTS-2000 Mode   | 2.08          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466CDE1780 | MTS-2000 Mode   | 2.1           |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0917 | MTS-2000 Mode   | 2.2           |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466CDE1779 | MTS-2000 Mode   | 2.36          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0919 | MTS-2000 Mode   | 3.48          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0943 | MTS-2000 Mode   | 4.14          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0927 | MTS-2000 Mode   | 4.54          |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0928 | MTS-2000 Mode   | 8.9           |
| Muskego                                | Muskego Fire Department                | Motorola | H01UCD6PW1BN | 466CDE1784 | MTS-2000 Mode   | 9.34          |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1346 | MCS-2000 Mode   | 1.18          |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1352 | MCS-2000 Mode   | 1.32          |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1367 | MCS-2000 Mode   | 2.2           |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1334 | MCS-2000 Mode   | 2.44          |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1325 | MCS-2000 Mode   | 3.22          |
| Muskego                                | Muskego Fire Department                | Motorola | M01UGM6PW6BN | 722ABE1342 | MCS-2000 Mode   | 5.34          |
|  | <b>Muskego Fire Department Total</b>   |          |              |            |                 | <b>56.22</b>  |
| Muskego                                | Muskego Park Department                | Motorola | H10UCH6DC5BN | 678SAQ2746 | LTS-2000 w/sca  | 2.22          |
| Muskego                                | Muskego Park Department                | Motorola | H10UCH6DC5BN | 678SAQ2743 | LTS-2000 w/sca  | 8.02          |
| Muskego                                | Muskego Park Department                | Motorola | H10UCH6DC5BN | 678SAQ2771 | LTS-2000 w/sca  | 14.08         |
| Muskego                                | Muskego Park Department                | Motorola | H10UCH6DC5BN | 678SAQ2748 | LTS-2000 w/sca  | 20.4          |
| Muskego                                | Muskego Park Department                | Motorola | H46UCF9PW6BN | 205CJF0530 | XTS-2500 Mode   | 2.22          |

## September, 2008 Trunked Radio Usage

|         |                                      |          |              |            |                |              |
|---------|--------------------------------------|----------|--------------|------------|----------------|--------------|
| Muskego | Muskego Park Department              | Motorola | H46UCF9PW6BN | 205CJF0528 | XTS-2500 Mode  | 8.02         |
| Muskego | Muskego Park Department              | Motorola | H46UCF9PW6BN | 205CJF0534 | XTS-2500 Mode  | 14.08        |
| Muskego | Muskego Park Department              | Motorola | H46UCF9PW6BN | 205CJF0532 | XTS-2500 Mode  | 20.4         |
| Muskego | Muskego Park Department              | Motorola | M10UGD6DC5BN | 760SAW0477 | LCS-2000 w/sca | 7.22         |
|         | <b>Muskego Park Department Total</b> |          |              |            |                | <b>96.66</b> |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4907 | MTS-2000 Mode  | 2.04         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4813 | MTS-2000 Mode  | 2.26         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4882 | MTS-2000 Mode  | 2.42         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4858 | MTS-2000 Mode  | 3.34         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4867 | MTS-2000 Mode  | 3.48         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4939 | MTS-2000 Mode  | 4.1          |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4828 | MTS-2000 Mode  | 6.34         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4900 | MTS-2000 Mode  | 7.16         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4807 | MTS-2000 Mode  | 8.18         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4873 | MTS-2000 Mode  | 8.54         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4985 | MTS-2000 Mode  | 9.56         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4908 | MTS-2000 Mode  | 12.54        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE5024 | MTS-2000 Mode  | 13.46        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4819 | MTS-2000 Mode  | 15.42        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4812 | MTS-2000 Mode  | 16.14        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4898 | MTS-2000 Mode  | 21.26        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE5026 | MTS-2000 Mode  | 24.7         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4866 | MTS-2000 Mode  | 26.12        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4941 | MTS-2000 Mode  | 26.3         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4826 | MTS-2000 Mode  | 26.54        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4837 | MTS-2000 Mode  | 27.38        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4931 | MTS-2000 Mode  | 27.58        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4999 | MTS-2000 Mode  | 28.72        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4914 | MTS-2000 Mode  | 30.4         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4854 | MTS-2000 Mode  | 34.22        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466CCU0101 | MTS-2000 Mode  | 34.3         |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4890 | MTS-2000 Mode  | 34.54        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4829 | MTS-2000 Mode  | 35.16        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4937 | MTS-2000 Mode  | 35.28        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4798 | MTS-2000 Mode  | 35.34        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4876 | MTS-2000 Mode  | 39.08        |
| Muskego | Muskego Police Department            | Motorola | H01UCD6PW1BN | 466ABE4938 | MTS-2000 Mode  | 45.42        |

## September, 2008 Trunked Radio Usage

|         |  |          |              |            |                 |               |
|---------|--|----------|--------------|------------|-----------------|---------------|
| Muskego | Muskego Police Department                    | Motorola | H01UCD6PW1BN | 466CCU0102 | MTS-2000 Mode   | 47.46         |
| Muskego | Muskego Police Department                    | Motorola | H01UCD6PW1BN | 466ABE4883 | MTS-2000 Mode   | 47.54         |
| Muskego | Muskego Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0210 | XTS-5000 Mode   | 14.74         |
| Muskego | Muskego Police Department                    | Motorola | M01UGL6PW4BN | 722ABG0528 | MCS-2000 Mode   | 1.42          |
| Muskego | Muskego Police Department                    | Motorola | M01UGL6PW4BN | 722abj0510 | MCS-2000 Mode   | 23.24         |
| Muskego | Muskego Police Department                    | Motorola | M01UGL6PW4BN | 722ABA0529 | MCS-2000 Mode   | 115           |
| Muskego | Muskego Police Department                    | Motorola | M01UGL6PW4BN | 722ABA0528 | MCS-2000 Mode   | 1008.42       |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1361 | MCS-2000 Mode   | 5.06          |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1366 | MCS-2000 Mode   | 6.34          |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1356 | MCS-2000 Mode   | 13.52         |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1368 | MCS-2000 Mode   | 15.22         |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1344 | MCS-2000 Mode   | 21.56         |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1362 | MCS-2000 Mode   | 133.9         |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1436 | MCS-2000 Mode   | 236.44        |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1351 | MCS-2000 Mode   | 242.46        |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1363 | MCS-2000 Mode   | 249.04        |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1360 | MCS-2000 Mode   | 269.54        |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1411 | MCS-2000 Mode   | 273.22        |
| Muskego | Muskego Police Department                    | Motorola | M01UGM6PW6BN | 722ABE1354 | MCS-2000 Mode   | 311.86        |
|         | <b>Muskego Police Department Total</b>       |          |              |            |                 | <b>3683.3</b> |
| Muskego | Muskego Public Works Department              | Motorola | H10UCH6DC5BN | 678SAU3833 | LTS-2000 w/o sc | 2.34          |
| Muskego | Muskego Public Works Department              | Motorola | H46UCF9PW6BN | 205CJF0520 | XTS-2500 Mode   | 2.34          |
| Muskego | Muskego Public Works Department              | Motorola | M10UGD6DC5BN | 760SAU0856 | LCS-2000 w/sca  | 1.02          |
| Muskego | Muskego Public Works Department              | Motorola | M10UGD6DC5BN | 760SAU0863 | LCS-2000 w/sca  | 1.28          |
| Muskego | Muskego Public Works Department              | Motorola | M10UGD6DC5BN | 760SAW0448 | LCS-2000 w/sca  | 1.32          |
| Muskego | Muskego Public Works Department              | Motorola | M10UGD6DC5BN | 760SAW0446 | LCS-2000 w/sca  | 2.06          |
|         | <b>Muskego Public Works Department Total</b> |          |              |            |                 | <b>10.36</b>  |
| Muskego | Muskego Utilities                            | Motorola | M10UGD6DC5BN | 760SAW0437 | LCS-2000 w/sca  | 1.42          |
|         | <b>Muskego Utilities Total</b>               |          |              |            |                 | <b>1.42</b>   |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466CDE1777 | MTS-2000 Mode   | 1.06          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ABE5000 | MTS-2000 Mode   | 1.18          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ABS3028 | MTS-2000 Mode   | 1.18          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466CEE0424 | MTS-2000 Mode   | 1.24          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ACG0318 | MTS-2000 Mode   | 1.26          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ABS3029 | MTS-2000 Mode   | 1.36          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ABS2917 | MTS-2000 Mode   | 1.46          |
| Muskego | Tess Corners Fire Department                 | Motorola | H01UCD6PW1BN | 466ABS3025 | MTS-2000 Mode   | 1.56          |

**September, 2008  
Trunked Radio Usage**

|                      |   |          |              |            |                 |                |
|----------------------|---|----------|--------------|------------|-----------------|----------------|
| Muskego              | Tess Corners Fire Department              | Motorola | H01UCD6PW1BN | 466CEL0441 | MTS-2000 Mode   | 2.28           |
| Muskego              | Tess Corners Fire Department              | Motorola | H01UCD6PW1BN | 466ABE5033 | MTS-2000 Mode   | 2.38           |
| Muskego              | Tess Corners Fire Department              | Motorola | H01UCD6PW1BN | 466CEE0427 | MTS-2000 Mode   | 6              |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2024 | XTS-2500 Mode   | 1.32           |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2026 | XTS-2500 Mode   | 1.42           |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2021 | XTS-2500 Mode   | 2.4            |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2023 | XTS-2500 Mode   | 3.06           |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2027 | XTS-2500 Mode   | 3.3            |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2025 | XTS-2500 Mode   | 4.1            |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2029 | XTS-2500 Mode   | 4.48           |
| Muskego              | Tess Corners Fire Department              | Motorola | H46UCF9PW6AN | 205CFV2028 | XTS-2500 Mode   | 15.26          |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1413 | MCS-2000 Mode   | 1.04           |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1397 | MCS-2000 Mode   | 1.06           |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1402 | MCS-2000 Mode   | 1.2            |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1392 | MCS-2000 Mode   | 1.32           |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ACG0721 | MCS-2000 Mode   | 7.2            |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1406 | MCS-2000 Mode   | 15.18          |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UGM6PW6BN | 722ABE1421 | MCS-2000 Mode   | 41.46          |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UJM6PW6AN | 722AZJ1220 | MCS-2000 Mode   | 1.02           |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UJM6PW6AN | 722AZJ1232 | MCS-2000 Mode   | 4.04           |
| Muskego              | Tess Corners Fire Department              | Motorola | M01UJN6PW6AN | 722AWY1687 | MCS-2000 Mode   | 1.38           |
| Muskego              | Tess Corners Fire Department              | Motorola | M20URS9PW1AN | 500CFV2621 | XTL-5000 Mobile | 2.58           |
| Muskego              | Tess Corners Fire Department              | Motorola | M20URS9PW1AN | 500CFV2620 | XTL-5000 Mobile | 37.52          |
|                      | <b>Tess Corners Fire Department Total</b> |          |              |            |                 | <b>171.3</b>   |
| <b>Muskego Total</b> |   |          |              |            |                 | <b>4019.26</b> |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3005 | MTS-2000 Mode   | 2.02           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS2997 | MTS-2000 Mode   | 3.08           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABE1364 | MTS-2000 Mode   | 3.18           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3007 | MTS-2000 Mode   | 3.58           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS2984 | MTS-2000 Mode   | 4.44           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3002 | MTS-2000 Mode   | 4.58           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3003 | MTS-2000 Mode   | 9.38           |
| Nashotah             | Nashotah Fire Department                  | Motorola | H10UCH6DC5BN | 678SBE1938 | LTS-2000 w/o sc | 4.2            |
| Nashotah             | Nashotah Fire Department                  | Motorola | M01UGM6PW6BN | 722ABS1450 | MCS-2000 Mode   | 1.22           |
|                      | <b>Nashotah Fire Department Total</b>     |          |              |            |                 | <b>35.68</b>   |
| Nashotah             | Nashotah Police Department                | Motorola | H18UCF9PW6AN | 721CJF1295 | XTS-5000 Mode   | 4.42           |
| Nashotah             | Nashotah Police Department                | Motorola | M01UGM6PW6BN | 722ABS1447 | MCS-2000 Mode   | 22.1           |

## September, 2008 Trunked Radio Usage

|                       |   |          |              |            |                 |              |
|-----------------------|---|----------|--------------|------------|-----------------|--------------|
|                       | <b>Nashotah Police Department Total</b>   |          |              |            |                 | <b>26.52</b> |
| Nashotah              | Nashotah Fire Department                  | Motorola | H18UCF9PW6AN | 721CJD4163 | XTS-5000 Mode   | 4.2          |
|                       | <b>Nashotah Fire Department Total</b>     |          |              |            |                 | <b>4.2</b>   |
| <b>Nashotah Total</b> |   |          |              |            |                 | <b>66.4</b>  |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0824 | MTS-2000 Mode   | 1.22         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0916 | MTS-2000 Mode   | 1.4          |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0813 | MTS-2000 Mode   | 2.56         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0816 | MTS-2000 Mode   | 3.2          |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0808 | MTS-2000 Mode   | 3.48         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0789 | MTS-2000 Mode   | 3.56         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0807 | MTS-2000 Mode   | 4.52         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0810 | MTS-2000 Mode   | 5.04         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0787 | MTS-2000 Mode   | 5.08         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0791 | MTS-2000 Mode   | 5.2          |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0821 | MTS-2000 Mode   | 9.02         |
| New Berlin            | New Berlin Fire Department                | Motorola | H01UCD6PW1BN | 466ABQ0759 | MTS-2000 Mode   | 9.46         |
| New Berlin            | New Berlin Fire Department                | Motorola | M01UGM6PW6AN | 722AWE0523 | MCS-2000 Mode   | 5.14         |
| New Berlin            | New Berlin Fire Department                | Motorola | M01UJM6PW6AN | 722AYE2212 | MCS-2000 Mode   | 2            |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0691 | XTL-5000 Mobile | 1.14         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0717 | XTL-5000 Mobile | 2.08         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0714 | XTL-5000 Mobile | 3.1          |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0715 | XTL-5000 Mobile | 3.26         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0712 | XTL-5000 Mobile | 3.44         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0705 | XTL-5000 Mobile | 4.08         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0698 | XTL-5000 Mobile | 4.5          |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0719 | XTL-5000 Mobile | 5.3          |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0707 | XTL-5000 Mobile | 5.32         |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0697 | XTL-5000 Mobile | 15.46        |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0700 | XTL-5000 Mobile | 19.06        |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0720 | XTL-5000 Mobile | 40.28        |
| New Berlin            | New Berlin Fire Department                | Motorola | M20URS9PW1AN | 500CJH0711 | XTL-5000 Mobile | 75.08        |
|                       | <b>New Berlin Fire Department Total</b>   |          |              |            |                 | <b>256</b>   |
| New Berlin            | New Berlin Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBA0832 | LCS-2000 w/sca  | 1.42         |
| New Berlin            | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0723 | XTL-5000 Mobile | 1.06         |
| New Berlin            | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0734 | XTL-5000 Mobile | 1.06         |
| New Berlin            | New Berlin Park and Recreation Department | Motorola | M20URS9PW1AN | 500CJH0721 | XTL-5000 Mobile | 1.1          |

**September, 2008  
Trunked Radio Usage**

|            |  |          |              |            |                 |              |
|------------|--|----------|--------------|------------|-----------------|--------------|
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0727 | XTL-5000 Mobile | 1.1          |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0741 | XTL-5000 Mobile | 1.24         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0735 | XTL-5000 Mobile | 2.32         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0737 | XTL-5000 Mobile | 2.32         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0743 | XTL-5000 Mobile | 3.08         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0728 | XTL-5000 Mobile | 3.34         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0733 | XTL-5000 Mobile | 5.1          |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0731 | XTL-5000 Mobile | 6.28         |
| New Berlin | New Berlin Park and Recreation Department              | Motorola | M20URS9PW1AN | 500CJH0730 | XTL-5000 Mobile | 6.3          |
|            | <b>New Berlin Park and Recreation Department Total</b> |          |              |            |                 | <b>35.72</b> |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3371 | XTS-5000 Mode   | 1.06         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3423 | XTS-5000 Mode   | 1.18         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3472 | XTS-5000 Mode   | 1.22         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3491 | XTS-5000 Mode   | 1.24         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3474 | XTS-5000 Mode   | 2.02         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3514 | XTS-5000 Mode   | 2.12         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3417 | XTS-5000 Mode   | 2.26         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3508 | XTS-5000 Mode   | 2.52         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3424 | XTS-5000 Mode   | 3.04         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3485 | XTS-5000 Mode   | 4.16         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3377 | XTS-5000 Mode   | 4.2          |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3496 | XTS-5000 Mode   | 4.48         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3490 | XTS-5000 Mode   | 6.06         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3419 | XTS-5000 Mode   | 6.22         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3426 | XTS-5000 Mode   | 8.44         |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3422 | XTS-5000 Mode   | 10.28        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3488 | XTS-5000 Mode   | 11           |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3512 | XTS-5000 Mode   | 11.28        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3413 | XTS-5000 Mode   | 11.38        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3487 | XTS-5000 Mode   | 11.56        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3517 | XTS-5000 Mode   | 12.12        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3416 | XTS-5000 Mode   | 12.24        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3486 | XTS-5000 Mode   | 12.28        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3470 | XTS-5000 Mode   | 15.56        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3494 | XTS-5000 Mode   | 16.14        |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3482 | XTS-5000 Mode   | 17           |
| New Berlin | New Berlin Police Department                           | Motorola | H18UCF9PW6AN | 721CJD3412 | XTS-5000 Mode   | 21.14        |

**September, 2008  
Trunked Radio Usage**

|            |                              |          |              |            |                 |         |
|------------|------------------------------|----------|--------------|------------|-----------------|---------|
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3499 | XTS-5000 Mode   | 21.16   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3373 | XTS-5000 Mode   | 21.54   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3479 | XTS-5000 Mode   | 22.14   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3523 | XTS-5000 Mode   | 22.36   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3478 | XTS-5000 Mode   | 23      |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3502 | XTS-5000 Mode   | 24.06   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3507 | XTS-5000 Mode   | 25.24   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3481 | XTS-5000 Mode   | 25.3    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3511 | XTS-5000 Mode   | 25.5    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3469 | XTS-5000 Mode   | 27.22   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3495 | XTS-5000 Mode   | 27.54   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3411 | XTS-5000 Mode   | 28.18   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3425 | XTS-5000 Mode   | 28.22   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3489 | XTS-5000 Mode   | 28.52   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3471 | XTS-5000 Mode   | 29.3    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3415 | XTS-5000 Mode   | 30.38   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3409 | XTS-5000 Mode   | 32.2    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3420 | XTS-5000 Mode   | 32.2    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3524 | XTS-5000 Mode   | 36.36   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3466 | XTS-5000 Mode   | 38.4    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3522 | XTS-5000 Mode   | 38.42   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3475 | XTS-5000 Mode   | 39.08   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3509 | XTS-5000 Mode   | 39.16   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3483 | XTS-5000 Mode   | 42.1    |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3480 | XTS-5000 Mode   | 42.12   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3375 | XTS-5000 Mode   | 42.16   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3497 | XTS-5000 Mode   | 43.54   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3372 | XTS-5000 Mode   | 45.42   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3516 | XTS-5000 Mode   | 45.58   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3379 | XTS-5000 Mode   | 52.14   |
| New Berlin | New Berlin Police Department | Motorola | H18UCF9PW6AN | 721CJD3484 | XTS-5000 Mode   | 58.52   |
| New Berlin | New Berlin Police Department | Motorola | M01UGL6PW4BN | 722ABA0526 | MCS-2000 Mode   | 203.58  |
| New Berlin | New Berlin Police Department | Motorola | M01UGL6PW4BN | 722ABA0527 | MCS-2000 Mode   | 1557.04 |
| New Berlin | New Berlin Police Department | Motorola | M10UGD6DC5BN | 760SAYFM54 | LCS-2000 w/sca  | 114.26  |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0751 | XTL-5000 Mobile | 3.36    |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0778 | XTL-5000 Mobile | 4.18    |
| New Berlin | New Berlin Police Department | Motorola | M20URS9PW1AN | 500CJH0748 | XTL-5000 Mobile | 4.5     |

## September, 2008 Trunked Radio Usage

|            |   |          |              |            |                 |                |
|------------|---|----------|--------------|------------|-----------------|----------------|
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0771 | XTL-5000 Mobile | 4.52           |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0746 | XTL-5000 Mobile | 9.3            |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0786 | XTL-5000 Mobile | 10.1           |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJD1855 | XTL-5000 Mobile | 14.44          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0754 | XTL-5000 Mobile | 15.42          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0787 | XTL-5000 Mobile | 19.32          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0753 | XTL-5000 Mobile | 22.12          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0747 | XTL-5000 Mobile | 23.56          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJD1854 | XTL-5000 Mobile | 30.04          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0775 | XTL-5000 Mobile | 42.12          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0774 | XTL-5000 Mobile | 47.5           |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0752 | XTL-5000 Mobile | 80.48          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0777 | XTL-5000 Mobile | 85             |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0785 | XTL-5000 Mobile | 96.1           |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0769 | XTL-5000 Mobile | 107.06         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0770 | XTL-5000 Mobile | 114.26         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0783 | XTL-5000 Mobile | 124.48         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0779 | XTL-5000 Mobile | 124.56         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0781 | XTL-5000 Mobile | 170.02         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0776 | XTL-5000 Mobile | 177.26         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0772 | XTL-5000 Mobile | 190.34         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0750 | XTL-5000 Mobile | 211.3          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0784 | XTL-5000 Mobile | 228.5          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0782 | XTL-5000 Mobile | 266.14         |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0749 | XTL-5000 Mobile | 277.4          |
| New Berlin | New Berlin Police Department              | Motorola | M20URS9PW1AN | 500CJH0773 | XTL-5000 Mobile | 298.44         |
|            | <b>New Berlin Police Department Total</b> |          |              |            |                 | <b>5925.96</b> |
| New Berlin | New Berlin Street Department              | Motorola | H18UCF9PW6AN | 721CJD3503 | XTS-5000 Mode   | 5.38           |
| New Berlin | New Berlin Street Department              | Motorola | H18UCF9PW6AN | 721CJD3505 | XTS-5000 Mode   | 7.52           |
| New Berlin | New Berlin Street Department              | Motorola | H18UCF9PW6AN | 721CJD3504 | XTS-5000 Mode   | 8.52           |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0825 | XTL-5000 Mobile | 1.4            |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0828 | XTL-5000 Mobile | 2.22           |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0834 | XTL-5000 Mobile | 3.2            |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0809 | XTL-5000 Mobile | 3.5            |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0796 | XTL-5000 Mobile | 3.56           |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0794 | XTL-5000 Mobile | 5.5            |
| New Berlin | New Berlin Street Department              | Motorola | M20URS9PW1AN | 500CJH0832 | XTL-5000 Mobile | 6.46           |

**September, 2008  
Trunked Radio Usage**

|   |   |          |              |            |                 |                |
|---|---|----------|--------------|------------|-----------------|----------------|
| New Berlin                              | New Berlin Street Department                          | Motorola | M20URS9PW1AN | 500CJH0813 | XTL-5000 Mobile | 8.02           |
| New Berlin                              | New Berlin Street Department                          | Motorola | M20URS9PW1AN | 500CJH0814 | XTL-5000 Mobile | 8.04           |
| New Berlin                              | New Berlin Street Department                          | Motorola | M20URS9PW1AN | 500CJH0833 | XTL-5000 Mobile | 13.54          |
|   | <b>New Berlin Street Department Total</b>             |          |              |            |                 | <b>76.86</b>   |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | H18UCF9PW6AN | 721CJD3852 | XTS-5000 Mode   | 6.5            |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0855 | XTL-5000 Mobile | 1.26           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0851 | XTL-5000 Mobile | 1.38           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0856 | XTL-5000 Mobile | 1.42           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0868 | XTL-5000 Mobile | 1.56           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0848 | XTL-5000 Mobile | 2.2            |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0863 | XTL-5000 Mobile | 2.54           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0837 | XTL-5000 Mobile | 4.2            |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0861 | XTL-5000 Mobile | 5.14           |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0849 | XTL-5000 Mobile | 5.3            |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0864 | XTL-5000 Mobile | 7.1            |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0865 | XTL-5000 Mobile | 13.06          |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0842 | XTL-5000 Mobile | 16.12          |
| New Berlin                              | New Berlin Water and Waste Water Utility              | Motorola | M20URS9PW1AN | 500CJH0840 | XTL-5000 Mobile | 29.36          |
|   | <b>New Berlin Water and Waste Water Utility Total</b> |          |              |            |                 | <b>97.14</b>   |
| <b>New Berlin Total</b>                 |   |          |              |            |                 | <b>6391.68</b> |
| North Lake Fire Department              | North Lake Fire Department                            | Motorola | H01UCD6PW1BN | 466ABL3331 | MTS-2000 Mode   | 1.18           |
| North Lake Fire Department              | North Lake Fire Department                            | Motorola | H01UCD6PW1BN | 466ABL3332 | MTS-2000 Mode   | 2.06           |
| North Lake Fire Department              | North Lake Fire Department                            | Motorola | H01UCF6PW1BN | 466ABL3200 | MTS-2000 Mode   | 4.5            |
| North Lake Fire Department              | North Lake Fire Department                            | Motorola | M01UGM6PW6BN | 722ABL1319 | MCS-2000 Mode   | 1.54           |
|   | <b>North Lake Fire Department Total</b>               |          |              |            |                 | <b>9.28</b>    |
| <b>North Lake Fire Department Total</b> |   |          |              |            |                 | <b>9.28</b>    |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H01UCF6PW1BN | 466ABW2947 | MTS-2000 Mode   | 5.3            |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1733 | XTS-5000 Mode   | 3.32           |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1739 | XTS-5000 Mode   | 3.88           |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1750 | XTS-5000 Mode   | 5.1            |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1746 | XTS-5000 Mode   | 6.36           |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1740 | XTS-5000 Mode   | 7.82           |
| North Prairie                           | North Prairie Fire Department                         | Motorola | H18UCH9PW7AN | 721CHF1744 | XTS-5000 Mode   | 13.62          |
| North Prairie                           | North Prairie Fire Department                         | Motorola | M01UGM6PW6AN | 722AWE0896 | MCS-2000 Mode   | 5.46           |
| North Prairie                           | North Prairie Fire Department                         | Motorola | M01UGM6PW6AN | 722AXS0640 | MCS-2000 Mode   | 60.34          |
| North Prairie                           | North Prairie Fire Department                         | Motorola | M20URS9PW1AN | 500CHF4346 | XTL-5000 Dual C | 13.5           |
|   | <b>North Prairie Fire Department Total</b>            |          |              |            |                 | <b>124.7</b>   |

**September, 2008  
Trunked Radio Usage**

|   |  |          |              |            |                 |               |
|---|--|----------|--------------|------------|-----------------|---------------|
| North Prairie                             | North Prairie Police Department                | Motorola | H18UCF9PW6AN | 721CJD4160 | XTS-5000 Mode   | 1.32          |
| North Prairie                             | North Prairie Police Department                | Motorola | H18UCF9PW6AN | 721CJD4161 | XTS-5000 Mode   | 12.48         |
| North Prairie                             | North Prairie Police Department                | Motorola | M01UGM6PW6BN | 722ABS1446 | MCS-2000 Mode   | 9.42          |
| North Prairie                             | North Prairie Police Department                | Motorola | M01UGM6PW6BN | 722ABS1444 | MCS-2000 Mode   | 47.26         |
|   | <b>North Prairie Police Department Total</b>   |          |              |            |                 | <b>70.48</b>  |
| <b>North Prairie Total</b>                |  |          |              |            |                 | <b>195.18</b> |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | H01UCD6PW1BN | 466ABE4853 | MTS-2000 Mode   | 1.04          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | H01UCD6PW1BN | 466ABE4847 | MTS-2000 Mode   | 1.16          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | H01UCD6PW1BN | 466ABE4872 | MTS-2000 Mode   | 2.58          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | H01UCD6PW1BN | 466ABE4888 | MTS-2000 Mode   | 3.02          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | H01UCD6PW1BN | 466ABE4889 | MTS-2000 Mode   | 3.52          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | M01UJM6PW6AN | 722AXY0620 | MCS-2000 Mode   | 1.52          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | M01UJM6PW6AN | 722AYE2079 | MCS-2000 Mode   | 4.94          |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | M01UJM6PW6AN | 722AXY0619 | MCS-2000 Mode   | 6.6           |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | M01UJM6PW6AN | 722AXY0623 | MCS-2000 Mode   | 19.06         |
| Oconomowoc Lake                           | Oconomowoc Lake Police Department              | Motorola | M01UJM6PW6AN | 722AYE2613 | MCS-2000 Mode   | 55.24         |
|   | <b>Oconomowoc Lake Police Department Total</b> |          |              |            |                 | <b>98.68</b>  |
| <b>Oconomowoc Lake Total</b>              |  |          |              |            |                 | <b>98.68</b>  |
| Oconomowoc Memorial Hospital              | Oconomowoc Memorial Hospital                   | Motorola | L04UJH9PW9AN | 761CDA0111 | Base, low power | 43.38         |
|   | <b>Oconomowoc Memorial Hospital Total</b>      |          |              |            |                 | <b>43.38</b>  |
| <b>Oconomowoc Memorial Hospital Total</b> |  |          |              |            |                 | <b>43.38</b>  |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | H46UCF9PW6BN | 205CJF0403 | XTS-2500 Mode   | 2.56          |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | H46UCF9PW6BN | 205CJF0514 | XTS-2500 Mode   | 27.54         |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SBQ0922 | LCS-2000 w/sca  | 1.2           |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SBQ0905 | LCS-2000 w/sca  | 1.44          |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SBQ0911 | LCS-2000 w/sca  | 2.2           |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SBQ0920 | LCS-2000 w/sca  | 2.22          |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SEW0027 | LCS-2000 w/sca  | 5.46          |
| Oconomowoc, City                          | Oconomowoc City DPW                            | Motorola | M10UGD6DC5BN | 760SBQ0899 | LCS-2000 w/sca  | 7.48          |
|   | <b>Oconomowoc City DPW Total</b>               |          |              |            |                 | <b>50.1</b>   |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466ABE2330 | MTS-2000 Mode   | 1.16          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466ABE2318 | MTS-2000 Mode   | 1.18          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466CFH0302 | MTS-2000 Mode   | 1.24          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466CFH0298 | MTS-2000 Mode   | 2.24          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466ABE1367 | MTS-2000 Mode   | 2.54          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466ABE2333 | MTS-2000 Mode   | 6.04          |
| Oconomowoc, City                          | Oconomowoc City Fire Department                | Motorola | H01UCD6PW1BN | 466ABE2326 | MTS-2000 Mode   | 6.24          |

## September, 2008 Trunked Radio Usage

|                  |  |          |              |            |                 |               |
|------------------|--|----------|--------------|------------|-----------------|---------------|
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H01UCD6PW1BN | 466CFH0300 | MTS-2000 Mode   | 10.32         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H01UCD6PW1BN | 466CFH0304 | MTS-2000 Mode   | 14.66         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H01UCD6PW1BN | 466CFH0301 | MTS-2000 Mode   | 18.4          |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H01UCD6PW1BN | 466ABE5031 | MTS-2000 Mode   | 41            |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H01UCD6PW1BN | 466CFH0299 | MTS-2000 Mode   | 73.26         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | H18UCF9PW6AN | 721CFC0895 | XTS-5000 Mode   | 16.84         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1436 | MCS-2000 Mode   | 1.5           |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722CFH1799 | MCS-2000 Mode   | 4.34          |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1375 | MCS-2000 Mode   | 5.58          |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1373 | MCS-2000 Mode   | 11.42         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1376 | MCS-2000 Mode   | 12.9          |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1457 | MCS-2000 Mode   | 15.44         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722CFH1797 | MCS-2000 Mode   | 20.22         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1365 | MCS-2000 Mode   | 148.04        |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2223 | MCS-2000 Mode   | 18.32         |
| Oconomowoc, City | Oconomowoc City Fire Department              | Motorola | M20URS9PW1AN | 500CHX1273 | XTL-5000 Mobile | 90.38         |
|                  | <b>Oconomowoc City Fire Department Total</b> |          |              |            |                 | <b>523.26</b> |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | H46UCF9PW6BN | 205CJF0402 | XTS-2500 Mode   | 10.08         |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | H46UCF9PW6BN | 205CJF0515 | XTS-2500 Mode   | 14.32         |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | H46UCF9PW6BN | 205CJF0512 | XTS-2500 Mode   | 26.28         |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SBQ0067 | LCS-2000 w/sca  | 1.2           |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SBQ0111 | LCS-2000 w/sca  | 1.3           |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SAW0976 | LCS-2000 w/sca  | 4.08          |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SAW2749 | LCS-2000 w/sca  | 4.2           |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SAW3389 | LCS-2000 w/sca  | 4.54          |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SAW0986 | LCS-2000 w/sca  | 5.18          |
| Oconomowoc, City | Oconomowoc City Parks                        | Motorola | M10UGD6DC5BN | 760SBQ0068 | LCS-2000 w/sca  | 10.2          |
|                  | <b>Oconomowoc City Parks Total</b>           |          |              |            |                 | <b>81.38</b>  |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE1381 | MTS-2000 Mode   | 3.5           |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4929 | MTS-2000 Mode   | 7.56          |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE1373 | MTS-2000 Mode   | 9.12          |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4919 | MTS-2000 Mode   | 18.2          |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE2322 | MTS-2000 Mode   | 38.32         |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE5011 | MTS-2000 Mode   | 42.06         |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE2306 | MTS-2000 Mode   | 53.4          |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE4924 | MTS-2000 Mode   | 56.04         |
| Oconomowoc, City | Oconomowoc City Police Department            | Motorola | H01UCD6PW1BN | 466ABE2292 | MTS-2000 Mode   | 59.2          |

## September, 2008 Trunked Radio Usage

|                  |  |          |              |            |                |                |
|------------------|--|----------|--------------|------------|----------------|----------------|
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H01UCD6PW1BN | 466ABE2303 | MTS-2000 Mode  | 59.96          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H01UCD6PW1BN | 466ABE1363 | MTS-2000 Mode  | 61.98          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H01UCD6PW1BN | 466ABE4918 | MTS-2000 Mode  | 66.3           |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H01UCD6PW1BN | 466ABE2298 | MTS-2000 Mode  | 72.46          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H01UCD6PW1BN | 466ABE1365 | MTS-2000 Mode  | 129.38         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H18UCF9PW6AN | 721CFC0887 | XTS-5000 Mode  | 1.14           |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | H18UCF9PW6AN | 721CFC0882 | XTS-5000 Mode  | 7.32           |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGL6PW4BN | 722ABE3135 | MCS-2000 Mode  | 10.58          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGL6PW4BN | 722ABE3137 | MCS-2000 Mode  | 41.38          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGL6PW4BN | 722ABE3131 | MCS-2000 Mode  | 107.32         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGL6PW4BN | 722ABE3133 | MCS-2000 Mode  | 820.14         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1388 | MCS-2000 Mode  | 7.28           |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1369 | MCS-2000 Mode  | 11.04          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1378 | MCS-2000 Mode  | 15.26          |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1380 | MCS-2000 Mode  | 140.92         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1396 | MCS-2000 Mode  | 187.78         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1399 | MCS-2000 Mode  | 304.02         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1389 | MCS-2000 Mode  | 327.58         |
| Oconomowoc, City | Oconomowoc City Police Department              | Motorola | M01UGM6PW6BN | 722ABS1386 | MCS-2000 Mode  | 338.5          |
|                  | <b>Oconomowoc City Police Department Total</b> |          |              |            |                | <b>2997.74</b> |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | H46UCF9PW6BN | 205CJF0543 | XTS-2500 Mode  | 2.26           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | H46UCF9PW6BN | 205CJF0546 | XTS-2500 Mode  | 4.38           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | H46UCF9PW6BN | 205CJF0547 | XTS-2500 Mode  | 6.18           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M01UJM6PW6AN | 722AXY0621 | MCS-2000 Mode  | 1.18           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M01UJM6PW6AN | 722AYE2565 | MCS-2000 Mode  | 1.48           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M01UJM6PW6AN | 722AXY0626 | MCS-2000 Mode  | 17.26          |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SEE0202 | LCS-2000 w/sca | 1.3            |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SAW0918 | LCS-2000 w/sca | 2.1            |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SAW0985 | LCS-2000 w/sca | 2.36           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0940 | LCS-2000 w/sca | 2.5            |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0793 | LCS-2000 w/sca | 4.38           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0949 | LCS-2000 w/sca | 6              |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0906 | LCS-2000 w/sca | 6.52           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0947 | LCS-2000 w/sca | 7.56           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0931 | LCS-2000 w/sca | 8.24           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0946 | LCS-2000 w/sca | 9.32           |
| Oconomowoc, City | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760scl0545 | LCS-2000 w/sca | 9.36           |

**September, 2008  
Trunked Radio Usage**

|                               |  |          |              |            |                 |                |
|-------------------------------|--|----------|--------------|------------|-----------------|----------------|
| Oconomowoc, City              | Oconomowoc City Utilities                      | Motorola | M10UGD6DC5BN | 760SBQ0895 | LCS-2000 w/sca  | 9.54           |
| Oconomowoc, City              | Oconomowoc City Utilities                      | Motorola | M28URS9PW1AN | 775TGA1715 | XTL-1500 Mobile | 6.22           |
|                               | <b>Oconomowoc City Utilities Total</b>         |          |              |            |                 | <b>108.14</b>  |
| Oconomowoc, City              | Oconomowoc City Wastewater                     | Motorola | H46UCF9PW6BN | 205CJF0410 | XTS-2500 Mode   | 3.02           |
| Oconomowoc, City              | Oconomowoc City Wastewater                     | Motorola | M10UGD6DC5BN | 760SAW0962 | LCS-2000 w/sca  | 3.42           |
|                               | <b>Oconomowoc City Wastewater Total</b>        |          |              |            |                 | <b>6.44</b>    |
| <b>Oconomowoc, City Total</b> |  |          |              |            |                 | <b>3767.06</b> |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2996 | MTS-2000 Mode   | 5.04           |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABE1370 | MTS-2000 Mode   | 5.86           |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2986 | MTS-2000 Mode   | 6.28           |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2980 | MTS-2000 Mode   | 8.8            |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2994 | MTS-2000 Mode   | 10.96          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2993 | MTS-2000 Mode   | 14.38          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2987 | MTS-2000 Mode   | 15.16          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2895 | MTS-2000 Mode   | 23.12          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2982 | MTS-2000 Mode   | 24.68          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2992 | MTS-2000 Mode   | 27.66          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | H01UCD6PW1BN | 466ABS2983 | MTS-2000 Mode   | 35.18          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1384 | MCS-2000 Mode   | 4.58           |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722CEG1778 | MCS-2000 Mode   | 8.8            |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1356 | MCS-2000 Mode   | 10.3           |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1394 | MCS-2000 Mode   | 20.98          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1402 | MCS-2000 Mode   | 39.68          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1393 | MCS-2000 Mode   | 56.74          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1382 | MCS-2000 Mode   | 173.28         |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M01UGM6PW6BN | 722ABS1387 | MCS-2000 Mode   | 188.6          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M10UGD6DC5BN | 760SBQ0120 | LCS-2000 w/sca  | 10.42          |
| Oconomowoc, Town              | Oconomowoc Town Police Department              | Motorola | M21URM9PW2AN | 624CJP0444 | XTL-2500RB      | 10.42          |
|                               | <b>Oconomowoc Town Police Department Total</b> |          |              |            |                 | <b>700.92</b>  |
| Oconomowoc, Town              | Oconomowoc Town Public Works                   | Motorola | M10UGD6DC5BN | 760SBQ0097 | LCS-2000 w/sca  | 2.26           |
| Oconomowoc, Town              | Oconomowoc Town Public Works                   | Motorola | M10UGD6DC5BN | 760SBQ0100 | LCS-2000 w/sca  | 4.22           |
| Oconomowoc, Town              | Oconomowoc Town Public Works                   | Motorola | M21URM9PW2AN | 624CJP0445 | XTL-2500RB      | 2.26           |
| Oconomowoc, Town              | Oconomowoc Town Public Works                   | Motorola | M21URM9PW2AN | 624CJP0447 | XTL-2500RB      | 4.22           |
|                               | <b>Oconomowoc Town Public Works Total</b>      |          |              |            |                 | <b>12.96</b>   |
| <b>Oconomowoc, Town Total</b> |  |          |              |            |                 | <b>713.88</b>  |
| Okauchee Fire Department      | Okauchee Fire Department                       | Motorola | H01UCD6PW1BN | 466ABS3031 | MTS-2000 Mode   | 3.08           |
| Okauchee Fire Department      | Okauchee Fire Department                       | Motorola | H01UCD6PW1BN | 466ABS3032 | MTS-2000 Mode   | 5.04           |

## September, 2008 Trunked Radio Usage

|                                       |                                       |          |              |            |               |              |
|---------------------------------------|---------------------------------------|----------|--------------|------------|---------------|--------------|
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3044 | MTS-2000 Mode | 5.18         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3030 | MTS-2000 Mode | 6.56         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3051 | MTS-2000 Mode | 7.14         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3043 | MTS-2000 Mode | 10.58        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3036 | MTS-2000 Mode | 14.68        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3046 | MTS-2000 Mode | 20.94        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3045 | MTS-2000 Mode | 24.78        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS3004 | MTS-2000 Mode | 58.74        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H01UCH6PW1BN | 466abc0151 | MTS-2000 Mode | 14.22        |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H46UCF9PW6BN | 205CHT3038 | XTS-2500 Mode | 2.06         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H46UCF9PW6BN | 205CHB0342 | XTS-2500 Mode | 2.3          |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H46UCF9PW6BN | 205CHT3039 | XTS-2500 Mode | 2.48         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | H46UCF9PW6BN | 205CHB0343 | XTS-2500 Mode | 9.46         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2810 | MCS-2000 Mode | 1.02         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | M01UJM6PW6AN | 722AXY0637 | MCS-2000 Mode | 2.34         |
| Okauchee Fire Department              | Okauchee Fire Department              | Motorola | M01UJM6PW6AN | 722AYE2667 | MCS-2000 Mode | 7.6          |
|                                       | <b>Okauchee Fire Department Total</b> |          |              |            |               | <b>198.2</b> |
| <b>Okauchee Fire Department Total</b> |                                       |          |              |            |               | <b>198.2</b> |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2916 | MTS-2000 Mode | 1.2          |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2975 | MTS-2000 Mode | 1.22         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2973 | MTS-2000 Mode | 1.44         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2923 | MTS-2000 Mode | 2.1          |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2912 | MTS-2000 Mode | 2.12         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2977 | MTS-2000 Mode | 2.26         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2913 | MTS-2000 Mode | 2.34         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2971 | MTS-2000 Mode | 3.22         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABE1380 | MTS-2000 Mode | 3.32         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2902 | MTS-2000 Mode | 3.58         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2920 | MTS-2000 Mode | 4.22         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABE1371 | MTS-2000 Mode | 4.88         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABE4934 | MTS-2000 Mode | 5.78         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2988 | MTS-2000 Mode | 6.28         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABE1375 | MTS-2000 Mode | 8.22         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2976 | MTS-2000 Mode | 9.38         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCD6PW1BN | 466ABE1379 | MTS-2000 Mode | 24.24        |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCF6PW1BN | 466ABE1902 | MTS-2000 Mode | 1.18         |
| Pewaukee Fire Department              | Pewaukee Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3422 | MTS-2000 Mode | 5.32         |

## September, 2008 Trunked Radio Usage

|                                       |   |          |              |            |                 |               |
|---------------------------------------|---|----------|--------------|------------|-----------------|---------------|
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABS3431 | MTS-2000 Mode   | 6.52          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABE1877 | MTS-2000 Mode   | 8.32          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABS3438 | MTS-2000 Mode   | 8.9           |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABS3428 | MTS-2000 Mode   | 9.26          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABS3417 | MTS-2000 Mode   | 10.6          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ABE1887 | MTS-2000 Mode   | 10.88         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | H01UCF6PW1BN | 466ACE1996 | MTS-2000 Mode   | 57.76         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M01UGM6PW6AN | 722AWE0425 | MCS-2000 Mode   | 1.32          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M01UGM6PW6BN | 722ACE1413 | MCS-2000 Mode   | 25.36         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M10UGD6DC5BN | 760SBS0944 | LCS-2000 w/sca  | 15.54         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0455 | XTL-2500RB      | 1.52          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0472 | XTL-2500RB      | 2.44          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0462 | XTL-2500RB      | 2.5           |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0463 | XTL-2500RB      | 3.18          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0461 | XTL-2500RB      | 5.1           |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0470 | XTL-2500RB      | 6.38          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0924 | XTL-2500RB      | 15.3          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0458 | XTL-2500RB      | 15.54         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0457 | XTL-2500RB      | 19.46         |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0467 | XTL-2500RB      | 27.2          |
| Pewaukee Fire Department              | Pewaukee Fire Department                    | Motorola | M21URM9PW2AN | 624CJP0469 | XTL-2500RB      | 53.56         |
|                                       | <b>Pewaukee Fire Department Total</b>       |          |              |            |                 | <b>398.94</b> |
| <b>Pewaukee Fire Department Total</b> |   |          |              |            |                 | <b>398.94</b> |
| Pewaukee, City                        | Pewaukee City Parks Department              | Motorola | M10UGD6DC5BN | 760SBS1206 | LCS-2000 w/sca  | 1.22          |
| Pewaukee, City                        | Pewaukee City Parks Department              | Motorola | M10UGD6DC5BN | 760SBS0724 | LCS-2000 w/o sc | 1.32          |
| Pewaukee, City                        | Pewaukee City Parks Department              | Motorola | M10UGD6DC5BN | 760SBS1175 | LCS-2000 w/sca  | 1.58          |
|                                       | <b>Pewaukee City Parks Department Total</b> |          |              |            |                 | <b>4.12</b>   |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS3059 | MTS-2000 Mode   | 1.06          |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS3053 | MTS-2000 Mode   | 1.2           |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS3063 | MTS-2000 Mode   | 1.4           |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2882 | MTS-2000 Mode   | 2.5           |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2883 | MTS-2000 Mode   | 6.62          |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2898 | MTS-2000 Mode   | 8.62          |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2896 | MTS-2000 Mode   | 8.86          |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2886 | MTS-2000 Mode   | 9.36          |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS3057 | MTS-2000 Mode   | 10.56         |
| Pewaukee, City                        | Pewaukee City Police Department             | Motorola | H01UCD6PW1BN | 466ABS2887 | MTS-2000 Mode   | 10.58         |

## September, 2008 Trunked Radio Usage

|                |  |          |              |            |                 |                |
|----------------|--|----------|--------------|------------|-----------------|----------------|
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2897 | MTS-2000 Mode   | 11.16          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2889 | MTS-2000 Mode   | 12.82          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2890 | MTS-2000 Mode   | 15.94          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2894 | MTS-2000 Mode   | 19.16          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H01UCD6PW1BN | 466ABS2892 | MTS-2000 Mode   | 27.38          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0139 | XTS-5000 Mode   | 2.04           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0126 | XTS-5000 Mode   | 3.92           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CFC0903 | XTS-5000 Mode   | 6.92           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0131 | XTS-5000 Mode   | 7.58           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0130 | XTS-5000 Mode   | 8.68           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0135 | XTS-5000 Mode   | 9              |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CFC0900 | XTS-5000 Mode   | 13.32          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0140 | XTS-5000 Mode   | 19.38          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CEG0134 | XTS-5000 Mode   | 28.56          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CFC0899 | XTS-5000 Mode   | 32.42          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | H18UCF9PW6AN | 721CFC0891 | XTS-5000 Mode   | 39.2           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0857 | MCS-2000 Mode   | 3.26           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0850 | MCS-2000 Mode   | 6.5            |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722CDY2377 | MCS-2000 Mode   | 8.52           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0858 | MCS-2000 Mode   | 22.2           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722CDY2378 | MCS-2000 Mode   | 23.88          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0853 | MCS-2000 Mode   | 25.62          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0855 | MCS-2000 Mode   | 53.44          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0852 | MCS-2000 Mode   | 92.1           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722CEN2073 | MCS-2000 Mode   | 122.06         |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0851 | MCS-2000 Mode   | 139.58         |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0859 | MCS-2000 Mode   | 140.86         |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UGM6PW6BN | 722ABW0856 | MCS-2000 Mode   | 161.3          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UJM6PW6AN | 722AYL0951 | MCS-2000 Mode   | 4.76           |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | M01UJM6PW6AN | 722AYL0949 | MCS-2000 Mode   | 68.66          |
| Pewaukee, City | Pewaukee City Police Department                    | Motorola | m21urm9pw1an | 514CGT1198 | XTL-2500 Mobile | 4.4            |
|                | <b>Pewaukee City Police Department Total</b>       |          |              |            |                 | <b>1195.38</b> |
| Pewaukee, City | Pewaukee City Public Works Department              | Motorola | m10ugd6dc5bn | 760sbs1202 | LCS-2000 w/sca  | 1.02           |
| Pewaukee, City | Pewaukee City Public Works Department              | Motorola | m10ugd6dc5bn | 760sbs1172 | LCS-2000 w/sca  | 1.52           |
| Pewaukee, City | Pewaukee City Public Works Department              | Motorola | m10ugd6dc5bn | 760sbs0203 | LCS-2000 w/sca  | 2.28           |
| Pewaukee, City | Pewaukee City Public Works Department              | Motorola | M10UGD6DC5BN | 760SBS1214 | LCS-2000 w/sca  | 6.4            |
|                | <b>Pewaukee City Public Works Department Total</b> |          |              |            |                 | <b>11.22</b>   |

**September, 2008  
Trunked Radio Usage**

|                                |  |          |              |            |                 |                |
|--------------------------------|--|----------|--------------|------------|-----------------|----------------|
| <b>Pewaukee, City Total</b>    |  |          |              |            |                 | <b>1210.72</b> |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466CFE0298 | MTS-2000 Mode   | 3.64           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2309 | MTS-2000 Mode   | 5.9            |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466CFE0117 | MTS-2000 Mode   | 6.02           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE1382 | MTS-2000 Mode   | 6.22           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE1378 | MTS-2000 Mode   | 7.18           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2310 | MTS-2000 Mode   | 11.98          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2313 | MTS-2000 Mode   | 13.22          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE1377 | MTS-2000 Mode   | 15.78          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466abs3061 | MTS-2000 Mode   | 16.22          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2289 | MTS-2000 Mode   | 18.16          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE1369 | MTS-2000 Mode   | 18.64          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2314 | MTS-2000 Mode   | 18.82          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2307 | MTS-2000 Mode   | 27.9           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE1384 | MTS-2000 Mode   | 32.02          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | H01UCD6PW1BN | 466ABE2316 | MTS-2000 Mode   | 39.62          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ACE1415 | MCS-2000 Mode   | 2.12           |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ABS1411 | MCS-2000 Mode   | 14.02          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ABS1391 | MCS-2000 Mode   | 59.58          |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ABS1383 | MCS-2000 Mode   | 92             |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ABS1392 | MCS-2000 Mode   | 153.06         |
| Pewaukee, Village              | Pewaukee Village Police Department                     | Motorola | M01UGM6PW6BN | 722ABS1406 | MCS-2000 Mode   | 168.7          |
|                                | <b>Pewaukee Village Police Department Total</b>        |          |              |            |                 | <b>730.8</b>   |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | H10UCH6DC5BN | 678SBN0727 | LTS-2000 w/o sc | 1.08           |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | H46UCF9PW6BN | 205CJF0504 | XTS-2500 Mode   | 1.08           |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | M10UGD6DC5BN | 760SBN0362 | LCS-2000 w/o sc | 1.14           |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | M10UGD6DC5BN | 760SBN0238 | LCS-2000 w/o sc | 1.24           |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | M10UGD6DC5BN | 760SBN0004 | LCS-2000 w/o sc | 1.38           |
| Pewaukee, Village              | Pewaukee Village Public Works Departments              | Motorola | M10UGD6DC5BN | 760SBN0234 | LCS-2000 w/o sc | 8.08           |
|                                | <b>Pewaukee Village Public Works Departments Total</b> |          |              |            |                 | <b>14</b>      |
| <b>Pewaukee, Village Total</b> |  |          |              |            |                 | <b>744.8</b>   |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0642 | XTS-2500 Mode   | 1.02           |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0637 | XTS-2500 Mode   | 1.26           |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0646 | XTS-2500 Mode   | 2.04           |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0647 | XTS-2500 Mode   | 2.2            |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0650 | XTS-2500 Mode   | 3.34           |
| Stone Bank Fire Department     | Stone Bank Fire Department                             | Motorola | H46UCF9PW6BN | 205CJF0641 | XTS-2500 Mode   | 4.08           |

**September, 2008  
Trunked Radio Usage**

|   |   |          |              |            |               |               |
|---|---|----------|--------------|------------|---------------|---------------|
| Stone Bank Fire Department              | Stone Bank Fire Department              | Motorola | H46UCH9PW7AN | 205CFP1185 | XTS-2500 Mode | 7.66          |
| Stone Bank Fire Department              | Stone Bank Fire Department              | Motorola | M21URM9PW2AN | 624CJK0846 | XTL-2500RB    | 1.04          |
| Stone Bank Fire Department              | Stone Bank Fire Department              | Motorola | M21URM9PW2AN | 624CJK0845 | XTL-2500RB    | 1.24          |
| Stone Bank Fire Department              | Stone Bank Fire Department              | Motorola | M21URM9PW2AN | 624CJK0848 | XTL-2500RB    | 2.04          |
| Stone Bank Fire Department              | Stone Bank Fire Department              | Motorola | M21URM9PW2AN | 624CJK0840 | XTL-2500RB    | 11.32         |
|   | <b>Stone Bank Fire Department Total</b> |          |              |            |               | <b>37.24</b>  |
| <b>Stone Bank Fire Department Total</b> |   |          |              |            |               | <b>37.24</b>  |
| Summit                                  | Summit Highway Department               | Motorola | M21URM9PW2AN | 624CJK1057 | XTL-2500RB    | 1.34          |
| Summit                                  | Summit Highway Department               | Motorola | M21URM9PW2AN | 624CJK1046 | XTL-2500RB    | 3.2           |
| Summit                                  | Summit Highway Department               | Motorola | M21URM9PW2AN | 624CJK1060 | XTL-2500RB    | 4.18          |
| Summit                                  | Summit Highway Department               | Motorola | M21URM9PW2AN | 624CJK1045 | XTL-2500RB    | 6.42          |
| Summit                                  | Summit Highway Department               | Motorola | M21URM9PW2AN | 624CJK1048 | XTL-2500RB    | 9.12          |
|   | <b>Summit Highway Department Total</b>  |          |              |            |               | <b>24.26</b>  |
| Summit                                  | Summit Police Department                | Motorola | H01UCD6PW1BN | 466AUL3029 | MTS-2000 Mode | 1.24          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4353 | XTS-5000 Mode | 2.22          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4347 | XTS-5000 Mode | 2.78          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4352 | XTS-5000 Mode | 6.12          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CFC0886 | XTS-5000 Mode | 6.46          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CFC0885 | XTS-5000 Mode | 6.72          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CFC0884 | XTS-5000 Mode | 6.8           |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4344 | XTS-5000 Mode | 7.18          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4351 | XTS-5000 Mode | 7.86          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CFC0883 | XTS-5000 Mode | 8.44          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4345 | XTS-5000 Mode | 9.02          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4354 | XTS-5000 Mode | 9.28          |
| Summit                                  | Summit Police Department                | Motorola | H18UCF9PW6AN | 721CJD4348 | XTS-5000 Mode | 13.04         |
| Summit                                  | Summit Police Department                | Motorola | M01UGM6PW6BN | 722ABL1313 | MCS-2000 Mode | 9.9           |
| Summit                                  | Summit Police Department                | Motorola | M01UGM6PW6BN | 722ABL1308 | MCS-2000 Mode | 33.32         |
| Summit                                  | Summit Police Department                | Motorola | M01UGM6PW6BN | 722ABL1338 | MCS-2000 Mode | 45.18         |
| Summit                                  | Summit Police Department                | Motorola | M01UGM6PW6BN | 722ABL1306 | MCS-2000 Mode | 116.52        |
| Summit                                  | Summit Police Department                | Motorola | M21URM9PW2AN | 624CJK1066 | XTL-2500RB    | 3.38          |
|   | <b>Summit Police Department Total</b>   |          |              |            |               | <b>295.46</b> |
| <b>Summit Total</b>                     |   |          |              |            |               | <b>319.72</b> |
| Summit Fire District                    | Summit Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS2999 | MTS-2000 Mode | 3.16          |
| Summit Fire District                    | Summit Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3009 | MTS-2000 Mode | 6.06          |
| Summit Fire District                    | Summit Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3019 | MTS-2000 Mode | 11.4          |
| Summit Fire District                    | Summit Fire Department                  | Motorola | H01UCD6PW1BN | 466ABS3017 | MTS-2000 Mode | 13.66         |

**September, 2008  
Trunked Radio Usage**

|                                   |                                     |          |              |            |                 |               |
|-----------------------------------|-------------------------------------|----------|--------------|------------|-----------------|---------------|
| Summit Fire District              | Summit Fire Department              | Motorola | H01UCF6PW1BN | 466ABW2342 | MTS-2000 Mode   | 1.22          |
| Summit Fire District              | Summit Fire Department              | Motorola | H01UCF6PW1BN | 466AUA0026 | MTS-2000 Mode   | 2.02          |
| Summit Fire District              | Summit Fire Department              | Motorola | H01UCF6PW1BN | 466ABW4099 | MTS-2000 Mode   | 2.04          |
| Summit Fire District              | Summit Fire Department              | Motorola | H01UCF6PW1BN | 466ABW4471 | MTS-2000 Mode   | 5.22          |
| Summit Fire District              | Summit Fire Department              | Motorola | H01UCF6PW1BN | 466AVS2206 | MTS-2000 Mode   | 7.32          |
| Summit Fire District              | Summit Fire Department              | Motorola | M01UJM6PW6AN | 722AXY0629 | MCS-2000 Mode   | 1.18          |
| Summit Fire District              | Summit Fire Department              | Motorola | M01UJM6PW6AN | 722AXY0632 | MCS-2000 Mode   | 1.44          |
| Summit Fire District              | Summit Fire Department              | Motorola | M01UJM6PW6AN | 722AXY0628 | MCS-2000 Mode   | 2.22          |
|                                   | <b>Summit Fire Department Total</b> |          |              |            |                 | <b>56.94</b>  |
| <b>Summit Fire District Total</b> |                                     |          |              |            |                 | <b>56.94</b>  |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3392 | MTS-2000 Mode   | 1.02          |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3377 | MTS-2000 Mode   | 1.26          |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3376 | MTS-2000 Mode   | 1.56          |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3413 | MTS-2000 Mode   | 2             |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3379 | MTS-2000 Mode   | 3.1           |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3390 | MTS-2000 Mode   | 4.42          |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3409 | MTS-2000 Mode   | 4.6           |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3408 | MTS-2000 Mode   | 7.12          |
| Sussex                            | Sussex Fire Department              | Motorola | H01UCF6PW1BN | 466ABS3380 | MTS-2000 Mode   | 11.4          |
| Sussex                            | Sussex Fire Department              | Motorola | H46UCF9PW6BN | 205CGV3324 | XTS-2500 Mode   | 2.28          |
| Sussex                            | Sussex Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1459 | MCS-2000 Mode   | 31.42         |
| Sussex                            | Sussex Fire Department              | Motorola | M10UGD6DC5BN | 760SBQ0043 | LCS-2000 w/sca  | 1.14          |
| Sussex                            | Sussex Fire Department              | Motorola | M10UGD6DC5BN | 760SBQ0039 | LCS-2000 w/sca  | 2.06          |
| Sussex                            | Sussex Fire Department              | Motorola | M10UGD6DC5BN | 760SBQ0078 | LCS-2000 w/sca  | 3.56          |
| Sussex                            | Sussex Fire Department              | Motorola | M10UGD6DC5BN | 760SAW0973 | LCS-2000 w/sca  | 13.56         |
| Sussex                            | Sussex Fire Department              | Motorola | M20URS9PW1AN | 500CJK1030 | XTL-5000 Mobile | 1.14          |
| Sussex                            | Sussex Fire Department              | Motorola | M20URS9PW1AN | 500CJK1031 | XTL-5000 Mobile | 2.06          |
| Sussex                            | Sussex Fire Department              | Motorola | M20URS9PW1AN | 500CJK1035 | XTL-5000 Mobile | 3.56          |
| Sussex                            | Sussex Fire Department              | Motorola | M20URS9PW1AN | 500CJK1026 | XTL-5000 Mobile | 13.56         |
|                                   | <b>Sussex Fire Department Total</b> |          |              |            |                 | <b>110.82</b> |
| <b>Sussex Total</b>               |                                     |          |              |            |                 | <b>110.82</b> |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466ABL3203 | MTS-2000 Mode   | 1.3           |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466ABL3156 | MTS-2000 Mode   | 1.32          |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466ABL3223 | MTS-2000 Mode   | 1.4           |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466AZY5344 | MTS-2000 Mode   | 1.48          |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466ABL3159 | MTS-2000 Mode   | 2.06          |
| Wales/Genesee Fire Department     | Wales/Genesee Fire Department       | Motorola | H01UCF6PW1BN | 466ABL3164 | MTS-2000 Mode   | 2.5           |

## September, 2008 Trunked Radio Usage

|  |  |          |              |            |               |              |
|--|--|----------|--------------|------------|---------------|--------------|
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | H01UCF6PW1BN | 466ABL3154 | MTS-2000 Mode | 3.76         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | H01UCF6PW1BN | 466ABL3221 | MTS-2000 Mode | 6.54         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | H01UCF6PW1BN | 466ABL3177 | MTS-2000 Mode | 11.62        |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | H01UCF6PW1BN | 466ABL3189 | MTS-2000 Mode | 16.04        |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1304 | MCS-2000 Mode | 1.38         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1342 | MCS-2000 Mode | 1.58         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1315 | MCS-2000 Mode | 2.78         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1301 | MCS-2000 Mode | 3.12         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1310 | MCS-2000 Mode | 8.02         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1314 | MCS-2000 Mode | 8.08         |
| Wales/Genesee Fire Department              | Wales/Genesee Fire Department              | Motorola | M01UGM6PW6BN | 722ABL1339 | MCS-2000 Mode | 14.28        |
|  | <b>Wales/Genesee Fire Department Total</b> |          |              |            |               | <b>87.26</b> |
| <b>Wales/Genesee Fire Department Total</b> |  |          |              |            |               | <b>87.26</b> |
| Waukesha County                            | Waukesha County Communications             | Motorola | M01UGL6PW4BN | 722CEC0629 | MCS-2000 Mode | 2.06         |
| Waukesha County                            | Waukesha County Communications             | Motorola | M01UGM6PW6BN | 722CEC0649 | MCS-2000 Mode | 33.02        |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758809   | None          | 1.02         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759102   | None          | 1.04         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758144   | None          | 1.08         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758810   | None          | 1.12         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758302   | None          | 1.26         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758702   | None          | 1.3          |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759228   | None          | 1.36         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759328   | None          | 1.38         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758609   | None          | 1.42         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759008   | None          | 1.48         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759245   | None          | 1.56         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758307   | None          | 2            |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758614   | None          | 2.04         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758209   | None          | 2.1          |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758804   | None          | 2.12         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759104   | None          | 2.16         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758802   | None          | 2.24         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758501   | None          | 2.44         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758814   | None          | 2.58         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID759145   | None          | 3.12         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758604   | None          | 3.54         |
| Waukesha County                            | Waukesha County Communications             | Motorola | UNIT ID      | ID758202   | None          | 5.2          |

**September, 2008  
Trunked Radio Usage**

|                 |                                |          |         |          |      |         |
|-----------------|--------------------------------|----------|---------|----------|------|---------|
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758829 | None | 5.42    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758404 | None | 6.18    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759128 | None | 6.24    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758607 | None | 6.28    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759108 | None | 6.54    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758301 | None | 7.14    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758808 | None | 7.2     |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759027 | None | 7.5     |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758201 | None | 8.18    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758827 | None | 10.2    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758207 | None | 10.8    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758601 | None | 11.3    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759101 | None | 11.3    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758304 | None | 11.38   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759144 | None | 11.64   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758204 | None | 12.4    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758845 | None | 12.5    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758602 | None | 12.56   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758927 | None | 14.26   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758344 | None | 14.62   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758615 | None | 15.08   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758844 | None | 16.3    |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758308 | None | 19.12   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758645 | None | 19.32   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759551 | None | 37.58   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758244 | None | 39.52   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759028 | None | 71.58   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758208 | None | 75.08   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758828 | None | 163.22  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758245 | None | 163.58  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758644 | None | 172.22  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758608 | None | 181.16  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758345 | None | 228.2   |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID759600 | None | 468.28  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758707 | None | 512.54  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758928 | None | 1335.2  |
| Waukesha County | Waukesha County Communications | Motorola | UNIT ID | ID758744 | None | 2872.52 |

## September, 2008 Trunked Radio Usage

|                 |  |          |              |            |                |                |
|-----------------|--|----------|--------------|------------|----------------|----------------|
| Waukesha County | Waukesha County Communications                 | Motorola | UNIT ID      | ID758508   | None           | 3054.62        |
| Waukesha County | Waukesha County Communications                 | Motorola | UNIT ID      | ID758445   | None           | 4274.3         |
|                 | <b>Waukesha County Communications Total</b>    |          |              |            |                | <b>13991.7</b> |
| Waukesha County | Waukesha County Fleet Maintenance              | Motorola | H10UCH6DC5BN | 678SBE0123 | LTS-2000 w/sca | 14.68          |
| Waukesha County | Waukesha County Fleet Maintenance              | Motorola | H46UCF9PW6BN | 205CJF0413 | XTS-2500 Mode  | 14.68          |
| Waukesha County | Waukesha County Fleet Maintenance              | Motorola | M21URM9PW2AN | 624CJP0932 | XTL-2500RB     | 1.38           |
| Waukesha County | Waukesha County Fleet Maintenance              | Motorola | M21URM9PW2AN | 624CJP0929 | XTL-2500RB     | 5.28           |
|                 | <b>Waukesha County Fleet Maintenance Total</b> |          |              |            |                | <b>36.02</b>   |
| Waukesha County | Waukesha County Humane Office                  | Motorola | H46UCF9PW6BN | 205CJF0719 | XTS-2500 Mode  | 19.86          |
|                 | <b>Waukesha County Humane Office Total</b>     |          |              |            |                | <b>19.86</b>   |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3035 | MTS-2000 Mode  | 1.3            |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3038 | MTS-2000 Mode  | 5.2            |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3039 | MTS-2000 Mode  | 6.22           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3037 | MTS-2000 Mode  | 19.2           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3027 | MTS-2000 Mode  | 20.5           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3026 | MTS-2000 Mode  | 21.04          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3040 | MTS-2000 Mode  | 58.3           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H01UCD6PW1BN | 466ABS3050 | MTS-2000 Mode  | 66.26          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0698 | XTS-2500 Mode  | 1.02           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0671 | XTS-2500 Mode  | 2.3            |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0695 | XTS-2500 Mode  | 2.56           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0666 | XTS-2500 Mode  | 3              |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0675 | XTS-2500 Mode  | 3.28           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0663 | XTS-2500 Mode  | 4.16           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0684 | XTS-2500 Mode  | 5.24           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0681 | XTS-2500 Mode  | 5.54           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0686 | XTS-2500 Mode  | 8.46           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0692 | XTS-2500 Mode  | 9.3            |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0682 | XTS-2500 Mode  | 9.52           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0688 | XTS-2500 Mode  | 9.52           |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0693 | XTS-2500 Mode  | 10.06          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0689 | XTS-2500 Mode  | 10.08          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0690 | XTS-2500 Mode  | 11.14          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0687 | XTS-2500 Mode  | 11.44          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0679 | XTS-2500 Mode  | 12.32          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0691 | XTS-2500 Mode  | 14.42          |
| Waukesha County | Waukesha County Maintenance Department         | Motorola | H46UCF9PW6BN | 205CJF0667 | XTS-2500 Mode  | 15.44          |

## September, 2008 Trunked Radio Usage

|                 |   |          |              |            |               |               |
|-----------------|---|----------|--------------|------------|---------------|---------------|
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0680 | XTS-2500 Mode | 16.32         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0699 | XTS-2500 Mode | 17.18         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0696 | XTS-2500 Mode | 18.52         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0694 | XTS-2500 Mode | 19.52         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0683 | XTS-2500 Mode | 20.2          |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0670 | XTS-2500 Mode | 22.44         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0662 | XTS-2500 Mode | 23.18         |
| Waukesha County | Waukesha County Maintenance Department              | Motorola | H46UCF9PW6BN | 205CJF0697 | XTS-2500 Mode | 23.48         |
|                 | <b>Waukesha County Maintenance Department Total</b> |          |              |            |               | <b>507.66</b> |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0482 | XTS-2500 Mode | 1.32          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0479 | XTS-2500 Mode | 1.34          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0461 | XTS-2500 Mode | 1.44          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0433 | XTS-2500 Mode | 1.54          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0707 | XTS-2500 Mode | 1.56          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0481 | XTS-2500 Mode | 2             |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0463 | XTS-2500 Mode | 2.2           |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0434 | XTS-2500 Mode | 2.2           |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0480 | XTS-2500 Mode | 2.44          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0467 | XTS-2500 Mode | 3.32          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0448 | XTS-2500 Mode | 3.36          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0454 | XTS-2500 Mode | 3.58          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0453 | XTS-2500 Mode | 4.1           |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0425 | XTS-2500 Mode | 4.38          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0437 | XTS-2500 Mode | 5.3           |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0452 | XTS-2500 Mode | 5.42          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0715 | XTS-2500 Mode | 6.1           |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0701 | XTS-2500 Mode | 6.48          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0484 | XTS-2500 Mode | 7.34          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0469 | XTS-2500 Mode | 8             |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0714 | XTS-2500 Mode | 8.14          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0447 | XTS-2500 Mode | 8.42          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0475 | XTS-2500 Mode | 9.06          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0443 | XTS-2500 Mode | 10.34         |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0473 | XTS-2500 Mode | 10.4          |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0458 | XTS-2500 Mode | 11.26         |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0466 | XTS-2500 Mode | 12.08         |
| Waukesha County | Waukesha County Parks and Land Use                  | Motorola | H46UCF9PW6BN | 205CJF0456 | XTS-2500 Mode | 12.1          |

**September, 2008  
Trunked Radio Usage**

|                 |                                    |          |              |            |               |        |
|-----------------|------------------------------------|----------|--------------|------------|---------------|--------|
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0431 | XTS-2500 Mode | 12.22  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0440 | XTS-2500 Mode | 12.34  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0439 | XTS-2500 Mode | 13.82  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0451 | XTS-2500 Mode | 13.86  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0476 | XTS-2500 Mode | 14.2   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0450 | XTS-2500 Mode | 14.32  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0704 | XTS-2500 Mode | 16.46  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0711 | XTS-2500 Mode | 17.22  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0477 | XTS-2500 Mode | 19.08  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0705 | XTS-2500 Mode | 19.48  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0471 | XTS-2500 Mode | 21.54  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0457 | XTS-2500 Mode | 22     |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0716 | XTS-2500 Mode | 22.54  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0700 | XTS-2500 Mode | 22.66  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0455 | XTS-2500 Mode | 22.9   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0445 | XTS-2500 Mode | 25.56  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0706 | XTS-2500 Mode | 26.38  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0483 | XTS-2500 Mode | 27.56  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0430 | XTS-2500 Mode | 30.34  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0712 | XTS-2500 Mode | 33.58  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0449 | XTS-2500 Mode | 34.3   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0470 | XTS-2500 Mode | 37.46  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0464 | XTS-2500 Mode | 38.58  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0474 | XTS-2500 Mode | 39.5   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0472 | XTS-2500 Mode | 43.84  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0702 | XTS-2500 Mode | 47.94  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0460 | XTS-2500 Mode | 56.54  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0438 | XTS-2500 Mode | 58.18  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0708 | XTS-2500 Mode | 58.78  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0468 | XTS-2500 Mode | 59.04  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0441 | XTS-2500 Mode | 67.16  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0442 | XTS-2500 Mode | 67.58  |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0444 | XTS-2500 Mode | 85.9   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | H46UCF9PW6BN | 205CJF0426 | XTS-2500 Mode | 115.12 |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M21URM9PW2AN | 624CJP1001 | XTL-2500RB    | 1.42   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M21URM9PW2AN | 624CJP0999 | XTL-2500RB    | 2.02   |
| Waukesha County | Waukesha County Parks and Land Use | Motorola | M21URM9PW2AN | 624CJP0982 | XTL-2500RB    | 2.3    |

## September, 2008 Trunked Radio Usage

|                 |   |          |              |            |               |                |
|-----------------|---|----------|--------------|------------|---------------|----------------|
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP0989 | XTL-2500RB    | 2.38           |
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP0984 | XTL-2500RB    | 3.04           |
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP0993 | XTL-2500RB    | 4.38           |
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP0980 | XTL-2500RB    | 7.52           |
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP0990 | XTL-2500RB    | 8.76           |
| Waukesha County | Waukesha County Parks and Land Use              | Motorola | M21URM9PW2AN | 624CJP1000 | XTL-2500RB    | 122.34         |
|                 | <b>Waukesha County Parks and Land Use Total</b> |          |              |            |               | <b>1527.36</b> |
| Waukesha County | Waukesha County Radio Services                  | Motorola | H01UCF6PW1BN | 466AAG2587 | MTS-2000 Mode | 1.12           |
| Waukesha County | Waukesha County Radio Services                  | Motorola | H01UCF6PW1BN | 466AAG2588 | MTS-2000 Mode | 3.16           |
| Waukesha County | Waukesha County Radio Services                  | Motorola | H01UCF6PW1BN | 466ABL3292 | MTS-2000 Mode | 4.5            |
| Waukesha County | Waukesha County Radio Services                  | Motorola | H01UCF6PW1BN | 466AAG2589 | MTS-2000 Mode | 4.5            |
|                 | <b>Waukesha County Radio Services Total</b>     |          |              |            |               | <b>13.28</b>   |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3626 | MTS-2000 Mode | 1.14           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3474 | MTS-2000 Mode | 1.2            |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3612 | MTS-2000 Mode | 1.26           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3477 | MTS-2000 Mode | 1.28           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3620 | MTS-2000 Mode | 2.46           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3584 | MTS-2000 Mode | 2.48           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3585 | MTS-2000 Mode | 3.66           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3617 | MTS-2000 Mode | 4.02           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3601 | MTS-2000 Mode | 5.52           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3588 | MTS-2000 Mode | 6.86           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3627 | MTS-2000 Mode | 7.54           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABS3055 | MTS-2000 Mode | 7.56           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3587 | MTS-2000 Mode | 8.02           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3471 | MTS-2000 Mode | 8.04           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3592 | MTS-2000 Mode | 8.14           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3465 | MTS-2000 Mode | 9.68           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABS3042 | MTS-2000 Mode | 9.88           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3623 | MTS-2000 Mode | 10.28          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3602 | MTS-2000 Mode | 10.3           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3593 | MTS-2000 Mode | 10.86          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3586 | MTS-2000 Mode | 11.46          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3625 | MTS-2000 Mode | 12.56          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3591 | MTS-2000 Mode | 13.38          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3619 | MTS-2000 Mode | 14.76          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | H01UCD6PW1BN | 466ABG3594 | MTS-2000 Mode | 17.74          |

**September, 2008  
Trunked Radio Usage**

|                 |                                    |          |              |            |               |       |
|-----------------|------------------------------------|----------|--------------|------------|---------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3473 | MTS-2000 Mode | 17.94 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3615 | MTS-2000 Mode | 20.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3466 | MTS-2000 Mode | 29.3  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3595 | MTS-2000 Mode | 29.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3461 | MTS-2000 Mode | 30.9  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3603 | MTS-2000 Mode | 38.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3583 | MTS-2000 Mode | 43.46 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABS3066 | MTS-2000 Mode | 48.2  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCD6PW1BN | 466ABG3475 | MTS-2000 Mode | 76.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H01UCF6PW1BN | 466ABW5072 | MTS-2000 Mode | 58.58 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJH0811 | XTS-5000 Mode | 1.02  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJH0821 | XTS-5000 Mode | 1.04  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CGR0394 | XTS-5000 Mode | 1.06  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6092 | XTS-5000 Mode | 1.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6103 | XTS-5000 Mode | 1.26  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6102 | XTS-5000 Mode | 1.28  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6128 | XTS-5000 Mode | 1.52  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4993 | XTS-5000 Mode | 1.54  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJH0813 | XTS-5000 Mode | 2.42  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6070 | XTS-5000 Mode | 3.12  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6087 | XTS-5000 Mode | 3.46  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5006 | XTS-5000 Mode | 4.14  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6129 | XTS-5000 Mode | 4.5   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6071 | XTS-5000 Mode | 4.54  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0124 | XTS-5000 Mode | 4.88  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4991 | XTS-5000 Mode | 5.06  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6093 | XTS-5000 Mode | 5.2   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6084 | XTS-5000 Mode | 6.02  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6108 | XTS-5000 Mode | 6.06  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6100 | XTS-5000 Mode | 6.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5001 | XTS-5000 Mode | 6.12  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CGR0392 | XTS-5000 Mode | 6.36  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6095 | XTS-5000 Mode | 6.48  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6090 | XTS-5000 Mode | 7.04  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4995 | XTS-5000 Mode | 7.06  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEA5005 | XTS-5000 Mode | 7.14  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0125 | XTS-5000 Mode | 7.32  |

## September, 2008 Trunked Radio Usage

|                 |                                    |          |              |            |               |       |
|-----------------|------------------------------------|----------|--------------|------------|---------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6086 | XTS-5000 Mode | 7.36  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0211 | XTS-5000 Mode | 7.48  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6121 | XTS-5000 Mode | 7.56  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6123 | XTS-5000 Mode | 8.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5002 | XTS-5000 Mode | 8.3   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CGR0393 | XTS-5000 Mode | 8.82  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6098 | XTS-5000 Mode | 8.86  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5000 | XTS-5000 Mode | 9.06  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6077 | XTS-5000 Mode | 9.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2220 | XTS-5000 Mode | 9.38  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJH0818 | XTS-5000 Mode | 9.62  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0208 | XTS-5000 Mode | 10.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6114 | XTS-5000 Mode | 10.1  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0122 | XTS-5000 Mode | 11.24 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6065 | XTS-5000 Mode | 11.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6109 | XTS-5000 Mode | 11.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4990 | XTS-5000 Mode | 12.4  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0205 | XTS-5000 Mode | 12.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4999 | XTS-5000 Mode | 12.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6115 | XTS-5000 Mode | 12.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6104 | XTS-5000 Mode | 13.32 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0133 | XTS-5000 Mode | 13.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0141 | XTS-5000 Mode | 14    |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6091 | XTS-5000 Mode | 14.64 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2219 | XTS-5000 Mode | 15.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4996 | XTS-5000 Mode | 15.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4998 | XTS-5000 Mode | 15.58 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0138 | XTS-5000 Mode | 16.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6076 | XTS-5000 Mode | 16.34 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5004 | XTS-5000 Mode | 16.4  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0128 | XTS-5000 Mode | 17.18 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6112 | XTS-5000 Mode | 18.04 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6082 | XTS-5000 Mode | 18.78 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6118 | XTS-5000 Mode | 19.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6068 | XTS-5000 Mode | 20.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6097 | XTS-5000 Mode | 20.7  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4992 | XTS-5000 Mode | 21    |

## September, 2008 Trunked Radio Usage

|                 |                                    |          |              |            |               |       |
|-----------------|------------------------------------|----------|--------------|------------|---------------|-------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6073 | XTS-5000 Mode | 21.4  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6126 | XTS-5000 Mode | 23.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4997 | XTS-5000 Mode | 23.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4989 | XTS-5000 Mode | 23.4  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6072 | XTS-5000 Mode | 23.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6099 | XTS-5000 Mode | 24.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0212 | XTS-5000 Mode | 25.3  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6106 | XTS-5000 Mode | 25.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5009 | XTS-5000 Mode | 26.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2221 | XTS-5000 Mode | 26.14 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6117 | XTS-5000 Mode | 26.66 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6107 | XTS-5000 Mode | 26.9  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2222 | XTS-5000 Mode | 27.84 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJH0823 | XTS-5000 Mode | 28.62 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0137 | XTS-5000 Mode | 29.74 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5003 | XTS-5000 Mode | 30.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CEG0129 | XTS-5000 Mode | 30.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea5007 | XTS-5000 Mode | 31.54 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6083 | XTS-5000 Mode | 32.38 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721cea4994 | XTS-5000 Mode | 33.16 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CFX2225 | XTS-5000 Mode | 35.22 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | H18UCF9PW6AN | 721CJF6067 | XTS-5000 Mode | 43.28 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1452 | MCS-2000 Mode | 1.58  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1442 | MCS-2000 Mode | 3.02  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1447 | MCS-2000 Mode | 3.34  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1443 | MCS-2000 Mode | 3.44  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABS1463 | MCS-2000 Mode | 8.14  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1437 | MCS-2000 Mode | 9.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1439 | MCS-2000 Mode | 9.16  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1450 | MCS-2000 Mode | 11.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1453 | MCS-2000 Mode | 14.44 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1446 | MCS-2000 Mode | 16.1  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1448 | MCS-2000 Mode | 17.68 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1295 | MCS-2000 Mode | 21.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1278 | MCS-2000 Mode | 26.42 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1280 | MCS-2000 Mode | 26.46 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1315 | MCS-2000 Mode | 28.06 |

**September, 2008  
Trunked Radio Usage**

|                 |                                    |          |              |            |                |        |
|-----------------|------------------------------------|----------|--------------|------------|----------------|--------|
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1267 | MCS-2000 Mode  | 28.64  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1312 | MCS-2000 Mode  | 39.1   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1285 | MCS-2000 Mode  | 39.34  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1303 | MCS-2000 Mode  | 42.4   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1284 | MCS-2000 Mode  | 62.56  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1275 | MCS-2000 Mode  | 62.66  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1311 | MCS-2000 Mode  | 79.9   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1272 | MCS-2000 Mode  | 80.34  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1281 | MCS-2000 Mode  | 83.44  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ACJ2590 | MCS-2000 Mode  | 98.76  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1304 | MCS-2000 Mode  | 107.26 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1270 | MCS-2000 Mode  | 111.02 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1277 | MCS-2000 Mode  | 111.72 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1282 | MCS-2000 Mode  | 124.08 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1273 | MCS-2000 Mode  | 124.4  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1308 | MCS-2000 Mode  | 131.48 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1274 | MCS-2000 Mode  | 134.2  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1268 | MCS-2000 Mode  | 143.96 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1305 | MCS-2000 Mode  | 144.7  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1286 | MCS-2000 Mode  | 164.8  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1444 | MCS-2000 Mode  | 173.62 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1279 | MCS-2000 Mode  | 178.52 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1298 | MCS-2000 Mode  | 193.76 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1276 | MCS-2000 Mode  | 225.56 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1271 | MCS-2000 Mode  | 268.84 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UGM6PW6BN | 722ABE1290 | MCS-2000 Mode  | 284.92 |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M01UJM6PW6AN | 722AYE2516 | MCS-2000 Mode  | 81.48  |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0738 | LCS-2000 w/sca | 1.04   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0821 | LCS-2000 w/sca | 1.44   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0704 | LCS-2000 w/sca | 1.52   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0703 | LCS-2000 w/sca | 1.58   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SAYFM64 | LCS-2000 w/sca | 2.46   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0812 | LCS-2000 w/sca | 3      |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0566 | LCS-2000 w/sca | 3      |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0754 | LCS-2000 w/sca | 3.08   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0709 | LCS-2000 w/sca | 3.22   |
| Waukesha County | Waukesha County Sheriff Department | Motorola | M10UGD6DC5BN | 760SBA0742 | LCS-2000 w/sca | 5.06   |

## September, 2008 Trunked Radio Usage

|                 |   |          |              |            |                 |                |
|-----------------|---|----------|--------------|------------|-----------------|----------------|
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M10UGD6DC5BN | 760SBA0698 | LCS-2000 w/sca  | 5.24           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M10UGD6DC5BN | 760SBA0737 | LCS-2000 w/sca  | 5.46           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M10UGD6DC5BN | 760SBA0749 | LCS-2000 w/sca  | 6.02           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M10UGD6DC5BN | 760SBA0770 | LCS-2000 w/sca  | 7.5            |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M10UGD6DC5BN | 760SBA0717 | LCS-2000 w/sca  | 14.12          |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0584 | XTL-5000 Mobile | 1.04           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0567 | XTL-5000 Mobile | 1.44           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0586 | XTL-5000 Mobile | 1.52           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0582 | XTL-5000 Mobile | 1.58           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0583 | XTL-5000 Mobile | 2.46           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0568 | XTL-5000 Mobile | 3              |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0603 | XTL-5000 Mobile | 3              |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0560 | XTL-5000 Mobile | 3.08           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0595 | XTL-5000 Mobile | 3.22           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0596 | XTL-5000 Mobile | 5.06           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0589 | XTL-5000 Mobile | 5.24           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0577 | XTL-5000 Mobile | 5.46           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0563 | XTL-5000 Mobile | 6.02           |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0580 | XTL-5000 Mobile | 7.5            |
| Waukesha County | Waukesha County Sheriff Department              | Motorola | M20URS9PW1AN | 500CJV0601 | XTL-5000 Mobile | 14.12          |
|                 | <b>Waukesha County Sheriff Department Total</b> |          |              |            |                 | <b>5447.56</b> |
| Waukesha County | Waukesha County Transportation Department       | Motorola | H46UCF9PW6BN | 205CJF0629 | XTS-2500 Mode   | 2.1            |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M01UGM6PW6BN | 722ABS1442 | MCS-2000 Mode   | 4.6            |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M01UGM6PW6BN | 722ABS1451 | MCS-2000 Mode   | 12.84          |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0906 | XTL-2500RB      | 1.06           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0893 | XTL-2500RB      | 1.08           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0902 | XTL-2500RB      | 1.1            |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJP0387 | XTL-2500RB      | 1.14           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJP0396 | XTL-2500RB      | 1.14           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0875 | XTL-2500RB      | 1.18           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0877 | XTL-2500RB      | 1.22           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0869 | XTL-2500RB      | 1.34           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJP0378 | XTL-2500RB      | 1.48           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0903 | XTL-2500RB      | 1.56           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0889 | XTL-2500RB      | 2.26           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0880 | XTL-2500RB      | 2.44           |
| Waukesha County | Waukesha County Transportation Department       | Motorola | M21URM9PW2AN | 624CJK0899 | XTL-2500RB      | 2.46           |

## September, 2008 Trunked Radio Usage

|  |  |          |              |            |                 |                 |
|--|--|----------|--------------|------------|-----------------|-----------------|
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0885 | XTL-2500RB      | 2.6             |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0868 | XTL-2500RB      | 3.16            |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0882 | XTL-2500RB      | 3.18            |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJP0397 | XTL-2500RB      | 3.8             |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0883 | XTL-2500RB      | 4.14            |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0872 | XTL-2500RB      | 4.2             |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJP0417 | XTL-2500RB      | 5.56            |
| Waukesha County                                | Waukesha County Transportation Department              | Motorola | M21URM9PW2AN | 624CJK0863 | XTL-2500RB      | 28.28           |
|  | <b>Waukesha County Transportation Department Total</b> |          |              |            |                 | <b>93.92</b>    |
| <b>Waukesha County Total</b>                   |  |          |              |            |                 | <b>21637.36</b> |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2211 | XTS-2500 Mode   | 1.3             |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2220 | XTS-2500 Mode   | 4.54            |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2213 | XTS-2500 Mode   | 5.08            |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2210 | XTS-2500 Mode   | 5.26            |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2221 | XTS-2500 Mode   | 7.38            |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2215 | XTS-2500 Mode   | 12              |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2212 | XTS-2500 Mode   | 13.04           |
| Waukesha County Technical College              | Waukesha County Technical College                      | Motorola | H46UCF9PW6BN | 205CGX2214 | XTS-2500 Mode   | 14.16           |
|  | <b>Waukesha County Technical College Total</b>         |          |              |            |                 | <b>62.76</b>    |
| <b>Waukesha County Technical College Total</b> |  |          |              |            |                 | <b>62.76</b>    |
| Waukesha Memorial Hospital                     | Waukesha Memorial Hospital                             | Motorola | L04UJH9PW9AN | 761ABQ2247 | Base, low power | 18.08           |
|  | <b>Waukesha Memorial Hospital Total</b>                |          |              |            |                 | <b>18.08</b>    |
| <b>Waukesha Memorial Hospital Total</b>        |  |          |              |            |                 | <b>18.08</b>    |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | H01UCD6PW1BN | 466ABQ0736 | MTS-2000 Mode   | 7.4             |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | H01UCD6PW1BN | 466ABQ0776 | MTS-2000 Mode   | 8.28            |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | M10UGD6DC5BN | 760SAW0253 | LCS-2000 w/o sc | 1.26            |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | M10UGD6DC5BN | 760SAW0279 | LCS-2000 w/o sc | 11.22           |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | M21URM9PW2AN | 624CJV0128 | XTL-2500RB      | 1.26            |
| Waukesha, City                                 | Waukesha City Engineering Department                   | Motorola | M21URM9PW2AN | 624CJV0131 | XTL-2500RB      | 11.22           |
|  | <b>Waukesha City Engineering Department Total</b>      |          |              |            |                 | <b>40.64</b>    |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H01UCD6PW1BN | 466ABQ0744 | MTS-2000 Mode   | 1.3             |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJF0042 | XTS-5000 Mode   | 1.2             |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJF0043 | XTS-5000 Mode   | 1.46            |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJF0034 | XTS-5000 Mode   | 1.54            |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJD2820 | XTS-5000 Mode   | 2.4             |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJF0032 | XTS-5000 Mode   | 3.42            |
| Waukesha, City                                 | Waukesha City Fire Department                          | Motorola | H18UCF9PW6AN | 721CJD2818 | XTS-5000 Mode   | 4.38            |

**September, 2008  
Trunked Radio Usage**

|                |                               |          |              |            |                 |       |
|----------------|-------------------------------|----------|--------------|------------|-----------------|-------|
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0030 | XTS-5000 Mode   | 5.22  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0028 | XTS-5000 Mode   | 7.34  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0033 | XTS-5000 Mode   | 8.08  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0012 | XTS-5000 Mode   | 8.28  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0027 | XTS-5000 Mode   | 10.22 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0016 | XTS-5000 Mode   | 11.18 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0019 | XTS-5000 Mode   | 11.4  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0018 | XTS-5000 Mode   | 12.04 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJD2825 | XTS-5000 Mode   | 13.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0023 | XTS-5000 Mode   | 14.5  |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJD2817 | XTS-5000 Mode   | 17.06 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0026 | XTS-5000 Mode   | 17.42 |
| Waukesha, City | Waukesha City Fire Department | Motorola | H18UCF9PW6AN | 721CJF0021 | XTS-5000 Mode   | 32.76 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CFA0321 | MCS-2000 Mode   | 2.24  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1387 | MCS-2000 Mode   | 5.1   |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1207 | MCS-2000 Mode   | 6.06  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1210 | MCS-2000 Mode   | 6.44  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722ABE1426 | MCS-2000 Mode   | 10.46 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1212 | MCS-2000 Mode   | 37.02 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M01UGM6PW6BN | 722CDJ1209 | MCS-2000 Mode   | 42.6  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFK66 | LCS-2000 w/sca  | 9.28  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M10UGD6DC5BN | 760SAYFL67 | LCS-2000 w/sca  | 40.58 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1029 | XTL-5000 Mobile | 1.28  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1049 | XTL-5000 Mobile | 1.5   |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGR0352 | XTL-5000 Mobile | 8.5   |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1042 | XTL-5000 Mobile | 9.28  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1053 | XTL-5000 Mobile | 20.38 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1041 | XTL-5000 Mobile | 23.16 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGR0350 | XTL-5000 Mobile | 26.26 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1034 | XTL-5000 Mobile | 26.48 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CGT0271 | XTL-5000 Mobile | 28.26 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1051 | XTL-5000 Mobile | 33.42 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1043 | XTL-5000 Mobile | 36.2  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1045 | XTL-5000 Mobile | 39.12 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1036 | XTL-5000 Mobile | 40.58 |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CJH1047 | XTL-5000 Mobile | 42.5  |
| Waukesha, City | Waukesha City Fire Department | Motorola | M20URS9PW1AN | 500CHX0020 | XTL-5000 Mobile | 49.38 |

## September, 2008 Trunked Radio Usage

|                |  |          |              |            |                 |               |
|----------------|--|----------|--------------|------------|-----------------|---------------|
| Waukesha, City | Waukesha City Fire Department              | Motorola | M20URS9PW1AN | 500CJH1031 | XTL-5000 Mobile | 68.3          |
| Waukesha, City | Waukesha City Fire Department              | Motorola | M20URS9PW1AN | 500CJH1055 | XTL-5000 Mobile | 70.54         |
| Waukesha, City | Waukesha City Fire Department              | Motorola | M20URS9PW1AN | 500CJH1050 | XTL-5000 Mobile | 101.1         |
|                | <b>Waukesha City Fire Department Total</b> |          |              |            |                 | <b>970.38</b> |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | H01UCD6PW1BN | 466CFA0327 | MTS-2000 Mode   | 49.36         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | H01UCD6PW1BN | 466ABQ0778 | MTS-2000 Mode   | 92.14         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | H01UCD6PW1BN | 466CEJ0367 | MTS-2000 Mode   | 120.58        |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | H01UCD6PW1BN | 466ABQ0782 | MTS-2000 Mode   | 141.34        |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1265 | LCS-2000 w/o sc | 7.52          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1424 | LCS-2000 w/o sc | 7.52          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1379 | LCS-2000 w/o sc | 10.38         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1398 | LCS-2000 w/o sc | 11.24         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1389 | LCS-2000 w/o sc | 13.42         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1327 | LCS-2000 w/o sc | 15.32         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1413 | LCS-2000 w/o sc | 19.42         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1396 | LCS-2000 w/o sc | 20.14         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1391 | LCS-2000 w/o sc | 20.14         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1284 | LCS-2000 w/o sc | 21.18         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1381 | LCS-2000 w/o sc | 21.56         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1341 | LCS-2000 w/o sc | 22.22         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1383 | LCS-2000 w/o sc | 34.42         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1436 | LCS-2000 w/o sc | 43.4          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1403 | LCS-2000 w/o sc | 43.46         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1397 | LCS-2000 w/o sc | 45.4          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1423 | LCS-2000 w/o sc | 46.22         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1335 | LCS-2000 w/o sc | 48.46         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1412 | LCS-2000 w/o sc | 52.5          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1333 | LCS-2000 w/o sc | 54.3          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1387 | LCS-2000 w/o sc | 55            |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1332 | LCS-2000 w/o sc | 59.34         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1334 | LCS-2000 w/o sc | 60.32         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1425 | LCS-2000 w/o sc | 69.3          |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1367 | LCS-2000 w/o sc | 73.18         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1414 | LCS-2000 w/o sc | 75.36         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1370 | LCS-2000 w/o sc | 83.08         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1392 | LCS-2000 w/o sc | 84.08         |
| Waukesha, City | Waukesha City Metro Transit System         | Motorola | M10UGD6DC5BN | 760SAW1385 | LCS-2000 w/o sc | 84.54         |

## September, 2008 Trunked Radio Usage

|                |   |          |              |            |               |                |
|----------------|---|----------|--------------|------------|---------------|----------------|
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0169 | XTL-2500RB    | 7.52           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0155 | XTL-2500RB    | 7.52           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0161 | XTL-2500RB    | 10.38          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0166 | XTL-2500RB    | 11.24          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0163 | XTL-2500RB    | 13.42          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0134 | XTL-2500RB    | 15.32          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0151 | XTL-2500RB    | 19.42          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0164 | XTL-2500RB    | 20.14          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0145 | XTL-2500RB    | 20.14          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0132 | XTL-2500RB    | 21.18          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0162 | XTL-2500RB    | 21.56          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0140 | XTL-2500RB    | 22.22          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0142 | XTL-2500RB    | 34.42          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0157 | XTL-2500RB    | 43.4           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0148 | XTL-2500RB    | 43.46          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0165 | XTL-2500RB    | 45.4           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0154 | XTL-2500RB    | 46.22          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0139 | XTL-2500RB    | 48.46          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0150 | XTL-2500RB    | 52.5           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0137 | XTL-2500RB    | 54.3           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0144 | XTL-2500RB    | 55             |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0136 | XTL-2500RB    | 59.34          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0138 | XTL-2500RB    | 60.32          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0168 | XTL-2500RB    | 69.3           |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0141 | XTL-2500RB    | 73.18          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0152 | XTL-2500RB    | 75.36          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0158 | XTL-2500RB    | 83.08          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0146 | XTL-2500RB    | 84.08          |
| Waukesha, City | Waukesha City Metro Transit System              | Motorola | M21URM9PW2AN | 624CJV0143 | XTL-2500RB    | 84.54          |
|                | <b>Waukesha City Metro Transit System Total</b> |          |              |            |               | <b>2808.26</b> |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466CFA0332 | MTS-2000 Mode | 1.12           |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466CFA0331 | MTS-2000 Mode | 1.22           |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466ABQ0753 | MTS-2000 Mode | 2.54           |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466ABQ0780 | MTS-2000 Mode | 5.24           |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466CFA0330 | MTS-2000 Mode | 9.5            |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466ABQ0746 | MTS-2000 Mode | 12.8           |
| Waukesha, City | Waukesha City Park and Recreation Department    | Motorola | H01UCD6PW1BN | 466ABQ0768 | MTS-2000 Mode | 16.24          |

**September, 2008  
Trunked Radio Usage**

|                |  |          |              |            |                 |       |
|----------------|--|----------|--------------|------------|-----------------|-------|
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H01UCD6PW1BN | 466ABQ0757 | MTS-2000 Mode   | 19.4  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H01UCD6PW1BN | 466CFA0329 | MTS-2000 Mode   | 20.1  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H01UCD6PW1BN | 466ABQ0933 | MTS-2000 Mode   | 20.58 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4241 | LTS-2000 w/o sc | 1.12  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4214 | LTS-2000 w/o sc | 1.22  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4238 | LTS-2000 w/o sc | 2.54  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4250 | LTS-2000 w/o sc | 5.24  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4242 | LTS-2000 w/o sc | 9.5   |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4203 | LTS-2000 w/o sc | 12.8  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4205 | LTS-2000 w/o sc | 16.24 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4243 | LTS-2000 w/o sc | 19.4  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4213 | LTS-2000 w/o sc | 20.1  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | H10UCH6DC5BN | 678SAU4217 | LTS-2000 w/o sc | 20.58 |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1263 | LCS-2000 w/o sc | 1.14  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1362 | LCS-2000 w/o sc | 1.16  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1257 | LCS-2000 w/o sc | 1.26  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBS0341 | LCS-2000 w/sca  | 2.54  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1368 | LCS-2000 w/o sc | 2.56  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1255 | LCS-2000 w/o sc | 2.56  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0045 | LCS-2000 w/o sc | 3.16  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0073 | LCS-2000 w/o sc | 3.28  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1177 | LCS-2000 w/o sc | 3.38  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SBE0470 | LCS-2000 w/o sc | 3.46  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1251 | LCS-2000 w/o sc | 4.08  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | m10ugd6dc5bn | 760scu0090 | LCS-2000 w/o sc | 4.28  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0080 | LCS-2000 w/o sc | 4.36  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0058 | LCS-2000 w/o sc | 4.4   |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1200 | LCS-2000 w/o sc | 4.46  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0064 | LCS-2000 w/o sc | 4.56  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1159 | LCS-2000 w/o sc | 5     |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1254 | LCS-2000 w/o sc | 5.22  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0082 | LCS-2000 w/o sc | 5.38  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0063 | LCS-2000 w/o sc | 6.04  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW0060 | LCS-2000 w/o sc | 6.18  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1165 | LCS-2000 w/o sc | 7.24  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1201 | LCS-2000 w/o sc | 9.02  |
| Waukesha, City | Waukesha City Park and Recreation Department | Motorola | M10UGD6DC5BN | 760SAW1359 | LCS-2000 w/o sc | 14.46 |

**September, 2008  
Trunked Radio Usage**

|                |   |          |              |            |                 |               |
|----------------|---|----------|--------------|------------|-----------------|---------------|
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAW1256 | LCS-2000 w/o sc | 23.3          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M10UGD6DC5BN | 760SAW1363 | LCS-2000 w/o sc | 24.4          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0197 | XTL-2500RB      | 1.14          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0201 | XTL-2500RB      | 1.16          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0195 | XTL-2500RB      | 1.26          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0209 | XTL-2500RB      | 2.54          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0204 | XTL-2500RB      | 2.56          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0193 | XTL-2500RB      | 2.56          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0170 | XTL-2500RB      | 3.16          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0176 | XTL-2500RB      | 3.28          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0206 | XTL-2500RB      | 3.46          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0189 | XTL-2500RB      | 4.08          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0207 | XTL-2500RB      | 4.28          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0178 | XTL-2500RB      | 4.36          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0171 | XTL-2500RB      | 4.4           |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0186 | XTL-2500RB      | 4.46          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0175 | XTL-2500RB      | 4.56          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0183 | XTL-2500RB      | 5             |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0192 | XTL-2500RB      | 5.22          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0179 | XTL-2500RB      | 5.38          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0174 | XTL-2500RB      | 6.04          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0172 | XTL-2500RB      | 6.18          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0198 | XTL-2500RB      | 7.24          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0187 | XTL-2500RB      | 9.02          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0200 | XTL-2500RB      | 14.46         |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0194 | XTL-2500RB      | 23.3          |
| Waukesha, City | Waukesha City Park and Recreation Department              | Motorola | M21URM9PW2AN | 624CJV0202 | XTL-2500RB      | 24.4          |
|                | <b>Waukesha City Park and Recreation Department Total</b> |          |              |            |                 | <b>527.86</b> |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4895 | MTS-2000 Mode   | 1.1           |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4801 | MTS-2000 Mode   | 1.32          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4926 | MTS-2000 Mode   | 1.52          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4904 | MTS-2000 Mode   | 2.06          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4830 | MTS-2000 Mode   | 2.08          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4877 | MTS-2000 Mode   | 2.38          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4891 | MTS-2000 Mode   | 2.54          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4936 | MTS-2000 Mode   | 3.26          |
| Waukesha, City | Waukesha City Police Department                           | Motorola | H01UCD6PW1BN | 466ABE4887 | MTS-2000 Mode   | 3.8           |

**September, 2008  
Trunked Radio Usage**

|                |                                 |          |              |            |               |       |
|----------------|---------------------------------|----------|--------------|------------|---------------|-------|
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5008 | MTS-2000 Mode | 4.12  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4865 | MTS-2000 Mode | 4.4   |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4878 | MTS-2000 Mode | 4.46  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4927 | MTS-2000 Mode | 4.62  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4995 | MTS-2000 Mode | 4.62  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4993 | MTS-2000 Mode | 5.46  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5007 | MTS-2000 Mode | 5.58  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4922 | MTS-2000 Mode | 5.72  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4896 | MTS-2000 Mode | 6.54  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4834 | MTS-2000 Mode | 7.06  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4805 | MTS-2000 Mode | 12.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5021 | MTS-2000 Mode | 12.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4875 | MTS-2000 Mode | 14.44 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4874 | MTS-2000 Mode | 15.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4879 | MTS-2000 Mode | 15.96 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE5009 | MTS-2000 Mode | 16.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4916 | MTS-2000 Mode | 17.42 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4991 | MTS-2000 Mode | 17.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4870 | MTS-2000 Mode | 19.26 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4799 | MTS-2000 Mode | 20.56 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4902 | MTS-2000 Mode | 21.8  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4859 | MTS-2000 Mode | 22.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4871 | MTS-2000 Mode | 23.7  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4925 | MTS-2000 Mode | 29.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4842 | MTS-2000 Mode | 35.2  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4814 | MTS-2000 Mode | 36.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4811 | MTS-2000 Mode | 36.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4815 | MTS-2000 Mode | 36.64 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4841 | MTS-2000 Mode | 39.58 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4861 | MTS-2000 Mode | 41.88 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4998 | MTS-2000 Mode | 44.96 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4825 | MTS-2000 Mode | 48.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4997 | MTS-2000 Mode | 49.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4935 | MTS-2000 Mode | 54.14 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4803 | MTS-2000 Mode | 54.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4800 | MTS-2000 Mode | 54.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4835 | MTS-2000 Mode | 56.26 |

## September, 2008 Trunked Radio Usage

|                |                                 |          |              |            |               |       |
|----------------|---------------------------------|----------|--------------|------------|---------------|-------|
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4992 | MTS-2000 Mode | 57    |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4806 | MTS-2000 Mode | 57.66 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4932 | MTS-2000 Mode | 59.62 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4869 | MTS-2000 Mode | 62.04 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4802 | MTS-2000 Mode | 64.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4817 | MTS-2000 Mode | 69.32 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4824 | MTS-2000 Mode | 69.42 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4857 | MTS-2000 Mode | 70.08 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4849 | MTS-2000 Mode | 73.72 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4809 | MTS-2000 Mode | 74.24 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4804 | MTS-2000 Mode | 76.7  |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4844 | MTS-2000 Mode | 79.32 |
| Waukesha, City | Waukesha City Police Department | Motorola | H01UCD6PW1BN | 466ABE4810 | MTS-2000 Mode | 89.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0052 | XTS-5000 Mode | 1.32  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0046 | XTS-5000 Mode | 1.48  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0082 | XTS-5000 Mode | 2.08  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0047 | XTS-5000 Mode | 3.4   |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0085 | XTS-5000 Mode | 4.12  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0084 | XTS-5000 Mode | 5.58  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0088 | XTS-5000 Mode | 7.06  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0056 | XTS-5000 Mode | 12.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0089 | XTS-5000 Mode | 12.78 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0086 | XTS-5000 Mode | 16.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0062 | XTS-5000 Mode | 36.02 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0061 | XTS-5000 Mode | 36.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0063 | XTS-5000 Mode | 36.64 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0081 | XTS-5000 Mode | 44.96 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0058 | XTS-5000 Mode | 48.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0080 | XTS-5000 Mode | 49.48 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0048 | XTS-5000 Mode | 50.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0054 | XTS-5000 Mode | 54.34 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0049 | XTS-5000 Mode | 54.68 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0051 | XTS-5000 Mode | 54.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0045 | XTS-5000 Mode | 55.26 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0057 | XTS-5000 Mode | 57.66 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0053 | XTS-5000 Mode | 64.18 |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0075 | XTS-5000 Mode | 69.32 |

**September, 2008  
Trunked Radio Usage**

|                |                                 |          |              |            |                 |        |
|----------------|---------------------------------|----------|--------------|------------|-----------------|--------|
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0078 | XTS-5000 Mode   | 69.42  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0044 | XTS-5000 Mode   | 71.18  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0059 | XTS-5000 Mode   | 74.24  |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0055 | XTS-5000 Mode   | 76.7   |
| Waukesha, City | Waukesha City Police Department | Motorola | H18UCF9PW6AN | 721CJF0060 | XTS-5000 Mode   | 89.82  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGL6PW4BN | 722ABE0568 | MCS-2000 Mode   | 842.24 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1393 | MCS-2000 Mode   | 1.56   |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1424 | MCS-2000 Mode   | 5.26   |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1430 | MCS-2000 Mode   | 25.6   |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1390 | MCS-2000 Mode   | 29.9   |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1417 | MCS-2000 Mode   | 45.18  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1425 | MCS-2000 Mode   | 52.7   |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1409 | MCS-2000 Mode   | 58.78  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1416 | MCS-2000 Mode   | 76.18  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1412 | MCS-2000 Mode   | 85.78  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1414 | MCS-2000 Mode   | 92.88  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1431 | MCS-2000 Mode   | 101.24 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1396 | MCS-2000 Mode   | 151.52 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1422 | MCS-2000 Mode   | 152.7  |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1428 | MCS-2000 Mode   | 155.68 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1388 | MCS-2000 Mode   | 172.14 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1410 | MCS-2000 Mode   | 172.24 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1435 | MCS-2000 Mode   | 172.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1401 | MCS-2000 Mode   | 184.36 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1405 | MCS-2000 Mode   | 186.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1394 | MCS-2000 Mode   | 186.82 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1434 | MCS-2000 Mode   | 187.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1432 | MCS-2000 Mode   | 197.38 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1415 | MCS-2000 Mode   | 213.26 |
| Waukesha, City | Waukesha City Police Department | Motorola | M01UGM6PW6BN | 722ABE1391 | MCS-2000 Mode   | 217.68 |
| Waukesha, City | Waukesha City Police Department | Motorola | M10UGD6DC5BN | 760SAYFK69 | LCS-2000 w/sca  | 3.2    |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0440 | XTL-2500 Mobile | 465    |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0439 | XTL-2500 Mobile | 521.28 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW1AN | 514CGK0441 | XTL-2500 Mobile | 2381.3 |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0969 | XTL-2500RB      | 3.2    |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0937 | XTL-2500RB      | 3.22   |
| Waukesha, City | Waukesha City Police Department | Motorola | M21URM9PW2AN | 624CJP0940 | XTL-2500RB      | 3.4    |

**September, 2008  
Trunked Radio Usage**

|                |  |          |              |            |                 |                 |
|----------------|--|----------|--------------|------------|-----------------|-----------------|
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0938 | XTL-2500RB      | 4.54            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0945 | XTL-2500RB      | 5.3             |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0942 | XTL-2500RB      | 7.18            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0939 | XTL-2500RB      | 7.3             |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0968 | XTL-2500RB      | 8.76            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0943 | XTL-2500RB      | 12.3            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0944 | XTL-2500RB      | 12.5            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0967 | XTL-2500RB      | 12.66           |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0936 | XTL-2500RB      | 13.74           |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0971 | XTL-2500RB      | 15.4            |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0941 | XTL-2500RB      | 15.76           |
| Waukesha, City | Waukesha City Police Department              | Motorola | M21URM9PW2AN | 624CJP0946 | XTL-2500RB      | 20.26           |
|                | <b>Waukesha City Police Department Total</b> |          |              |            |                 | <b>10266.64</b> |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABE4797 | MTS-2000 Mode   | 1.16            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABQ0738 | MTS-2000 Mode   | 3.2             |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABQ0922 | MTS-2000 Mode   | 5               |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABQ0775 | MTS-2000 Mode   | 11.56           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABA1024 | MTS-2000 Mode   | 13.32           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABQ0781 | MTS-2000 Mode   | 21.08           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABE4868 | MTS-2000 Mode   | 27.44           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABE4794 | MTS-2000 Mode   | 38.16           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H01UCD6PW1BN | 466ABA1023 | MTS-2000 Mode   | 39.74           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAQ2776 | LTS-2000 w/o sc | 1.16            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAU4096 | LTS-2000 w/o sc | 3.2             |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAU4083 | LTS-2000 w/o sc | 5               |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAU4092 | LTS-2000 w/o sc | 11.56           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAU4090 | LTS-2000 w/o sc | 21.08           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAQ2783 | LTS-2000 w/scal | 27.44           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | H10UCH6DC5BN | 678SAU4149 | LTS-2000 w/o sc | 38.16           |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1250 | LCS-2000 w/o sc | 1.06            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAYEZ77 | LCS-2000 w/o sc | 1.2             |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAYEZ06 | LCS-2000 w/o sc | 1.28            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1388 | LCS-2000 w/o sc | 1.34            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1182 | LCS-2000 w/o sc | 1.38            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1300 | LCS-2000 w/o sc | 1.4             |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1417 | LCS-2000 w/o sc | 1.42            |
| Waukesha, City | Waukesha City Public Works Department        | Motorola | M10UGD6DC5BN | 760SAW1420 | LCS-2000 w/o sc | 1.46            |

**September, 2008  
Trunked Radio Usage**

|                |                                       |          |              |            |                 |       |
|----------------|---------------------------------------|----------|--------------|------------|-----------------|-------|
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1406 | LCS-2000 w/o sc | 1.52  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1203 | LCS-2000 w/o sc | 2.2   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1434 | LCS-2000 w/o sc | 2.3   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0241 | LCS-2000 w/o sc | 2.48  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAYEZ48 | LCS-2000 w/o sc | 2.48  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1171 | LCS-2000 w/o sc | 2.58  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1104 | LCS-2000 w/o sc | 3.26  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1285 | LCS-2000 w/o sc | 3.44  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1431 | LCS-2000 w/o sc | 3.52  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1419 | LCS-2000 w/o sc | 4.1   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1212 | LCS-2000 w/o sc | 4.18  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1399 | LCS-2000 w/o sc | 4.32  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1369 | LCS-2000 w/o sc | 5.22  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1324 | LCS-2000 w/o sc | 5.48  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1232 | LCS-2000 w/o sc | 7.34  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1366 | LCS-2000 w/o sc | 11.02 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1400 | LCS-2000 w/o sc | 14.3  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1209 | LCS-2000 w/o sc | 14.46 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW1373 | LCS-2000 w/o sc | 17.52 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M10UGD6DC5BN | 760SAW0515 | LCS-2000 w/sca  | 27.16 |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0217 | XTL-2500RB      | 1.06  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0222 | XTL-2500RB      | 1.18  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0281 | XTL-2500RB      | 1.2   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0249 | XTL-2500RB      | 1.26  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0282 | XTL-2500RB      | 1.28  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0271 | XTL-2500RB      | 1.34  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0257 | XTL-2500RB      | 1.38  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0275 | XTL-2500RB      | 1.4   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0239 | XTL-2500RB      | 1.42  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0241 | XTL-2500RB      | 1.46  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0235 | XTL-2500RB      | 1.52  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0263 | XTL-2500RB      | 2.2   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0248 | XTL-2500RB      | 2.3   |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0210 | XTL-2500RB      | 2.48  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0283 | XTL-2500RB      | 2.48  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0256 | XTL-2500RB      | 2.58  |
| Waukesha, City | Waukesha City Public Works Department | Motorola | M21URM9PW2AN | 624CJV0252 | XTL-2500RB      | 3.26  |

## September, 2008 Trunked Radio Usage

|                |   |          |              |            |                 |               |
|----------------|---|----------|--------------|------------|-----------------|---------------|
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0225 | XTL-2500RB      | 3.44          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0246 | XTL-2500RB      | 3.52          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0240 | XTL-2500RB      | 4.1           |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0267 | XTL-2500RB      | 4.18          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0232 | XTL-2500RB      | 4.32          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0224 | XTL-2500RB      | 5             |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0228 | XTL-2500RB      | 5.22          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0278 | XTL-2500RB      | 5.48          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0269 | XTL-2500RB      | 7.34          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0227 | XTL-2500RB      | 11.02         |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0287 | XTL-2500RB      | 11.3          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0233 | XTL-2500RB      | 14.3          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0266 | XTL-2500RB      | 14.46         |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0229 | XTL-2500RB      | 17.52         |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M21URM9PW2AN | 624CJV0286 | XTL-2500RB      | 27.16         |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M28URS9PW1AN | 775TFS0160 | XTL-1500 Mobile | 5.14          |
| Waukesha, City | Waukesha City Public Works Department                 | Motorola | M28URS9PW1AN | 775TFS0152 | XTL-1500 Mobile | 5.14          |
|                | <b>Waukesha City Public Works Department Total</b>    |          |              |            |                 | <b>596.12</b> |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW1541 | LTS-2000 w/o sc | 1.04          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW1534 | LTS-2000 w/o sc | 1.42          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAYDV77 | LTS-2000 w/o sc | 1.44          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW1545 | LTS-2000 w/o sc | 2.06          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAYDW12 | LTS-2000 w/o sc | 2.16          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAYDV97 | LTS-2000 w/o sc | 3.16          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW1542 | LTS-2000 w/o sc | 4.52          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW1567 | LTS-2000 w/o sc | 5.36          |
| Waukesha, City | Waukesha City Wastewater Treatment Plant              | Motorola | H10UCH6DC5BN | 678SAW2405 | LTS-2000 w/o sc | 5.58          |
|                | <b>Waukesha City Wastewater Treatment Plant Total</b> |          |              |            |                 | <b>26.74</b>  |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAW2439 | LTS-2000 w/o sc | 1.02          |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAYDV89 | LTS-2000 w/o sc | 3.44          |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAYDV79 | LTS-2000 w/o sc | 4.02          |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAW1570 | LTS-2000 w/o sc | 4.44          |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAW1547 | LTS-2000 w/o sc | 13.58         |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAW1546 | LTS-2000 w/o sc | 16.46         |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | H10UCH6DC5BN | 678SAW2433 | LTS-2000 w/o sc | 19.24         |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | M10UGD6DC5BN | 760SBA0391 | LCS-2000 w/o sc | 1.18          |
| Waukesha, City | Waukesha City Water Utility                           | Motorola | M10UGD6DC5BN | 760SBA0380 | LCS-2000 w/o sc | 1.36          |

## September, 2008 Trunked Radio Usage

|                                  |  |          |              |            |                 |                 |
|----------------------------------|--|----------|--------------|------------|-----------------|-----------------|
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYEZ62 | LCS-2000 w/o sc | 2               |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYFA00 | LCS-2000 w/o sc | 2.22            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYFB61 | LCS-2000 w/o sc | 2.44            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYFD13 | LCS-2000 w/o sc | 3.2             |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760SAYEZ05 | LCS-2000 w/o sc | 3.34            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M10UGD6DC5BN | 760scg0298 | LCS-2000 w/sca  | 32.04           |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0312 | XTL-2500RB      | 1.18            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0310 | XTL-2500RB      | 1.36            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0300 | XTL-2500RB      | 2               |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0307 | XTL-2500RB      | 2.22            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0302 | XTL-2500RB      | 2.44            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0293 | XTL-2500RB      | 3.2             |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0308 | XTL-2500RB      | 3.34            |
| Waukesha, City                   | Waukesha City Water Utility                | Motorola | M21URM9PW2AN | 624CJV0314 | XTL-2500RB      | 32.04           |
|                                  | <b>Waukesha City Water Utility Total</b>   |          |              |            |                 | <b>157.76</b>   |
| <b>Waukesha, City Total</b>      |  |          |              |            |                 | <b>15394.4</b>  |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2947 | MTS-2000 Mode   | 1.12            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ACG1252 | MTS-2000 Mode   | 1.34            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2931 | MTS-2000 Mode   | 1.36            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2937 | MTS-2000 Mode   | 1.38            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2932 | MTS-2000 Mode   | 1.56            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2929 | MTS-2000 Mode   | 2.02            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2928 | MTS-2000 Mode   | 5.56            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2935 | MTS-2000 Mode   | 7.3             |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | H01UCD6PW1BN | 466ABS2926 | MTS-2000 Mode   | 8.64            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1462 | MCS-2000 Mode   | 1.02            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1441 | MCS-2000 Mode   | 3.1             |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1456 | MCS-2000 Mode   | 6.04            |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1461 | MCS-2000 Mode   | 11              |
| Waukesha, Town                   | Waukesha Town Fire Department              | Motorola | M01UGM6PW6BN | 722ABS1435 | MCS-2000 Mode   | 18              |
|                                  | <b>Waukesha Town Fire Department Total</b> |          |              |            |                 | <b>69.44</b>    |
| <b>Waukesha, Town Total</b>      |  |          |              |            |                 | <b>69.44</b>    |
| Wisconsin, State of              | Wisconsin State Patrol                     | Motorola | M01UJN6PW6BN | 722CEA0632 | MCS-2000        | 8.48            |
|                                  | <b>Wisconsin State Patrol Total</b>        |          |              |            |                 | <b>8.48</b>     |
| <b>Wisconsin, State of Total</b> |  |          |              |            |                 | <b>8.48</b>     |
|                                  |  |          |              |            |                 |                 |
| <b>Grand Total</b>               |  |          |              |            |                 | <b>67601.18</b> |